

5-1-2010

An Analysis of Current Intersection Support and Falls in United States Coal Mines and Recommendations to Improve Safety

Allen Robert Mueller

Southern Illinois University Carbondale, allenrmueller@gmail.com

Follow this and additional works at: <http://opensiuc.lib.siu.edu/theses>

Recommended Citation

Mueller, Allen Robert, "An Analysis of Current Intersection Support and Falls in United States Coal Mines and Recommendations to Improve Safety" (2010). *Theses*. Paper 186.

This Open Access Thesis is brought to you for free and open access by the Theses and Dissertations at OpenSIUC. It has been accepted for inclusion in Theses by an authorized administrator of OpenSIUC. For more information, please contact opensiuc@lib.siu.edu.

AN ANALYSIS OF CURRENT INTERSECTION SUPPORT AND FALLS IN
UNITED STATES COAL MINES AND RECOMMENDATIONS
TO IMPROVE SAFETY

by

Allen R. Mueller

B.S. in Mining Engineering
Southern Illinois University – Carbondale, IL

A Thesis
Submitted in Partial Fulfillment of the Requirements for the
Master of Science Degree

Department of Mining and Mineral Resources Engineering
in the Graduate School
Southern Illinois University Carbondale
May 2010

THESIS APPROVAL

AN ANALYSIS OF CURRENT INTERSECTION SUPPORT AND FALLS
IN UNITED STATES COAL MINES AND RECOMMENDATIONS
TO IMPROVE SAFETY

By

Allen R. Mueller

A Thesis Submitted in Partial
Fulfillment of the Requirements
for the Degree of
Master of Science
in the field of Mining Engineering

Approved by:

Dr. A.J.S. Spearing (Chair)

Dr. Bradley Paul

Graduate School

Southern Illinois University Carbondale

November 12, 2009

AN ABSTRACT OF THE THESIS OF

ALLEN R. MUELLER, for the MASTER OF SCIENCE degree in MINING ENGINEERING, presented on May 1, 2009, at Southern Illinois University Carbondale.

TITLE: AN ANALYSIS OF CURRENT INTERSECTION SUPPORT AND FALLS IN UNITED STATES COAL MINES AND RECOMMENDATIONS TO IMPROVE SAFETY

MAJOR PROFESSOR: Dr. A.J.S. Spearing, Associate Professor
DEPARTMENT OF MINING AND MINERAL
RESOURCES ENGINEERING

Background: The support of intersections in coal mines is an important safety issue in the U.S., as intersections are by far the most common area for unplanned falls of ground. A relatively comprehensive, nation-wide study of falls of ground is coupled with a national survey to mines about their support methods to determine common characteristics of failure and recommend changes to improve stability, and recommendations for future research.

Methods: Over 600 fall of ground reports were collected from nine of the 11 Mine Safety and Health Administration (MSHA) District offices, and data was compiled to determine common characteristics of these unplanned falls. Statistical analysis was conducted on the data to examine which variables affected fall dimensions. To obtain data on current support usage, mail and phone surveys were collected with responses from 70 underground coal mines, representing approximately 235 million tons of annual production, or 66% of the U.S. total. These surveys provided a national snapshot of what support mines are using as well as typical extraction height, intersection width, and other details. Rocscience's Phase² software was used to model a typical coal mine intersection and examine possible stability changes with different support options.

Results: Surveys from underground mines revealed that the current industry average for intersection width is 20ft, average bolt length is 6ft, average distance from pillars to the first row of bolts is 3 to 4 ft, and a great majority of mines do not angle bolts over pillars. The fall of ground study confirmed that most falls are thicker than the average bolt length of 6 ft. and tend to be massive, extending past the intersection width of 20ft. The study also showed that falls with longer roof bolts installed typically had thicker falls which broke above the anchorage zone. Statistical analysis found a few questionably significant interactions, with the most prominent being the effect of roof type on fall height.

Immediate roof geologies of dark shale and thinly laminated shale resulted in higher roof falls than other types. 2D modeling was unsuccessful at replicating the type of massive shear failures that have been commented on by MSHA personnel and that the study data suggests. It is the author's opinion that Phase² and 2-D modeling in general may not be powerful or comprehensive enough to capture the true shear behavior of the rock strata in the roof beam because it cannot effectively model failure and dilation.

Conclusions: Increasing bolt length may not be the most effective solution to reducing massive intersection failures. Rather, installing angled bolts over pillars may increase the strength of the system at the crucial roof-pillar edge. Weathering of bolts and/or rock are likely contributing to the significant number of cutter failures happening months or years after excavation. Recommendations for future action include 3D modeling of cutter failure and benefits of angled bolts over pillars. More consistent and thorough MSHA 7000 50a forms will enable more accurate statistical analysis and a better understanding of massive failure characteristics.

ACKNOWLEDGMENTS

The author would like to take this opportunity to give Dr. A.J.S. (Sam) Spearing, the major professor and defense committee chair, his utmost appreciation and gratitude for his constant guidance and encouragement he has provided during the course of this Master's study. The author also thanks Dr. Yoginder P. Chugh and Dr. Bradley Paul for their critical evaluation of the thesis and their valuable suggestions, and the National Institute for Occupational Safety and Health (NIOSH) for their financial support of this project.

Last but not least, the author expresses his greatest appreciation to his fiancé, family, friends, colleagues, and all other people who have directly or indirectly provided moral support and encouragement.

TABLE OF CONTENTS

<u>CHAPTER</u>	<u>PAGE</u>
ABSTRACT	i
ACKNOWLEDGMENTS	iii
LIST OF TABLES	vi
LIST OF FIGURES.....	vii
CHAPTER	
CHAPTER 1 – INTRODUCTION	1
1.1 - Statement of Objective.....	1
1.2 - Significance of the Problem.....	1
1.3 - Information Available Through Regulatory Reports.....	7
CHAPTER 2 – LITERATURE REVIEW	9
2.1 - Coal Mine Layouts and Intersections	9
2.2 - Typical Geology Above Coal Seams.....	11
2.3 - Stress Fields Around Coal Seams.....	11
2.4 - Devices Used to Support Coal Mine Roof.....	12
2.5 - Mathematical Models of Roof Stresses and Failures.....	18
2.6 - Previous Studies of Roof Stability.....	24
CHAPTER 3 – RESEARCH OBJECTIVES AND PROCEDURES	32
3.1 - Statement of the Objective.....	32
3.2 - Work Steps to Achieve the Objective.....	32
CHAPTER 4 – STUDY RESULTS AND DISCUSSION.....	40
4.1 – Intersection Support Survey.....	40

4.2 – Unplanned Fall of Ground Study	46
4.3 – Finite Element Modeling of Failure Modes	50
4.4 – Statistical Analysis of Collected Data	53
CHAPTER 5 – CONCLUSIONS AND RECOMMENDATIONS	58
5.1 - Conclusions.....	58
5.2 - Recommendations.....	60
REFERENCES.....	64
APPENDICES	
Appendix A – Current Intersection Support Practices by State	69
Appendix B – Unplanned Fall Results from MSHA.....	102
Appendix C – Detailed Fall Results by MSHA District	126
VITA	156

LIST OF TABLES

<u>TABLE</u>	<u>PAGE</u>
Table 1.1 Historical fatality data for U.S. coal mines	2
Table 2.1 Plate theory analysis of entry widths	23
Table 3.1 Input rock strata values	38
Table 4.1 Relationship of primary bolt length and fall height	47
Table 4.2 ANOVA test of roof type on fall height.....	54
Table 4.3 ANOVA test of MSHA District on fall length.....	54
Table 4.4 ANOVA test of stand up time on fall length	55
Table 4.5 Four-way ANOVA test	57

LIST OF FIGURES

<u>FIGURE</u>	<u>PAGE</u>
Figure 1.1 U.S. raw coal production	1
Figure 1.2 MSHA Districts by location	7
Figure 1.3 2008 MSHA budget allocations.....	8
Figure 2.1 Rectangular pillar pattern.....	9
Figure 2.2 Angled crosscut pattern	10
Figure 2.3 Longwall mining diagram.....	10
Figure 2.4 Model for granular material supported using rock bolts	15
Figure 2.5 Intersection Truss system.....	17
Figure 2.6 Beam theory model.....	18
Figure 2.7 Separation of roof strata.....	19
Figure 2.8 Distributed beam loading.....	19
Figure 2.9 Entry orientation for maximum stability	24
Figure 2.10 Effect of low and high k value on safety factors	25
Figure 2.11 Seasonal roof fall rates for U.S. coal basins	26
Figure 2.12 Illustration of a ground response curve.....	28
Figure 2.13 Cutter roof failure diagram	30
Figure 3.1 Rock strata used in Phase ²	37
Figure 4.1 Maximum reported room width.....	41
Figure 4.2 Mining height distribution	41
Figure 4.3 Bolt types used.....	42
Figure 4.4 Bolt diameter distribution	43
Figure 4.5 Bolt length distribution	43

Figure 4.6 Bolt length distribution by diameter	44
Figure 4.7 Distance of nearest primary rock bolt to pillars.....	45
Figure 4.8 Maximum cable bolt length distribution.....	45
Figure 4.9 Unplanned fall of ground thickness	46
Figure 4.10 Unplanned fall of ground length.....	47
Figure 4.11 Fall length vs. fall width	48
Figure 4.12 Fall length vs. fall width (detail).....	48
Figure 4.13 Stand-up times for unplanned falls of ground	49
Figure 4.14 Roof and floor displacement.....	50
Figure 4.15 Normal intersection stress in three dimensions	51
Figure 4.16 Shear stress across intersection width.....	51
Figure 4.17 Fall length by MSHA District.....	55
Figure 4.18 Stand-up time vs. fall length.....	56
Figure 5.1 Average results for primary bolt length and average fall of ground height	59

CHAPTER 1

INTRODUCTION

1.1 Statement of Objective

The objective of this thesis was to identify common characteristics of unplanned roof falls and support methods currently used, and to make recommendations to improve rock fall related safety.

1.2 Significance of the Problem

1.2.1 The Important Role of Underground Coal Production

Coal is a vital element in the United States' energy production and is actively mined in 33 states. Approximately 90% of this coal production is used to generate electric power, and coal is used to generate almost half of the country's electricity needs. Coal mining is responsible for over \$60 billion in annual revenue and the industry directly and indirectly supports over 750,000 jobs in the U.S (U.S. Energy Information Administration, 2009). As Figure 1.1 shows, annual production has risen at a steady rate since 1958 with approximately three times the amount of coal being mined in recent years compared to fifty years ago.




Figure 1.1: U.S. Raw Coal Production (Energy Information Administration, 2008)

In the year 2008, there were about 1.15 billion short tons of coal produced from 1,438 mines. 612 of these mines were underground operations, and they accounted for about 31% of the total coal produced (U.S. Energy Information Administration, 2009).

1.2.2 Importance of Roof Falls to Coal Mine Safety

Each year, approximately 35,000 coal miners work in underground mines (U.S. Energy Information Administration, 2008). Annual fatalities have been declining steadily (while production has been rising), and in 2005 the number of fatalities was 23, the safest year of U.S. coal mining in history. Recently, the fatality rate for these miners has been around 20 deaths per 100,000 workers. This rate is significantly higher than the overall private industry fatality rate of 4.2, but is still a lower fatality rate than occupations such as airline pilots, truck drivers, farmers, and fishing workers (U.S. Bureau of Labor Statistics, 2007). The downward trend in annual fatalities through 2005 can be seen in Table 1.1. The year 1911 is included for comparison because that was the year of the most recorded fatalities.

Table 1.1: Historical Fatality Data for U.S. Coal Mines

Year	Number of Miners	Production (Tons x 10 ⁶)	Fatalities	Year	Number of Miners	Production (Tons x 10 ⁶)	Fatalities
1911	666,552	+461	2,821	1996	126,451	1066	39
1984	208,160	897	125	1997	126,429	1092	30
1985	197,049	885	68	1998	122,083	1120	29
1986	185,167	892	89	1999	114,489	1102	35
1987	172,780	920	63	2000	108,098	1076	38
1988	166,278	952	53	2001	114,458	1130	42
1989	164,929	983	68	2002	110,966	1097	28
1990	168,625	1032	66	2003	104,824	1074	30
1991	158,677	998	61	2004	108,734	1114	28
1992	153,128	1000	55	2005	116,436	1134	23
1993	141,183	947	47	2006	122,975	1164	47
1994	143,645	1036	45	2007	N/A	1150	33
1995	132,111	1035	47	2008	N/A	1170	29

Source: Annual Coal Report for 2008, Energy Information Administration.

In 2006 there were two major disasters – Sago and Darby, which caused the unusually high spike in the number of fatalities. Sago was a methane explosion in a West Virginia mine in which 12 miners perished, and the prevailing theory for an ignition source is from a lightning strike in the area. The disaster at Darby in Kentucky was also a methane explosion, but was ignited with an acetylene cutting torch. This mine accident claimed the lives of 5 men.

Roof and rib control problems account for about 30% of the underground coal fatality rate (Mine Safety and Health Administration, 2006). Coal mine intersections, including the ribs immediately around those intersections, account for approximately 71% of all roof falls, even though they only form 20-25% of the total development. This shows that a fall is several times more likely to occur in an intersection than an entry on a unit length basis (Molinda, 1998). Clearly the objective of this thesis, in detecting causes and suggesting mitigating responses that coal operators may take to reduce the incidence of unexpected falls, will improve worker safety in one of the U.S. most vital industries.

1.2.3 The Importance of Roof Falls to Coal Mine Productivity

According to C. Mark, there are over 1,500 roof falls that occur every year in U.S. coal mines (Mark, 2001). As mentioned in the previous section, a large majority of these falls occur in intersection areas. To be reportable to the Mine Safety and Health Administration (MSHA) as an unplanned fall of ground, a roof fall must be at or above the anchorage zone in active workings where roof bolts are in use; or, an unplanned roof or rib fall in active workings that impairs ventilation or impedes passage. The roof falls that meet these criteria clearly have the ability to create unsafe conditions, disrupt production, and shift resources away from necessary tasks.

Coal from areas except the Powder River Basin currently sells for upwards of \$40 per ton, or about \$2.29 per million BTU. This cost can be compared with petroleum (\$11/million BTU) and natural gas (\$7.50/million BTU) to see that coal is one of the most inexpensive forms of energy (Energy Information Administration, 2009). While the cost per unit may be less for coal, the infrastructure to burn it can cost substantially more. As an example, a coal-fired power plant costs about \$1200 per kWh to construct, while a simple cycle natural gas plant can cost as little as \$400/kWh (JC Miras, 2008). Underground coal mines must compete on a cost/BTU basis against surface mined coal. Powder River Basin coal sells for about \$9 per ton, and while there can be significant transportation costs to move the coal to other parts of the country, keeping production and efficiency up in underground coal mines is critical to maintaining a competitive stance in the industry (Energy Information Administration, 2009).

1.2.3 Importance of Roof Falls to Regulatory Compliance and Cost

The U.S. Congress passed the Federal Mine Safety and Health Act of 1977 (Mine Act), and this amended the 1969 Coal Act in several significant ways. It also consolidated all the federal health and safety regulations of the mining industry under a single statutory scheme. It strengthened and expanded the rights of miners, and enhanced the protection of miners from retaliation for exercising those rights (such as the right to refuse to work in dangerous conditions). The Mine Act also transferred responsibility for enforcement from the Department of the Interior (U.S. Bureau of Mines) to the Department of Labor, and renamed the new agency the Mine Safety and Health Administration (MSHA). Under this Mining Act, safety continued to improve steadily.

Following the Sago and Darby mine accidents in 2006, Congress rapidly passed the Mine Improvement and New Emergency Response (MINER) Act. The main relevant provisions of this Act according to MSHA are:

- Require each mine to develop and continuously update a written emergency preparedness plan, which must be recertified by MSHA every 6 months.
- Use equipment and technology that is commercially available if it can improve safety.
- Require every mine to have 2 experienced rescue teams capable of responding within 1 hour if required.
- Require mine operators to report dangerous incidents and accidents within 15 minutes to MSHA or face fines of up to \$60,000.
- Raising the criminal penalty cap to \$250,000 for the first offence and a maximum civil penalty of \$220,000 for flagrant violations.
- Direct that within 3 years, mines will have wireless two-way communication and an electronic personnel tracking system in place.
- Empower MSHA to shut down a mine when it has refused to pay a final order penalty.

While these provisions have little to do directly with accidents associated with falls of ground, these still remain a cause of concern with mine operators and MSHA. One of the provisions of the MINER Act that does impact rock related safety is the requirement for all unplanned roof falls to be reported to a central MSHA office by telephone within 15 minutes of being discovered (30 CFR § 50.10). After reporting an unplanned roof fall within the timeframe specified, the mine must submit a 7000-1 form

to MSHA. These reports include the following information relevant to roof falls: time of accident, location, steps taken to prevent a recurrence, and full details and description of the accident. In response to roof or ground control problems, MSHA inspectors have the option to investigate roof falls and fill out 7000-50a reports which commonly include details on the length, width, and height of the roof fall as well as the length and type of bolts used. Other parameters that are inconsistently reported from district to district are: stand-up time before the fall, immediate roof thickness and geology, and the presence of water or cutters in the roof. These plans and information feedback system provide initial data to MSHA for use in evaluating roof falls and possible ways of addressing them. This information can be also be used to evaluate the adequacy of roof control plans, modification requirements, and resulting compliance costs.

Under the law, each mine is required to submit a roof control plan to MSHA explaining how and specifying what materials they will use to ensure that the roof and ribs of their coal mines are maintained safe and controlled (30 CFR § 75.220). These plans generally contain information on topics such as overlying roof strata, support materials used, installation sequence, drill hole size, and others. These details can be compared to performance results in preventing roof falls, and MSHA can require modifications to the roof control plan as a result of falls.

As an example, 30 inch fully grouted roof bolts on a 5ft. x 5ft. pattern (the minimum allowed under regulation – 30 CFR § 75.204) for a 6 foot coal seam would impose a direct materials cost of about \$2.12 per foot mined. Roof fall incidents make it common for MSHA district managers to require 4ft. x 4ft. patterns with longer roof bolts. The direct cost of materials for 7 foot fully grouted roof bolts on 4 foot centers is about

\$6.91 per foot for the same 6 foot coal seam (Oldsen, 2009). While the difference in cost may be justified if it will increase stability, simply using bigger and more frequent bolting may not be the best option for fall prevention and can be rather costly.

1.3 Information Available Through Regulatory Reports

MSHA's coal oversight and enforcement is broken up into 11 Districts as shown in Figure 1.2. These Districts tend to correspond to coal basins and unique ground control conditions in different parts of the country.




Figure 1.2: MSHA Districts by Location (MSHA.gov, 2009)

MSHA is largely a mine safety law enforcer. MSHA's budget for 2008 was \$313.5 million, which included a \$16.6 million increase specifically for the enforcement of coal mines. The breakdown in Figure 1.3 shows that most of the money was spent on enforcement.




Figure 1.3: 2008 MSHA Budget Allocations (in Millions of Dollars (MSHA, 2009))

The amount of money in fines assessed by MSHA totaled \$194.3 million in 2008, and citations are the primary source of income for the organization (MSHA, 2009).

MSHA has a major facility in Beckley, West Virginia called the National Mine Health and Safety Academy. The primary purpose for this academy is to train MSHA staff, new miners and retrain and update experienced miners on safety related aspects of ground control, mine rescue, ventilation, and other topics. Unlike the U.S. Bureau of Mines which was replaced as a safety enforcer in 1969, MSHA does not have a direct research and development arm. Thus, while MSHA has a Tech Support Group and may generate much data that could be used to evaluate roof fall problems, it does not have research capability of its own. This work, funded in part through the National Institute for Occupational Safety and Health (NIOSH), looks to fill some of the need of coupling roof control plans and roof fall data into a systematically reviewed and analyzed response. Information from both studies can be used by a wide variety of people including: safety personnel at mines, rock mechanics researchers, MSHA, and NIOSH.

CHAPTER 2

LITERATURE REVIEW

2.1 Coal Mine Layouts and Intersections.

In room and pillar coal mining, parallel entries are driven through the coal seam and are joined together at regular intervals by crosscuts. This is to maximize extraction by creating a checker board pattern of pillars and assists with ventilation. One standard pattern runs the crosscuts and entries at 90 degrees to each other with the crosscuts spaced such that the pillars are rectangular, as shown in Figure 2.1.




Figure 2.1: Rectangular Pillar Pattern (Arch Coal, 2008)

Another similar pattern orients the crosscuts perpendicular to the entries, but spaces them so that pillars are square. Still another layout that is used in coal mines orients the crosscuts at approximately 60 degrees to the entries, which can provide better visibility for the continuous miner operator. This oblique angled pattern can also reduce conveyor spillage compared to a 90 degree pattern which requires a sharper angle for the conveyor to turn (Ganguli, 2009). The angled crosscut pattern is shown in Figure 2.2.




Figure 2.2: Angled Crosscut Pattern (Ganguli, 2009)

Room and pillar style entries are also used for the development of head and tailgates on longwall panels. The pillars on either side of the longwall panel support an increasing amount of weight as the panel advances and extracts coal. Supplemental yielding support (such as timbers and cribs) is often required in these areas due to the extremely high stresses placed on the pillars and the consequent high and often non-uniform roof convergences. A typical longwall layout can be seen in Figure 2.3.




Figure 2.3: Longwall Mining Diagram (Arch Coal, 2008)

2.2 Typical Geology Above Coal Seams

The overlying roof strata above coal deposits is a widely varying, depending on regional and local geology, as well as the depth of the coal seam being mined. The roof conditions can also be affected by the presence of water and high horizontal stresses, in addition to the particular geology in that area. The types of deposits immediately above coal can range from massive thick layers of sandstone or limestone, to strong laminated layers of siltstone and sandstone, to thin weak layers of shale or mudstone (Jeremic, 1985). One of the most frequently seen overlying strata in coal mines is a laminated shale roof that is prone to immediate skin failure. In many mines, it is necessary to bolt wire mesh to the roof to prevent flaking and progressive failure of the weak shale layer, due in part to weathering and lateral confinement.

Tang (1984) in a paper on bolt design states that immediate roof geologies can be divided into three types: (A) the deflection of each strata is larger than that of its overlying strata, and each strata deflects independently, (B) some strata deflect more than the overlying strata, and (C) the deflection of each strata is larger than or equal to that of its underlying strata. The immediate roof of case A is most critical to stability; therefore an adequately designed roof bolting system is crucial. Additionally, the effect of axial loading due to horizontal stresses should be considered in the design of support systems.

2.3 Stress Fields Around Coal Seams

Stress fields occur naturally in the ground prior to mining, and these effects are important when considering ground control issues. The horizontal and vertical stress fields can cause major stability problems if they are not controlled through adequate pillar design, room spacing, entry orientation, and support design. Vertical stress

magnitudes increase with depth and are a result of the overburden weight above the excavation. Horizontal stress magnitudes and directions vary primarily with geographic location, and can exceed the vertical stress by a factor of 3 or more, particularly in shallower deposits. Research suggests that plate tectonics are responsible for the magnitude and direction of horizontal stress fields, which can cause roof buckling and bed separation among other problems. As early as the 1940's, researchers recognized that large horizontal stresses were responsible for much of the roof damage experienced underground (Mark, 2008). In addition to the magnitude of horizontal and vertical stress, the ratio of horizontal stress to vertical stress (σ_{hmax}/σ_v) can influence roof stability as well. This effect will be discussed further later.

2.4 Devices Used to Support Coal Mine Roof

2.4.1 Primary Support Devices

Roof bolting is a legally required practice in U.S. coal mines, and is referred to as primary support because it occurs concurrently with development. Depending on the particular roof geology and the type of bolt used, the system can help support the roof by providing skin control, suspension, or beam building. C. Mark suggests that regardless of the type of bolt used (mechanical, grouted, tensioned) the local geology has the largest role in determining which mode the bolt system is required for support. The intensity of support provided by a bolt system is determined by load bearing capacity of individual bolts, density of the bolting pattern, and the length of bolts (Mark, 2001). The bolt grade and stiffness, as well as the anchoring mechanism could also be considered as factors within support intensity.

Two frequently used bolt types in the U.S. are mechanical anchor and fully resin grouted bolts. Mechanical anchor bolts usually pass through thinly layered rock located above the coal into thicker or massive rock layers located above. They anchor into the thick strata and are tensioned at the bottom of the thin strata, effectively pinning the thin strata to the massive roof above. Because they are tensioned upon installation, they can be referred to as active bolts. Indeed the model used to size mechanical anchor roof bolts assumes that each roof bolt supports an independent block of rock half way to its nearest neighbor and that the block is essentially hanging from the massive roof above by the bolt.

Grouted roof bolt systems can be divided into two categories: passive and active bolts. Active bolts are tensioned upon installation, and can be anchored by either using a two speed resin or a mechanical shell with resin; Passive bolts are un-tensioned on installation and are usually fully grouted with resin cartridges. The high stiffness of this system is accomplished due to the full contact grout anchor, and the ability of the small resin grout annulus to quickly transfer the loads back into the rock mass. Grouted roof bolts, which are completely anchored to the rock over their entire length, are regarded as transforming thin individual rock layers into a single massive beam – in effect, the resin forms a laminated beam. In 2000, Dennis Dolinar conducted a study which found that a strong shift in the coal industry's bolt preference has occurred in the last two decades, with fully grouted bolt usage increasing from 40% to over 80%, and mechanical anchor bolt usage decreasing from 35% to 8%. A decreasing trend in roof fall rates has been observed during this shift in preference from mechanical to fully-grouted bolts, although there are many factors that may be contributing to this effect (Dolinar, 2000). Resin-

grouted rebar can be considered a superior system to the mechanical anchor bolt because of the load transfer capabilities, and the higher anchorage capacity.

Load transfer between the support and the rock is imperative to all bolt systems, so the annulus distance in fully grouted bolts (the distance between the bolt and the surrounding rock that is filled with grout) and effective resin mixing are important factors in the performance of the system. Dolinar also states that experimental research has shown that the optimum annulus is about 0.125", so the best system for use in a 1" hole is using 0.75" diameter #6 rebar. Despite this fact, a majority (80%) of the resin-grouted bolts in use today are the smaller 0.625" size, thus causing the annulus distance in the typical 1" hole to exceed the optimum (Dolinar, 2000). This situation merits attention, because it is not known to what degree the increase in annulus and 30% decrease in steel affects the performance of systems in 1" holes.

Resin quality is another area where further research can be implemented; a common percentage of filler is around 75%, however some resins contain up to 85% filler. It is not yet known what degree of impact this has on bolt performance (Dolinar, 2000).

The interaction effects of rock bolts is another interesting area to examine. Figure 2.4 is an explanation of how rock bolts operate in a granular medium according to Tom Lang and demonstrated by E. Hoek to students (Hoek, 2007). Particularly thinly laminated roof strata that are very weak could be considered to have similar behavior to granulated material. A zone of compression is induced in the red zone, generally as long as the bolt spacing is less than the bolt length. The smaller the bolt spacing, the larger the reinforced "compression" beam developed in the excavation roof. Installing bolts closer

to pillar edges may result in more stability, as the compression zone is effectively transferred from the roof to the pillar.




Figure 2.4: Model for granular material supported using rock bolts (Hoek)

Bolt length is more of an issue for mechanical-anchor bolts than fully-grouted (although is important for both types), because resin bolts can achieve the capacity of the support with about 2 feet of length. Mechanical bolts need to be long enough to anchor in a stable bed, which may be 6 or more feet above the immediate roof (Dolinar, 2000). The highest bolt loads typically occur at the center of the intersection so if the roof is failing in tension, it may be beneficial to increase bolt length (mechanical) or to increase rebar diameter to #6 (resin) in these areas to strengthen the contact area and anchorage to resist the greater bolt load (Mark, 2000).

2.4.2 Secondary and Supplemental Support Devices

Additional support that is installed after excavation may be installed routinely throughout the mine as part of the ground control plan, in intersections for stability, or used exclusively in local areas where geological problems are occurring. Roof fall history

in a particular area and industry experience are two of the contributing factors affecting the usage and placement of various types of secondary and supplemental support.

Support systems such as cable bolts and truss bolts are installed in the roof for support in addition to the primary bolting pattern. Similar to a standard roof bolt, cable bolts have an anchored end in resin typically with an effective length of 4ft of grout that is attached to a cable within the rock, attached to a roof plate. A bulb or birdcage twisted within the cable helps the resin grip and mixture, and increases the back pressure of insertion. Typically cable bolts can deform more than traditional bolts under the same load, but varying the resin length can increase stiffness to a desirable level for a particular geology (Mucho, 1998). Additionally, the flexibility of cable bolts is an advantage because long cables can be easily installed in narrow coal seams. Cable bolts generally have a higher yield and failure strength than rebar bolts, but they will eventually fail, unlike most properly installed yielding free standing support and they also cover less area. They do have advantages over standing support however, they cost less in materials/labor, are transported more easily, eliminate injuries from workers handling and constructing cribs, and reduce ventilation resistance (Mucho, 1998).

Truss intersection support systems started appearing in the late 1980's and have been gaining popularity as a method of supplementary support, or even primary support in some cases. Specialty systems such as the Intersection Truss are designed to support an entire intersection, using compressive forces in three dimensions. Keyblocks or laminations that lie between two truss bolts can cause stability problems, however. To add stability, the systems can be placed before crosscuts are excavated, putting the

intersection in compression before it is even created (Seegmiller, 1990). Figure 2.5 shows the Intersection Truss product by Western Support Systems.




Figure 2.5: Intersection Truss system (Seegmiller, 1990).

There are many types of free standing support available for use in the mining industry. Timber posts and cribs have historically been the dominant products, however their relatively low early stiffness and relatively high total installed cost has necessitated the development of alternative support systems (Barczak, 2005). Dozens of different types of free standing support have been created, including pumpable cribs, steel cans and props, and engineered cribs from materials such as coal combustion byproducts. The selection of which product to use depends on the geology and loading characteristics of the roof, the pillar strength, and other site-specific factors. Resources such as the ground reaction curve, if available, can be utilized in the selection of roof support products. The ground reaction curve concept will be discussed in Section 2.6.4. It is important to note that floor heave and pillar yielding cannot be completely eliminated by standing roof

support system. The convergence associated with these problems should be considered “uncontrollable” and the support product needs to be able to survive that deformation without being damaged to the point of losing required roof support capacity (Barczak, 2001).

2.5 Mathematical Models of Roof Stresses and Failures

2.5.1 The Beam Model

In the beam model, the roof is considered to be a single piece beam supported at both ends by the pillars as shown in Figure 2.6.




Figure 2.6: Beam Theory Model

The beam is considered to be rigidly clamped at the ends so that no rotation or motion is possible. In a classic beam theory model, the load on the beam comes from its own weight and depends on the thickness of the beam. Load forces are considered to be the vertical downward force of the beam’s own weight. In understanding what features of a real coal mine setting are captured by beam theory, one considers that the stiffness and resistance to bending of a rock layer is proportional to the rock layer thickness and modulus of elasticity. In an unsupported setting, some subset of the rock layers between the mine opening and the surface will be less stiff than the rock layers above. These rock layers will sag away from the rock above causing bed separation as shown in Figure 2.7.




Figure 2.7: Separation of Roof Strata (Brady, 1985).

If fully grouted roof bolts are used, then the rock layers are often considered as if they were held together in a single beam and one might consider the units that separate from the rocks above to form the beam as having the thickness of the length of the roof bolts. In still another case, some of the rock layers above the beam formed by the roof bolts may be less stiff than the rock layers above, causing rock strata above to rest and apply an extra load to the beam beyond its own weight. In all cases, the coal below and the rock above the beam and over the pillars is modeled as rigid and inflexible, thus imposing the rigid hold on the ends of the beam. The following information and formulas are from Dr. Y.P. Chugh's notes for Rock Mechanics: Principles and Design (2009).

Let γ be the unit weight of distributed load on the beam as shown in Figure 2.8.




Figure 2.8: Distributed beam loading (Modified from Chugh, 2009)

One then lets L stand for the length or unsupported span, t for the beam thickness, and E the modulus of elasticity. This model has been solved mathematically to show that the maximum normal stress is:

$$\sigma_{xx(\max)} = \frac{\gamma L^2}{2t}$$

One cause of beam failure is tensile stress in the beam, and the beam breaks at the point when the tensile stress on the beam exceeds the tensile strength of the rock. The maximum deflection (η_{\max}) at the center of a beam is affected even more by an increase in the span:

$$\eta_{\max} = \frac{\gamma L^4}{32Et^2}$$

One can consider this model further examining shear stresses attempting to slice the beam in two. The shear stress is represented by the equation:

$$\sigma_{xz(\max)} = \frac{3\gamma L}{4}$$

A typical range of tensile strength for coal mine roof rocks is 150 to 500 psi (Chugh, 2009) and a typical value for shear strength is approximately 170 psi (Esterhuizen, 2009). Most coal mine roof rocks are about 10-15 times stronger in compression than in tension. Solving the beam equation one finds the maximum shear stress occurs at the ends of the beam, and the shear stress is much smaller than the tensile stress. This is due to the fact that the tensile stress increases exponentially with length, while shear stress increases at a linear rate. With this considered, one might expect failure to occur at the center of the beam at the point of maximum tensile stress. W.C. Patrick (1980) conducted a study on frequency of roof failure types and found that massive dome

failures occur in approximately 66% of intersection falls, with the great majority of falls being longer than the typical intersection width of 20 ft. These results seem to correspond rather poorly to a tensile failure occurring at mid-span and instead point to a shear failure at the pillar edge.

Still another real life complication involves stress fields. The classic beam theory model considers that stress is driven by the downward pull of gravity. In fact, in many areas there is a tectonic stress field that imposes compressive forces from the sides. Depending on the orientation of the rooms and entries relative to the maximum horizontal stress, it is possible for the compressive forces to reduce the tension within the roof beam.

Given these considerations, it appears that the beam model may not correspond well to regular modes of failure seen in the field. Several aspects of the beam model seem inaccurate when one applies it to analysis of intersection failures, because the area in cross section does not extend indefinitely as the 2D model suggests. When the roof length is twice the width, beam theory may be used for entries but when the length is less than twice the width as in intersections, the stress and deflection calculations must be based on the Flat Plate Theory (Chugh, 2009).

2.5.2 The Plate Theory Model

From Dr. Y.P. Chugh's course notes for Rock Mechanics: Principles and Design, flat plate theory considers a rectangular plate that is clamped at all corners and is based on the following conditions:

- 1) The plate is a straight, flat structural element whose width is at least 4 times the thickness and whose length is equal to or greater than its width.
- 2) Material is elastic, homogeneous, and isotropic.

- 3) Maximum deflection is one half the thickness.
- 4) All loads and reactions are normal to the plate.
- 5) When the plate deflects, the central plane remains unstressed.
- 6) Vertical straight lines before flexure remain straight but become inclined to the vertical. The normal stresses in the plane of the plate are proportional to the distance from the central plane.

For such a plate clamped rigidly at four corners, the maximum deflection occurs at the center of the plate and is given by:

$$\eta_{\max} = \frac{\alpha q a^4}{Et^3}$$

Maximum normal stress is found using the following equation:

$$\sigma_{.xx(\max)} = \frac{6\beta q a^2}{t^2}$$

Where q is the uniformly applied load per unit area, a is the cross-sectional area of the plate, α and β are coefficients for a uniformly loaded rectangular plate. A typical intersection has a length to width ratio of 1.0, so the coefficients for α and β are 0.0138 and 0.0513 respectively. These coefficient values were obtained from Dr. Y.P. Chugh's course notes for Rock Mechanics: Principles and Design and are standard inputs for this equation when Poisson's ratio is equal to 0.3. The value for $q = \gamma * t * b$, where b is the length of the plate. Table 2.1 shows an example of the changes in stress and deflection that occur from a 16 ft. to a 22 ft. entry span. A mining depth of 400 ft. and an immediate roof thickness of 12 in. were used in the example. As seen below, the 22 ft. span has over three times the deflection and almost double the maximum stress as a 16 ft. entry.

Table 2.1: Plate Theory Analysis of Entry Widths

	16' Plate	18' Plate	20' Plate	22' Plate
Opening length	16	18	20	22
Opening width	16	18	20	22
E	725000	725000	725000	725000
α	0.0138	0.0138	0.0138	0.0138
β	0.0513	0.0513	0.0513	0.0513
q	0.53208	0.53208	0.53208	0.53208
γ	0.04434	0.04434	0.04434	0.04434
Thickness (in.)	12	12	12	12
Area (in.)	192	216	240	264
σ_{xx} (psi)	41.93	53.06	65.51	79.27
η_{max} (in.)	0.008	0.013	0.019	0.028

The beam and plate theory equations show that a minor increase in diagonal span can cause much higher levels of deflection and stresses, and a decrease in stability. The large span in the intersection causes more vertical stress relief, and makes it easier for the roof to yield due to the lower level of vertical confinement. It also causes more shear stress over intersection corners, and increases probability of shear failure (Zhang, 2003). Additionally, the modulus of elasticity (E) has a major impact on roof stability and design of safe room and intersection spans.

Estimates for safe roof spans in U.S. coal mines may be more effectively determined by means of engineering rock mass classifications designed for coal applications. Reliance solely on beam and/or plate theories is not recommended due to uncertainties in the assumptions, as well as in the required input data (Bieniawski, 1983). Geological strata are unlikely to be elastic, homogeneous, and isotropic, and values of Young's modulus and immediate roof thickness can vary locally throughout a deposit. Additionally, any discontinuities or water present make it more difficult to deal with a rock mass using

ideal engineering conditions such as a plate or a beam (Gadde, 2007). The use and application of rock mass classifications will be discussed later in this chapter.

2.6 Previous Studies of Roof Stability

2.6.1 Horizontal Stress Fields

Horizontal in-situ stress is a major issue that affects roof strata behavior, and orienting the entries in a particular direction can increase intersection stability significantly. Numerical 3D modeling has shown that intersections are most stable when the direction of maximum horizontal stress (σ_{hmax}) is square with the intersection and not stressing the roof across the diagonal span. (Gadde, 2004). Entries are most stable only in the direction of σ_{hmax} (and least stable at 90° to σ_{hmax}), therefore the most stable condition for both entries and intersections is to have entries parallel to maximum horizontal stress. This optimum orientation is shown in Figure 2.9.




Figure 2.9: Entry Orientation for Maximum Stability

The ratio of horizontal stress to vertical stress (σ_{hmax}/σ_v) is referred to as a k value, and high values can be an indicator of potential roof control problems. Additionally, extremely low k values can cause as much potential instability as high values (Gadde,

2004). The effect of low and high k values on safety factors can be seen in Figure 2.10, which was created by M. Gadde using computer modeling.




Figure 2.10: Effect of low and high k values on safety factors (Gadde, 2004)

The roof layers (referred to as bed numbers) in Figure 2.10 begin with the weak immediate roof and end with the highest, most stable strata. This graph shows that an optimal k value for highest safety factor is between 0.5 and 1.0, with lower or higher ratios producing lower safety factors. Orienting entries optimally is an excellent way to increase entry and intersection stability, and decrease primary and supplementary support costs. Areas that experience extremely low or high horizontal to vertical stress ratios can potentially benefit from orienting their entries appropriately to optimize their roof stability.

2.6.2 Humidity Impacts

Another factor in the stability of coal mine roof strata can be the amount of humidity in the air. Figure 2.11 shows that the roof fall rate (roof falls per 100 employees) increases in the humid summer quarter in most coal regions of the United States, but the change is most pronounced in the Illinois Basin (Molinda, 2006).




Figure 2.11: Seasonal roof fall rates for U.S. coal basins (Molinda, 2008)

Environmental effects such as atmospheric moisture, barometric pressure and temperature are especially influential on the moisture-sensitive shales that commonly occur above or below an extracted coal seam, as in the Illinois Basin. Dr. Y.P. Chugh suggests there are three ways to deal with moisture effects on weak rocks: control of humidity changes, reducing moisture migration in shales, and rock reinforcement (Chugh, 1982). Controlling humidity is an expensive option, using tempering chambers to condition the surface air to match temperature and moisture equilibrium throughout the mine. Some mines have attempted continuous wetting to reduce varying humidity levels, although this method is not very popular. Reducing moisture migration into shale rocks can be achieved by leaving coal in the roof, using resin bolts, or applying mine sealants (Chugh, 1982). Using sealants to prevent moisture migration gained popularity in the 1970's, although areas of high air velocity can be problematic due to artificial dehydration of the sealant. Steel-reinforced gunite and dry shotcrete was used at the Wabash mine in 1975 for stabilizing entries with immediate shale roofs (Chugh, 1982). A recent study by Peter Zhang also suggests that a thin layer of polymer-based sealing

material may be an effective and economical option for preventing weathering in long-term track and belt entries (Zhang, 2009).

2.6.3 Roof Rock Mass Rating Systems

One alternative to plate or beam theory is geological classification systems such as the CMRR (Coal Mine Roof Rating). The CMRR, developed by the U.S. Bureau of Mines in 1994, is an empirically based engineering classification that evaluates roof discontinuities which most contribute to the weakness and failure of the roof mass. The rock sample is assigned a number between 0 and 100 that can be used in engineering calculations to help in pillar design, intersection sizing, and other applications.

As explained by G.M. Molinda, determining the CMRR value is a two-part system. The Unit Rating of each rock strata in the bolted interval is determined by evaluating the discontinuities in the rock with simple field tests such as a hammer and chisel strike. Points are assigned for the spacing and frequency of joint sets, bedding planes, and other discontinuities, and points deducted for moisture sensitivity and multiple discontinuities.

The second part of the CMRR is to determine the Roof Rating. The thickness-weighted average of the individual Unit Ratings is determined, and adjustments made for the presence of a strong bed in the bolted roof. Additionally, the Roof Rating can be adjusted for weak Unit contacts or groundwater inflow. Typically roofs with $CMRR < 25$ fall very soon after mining, so the safer working range is 25-100 (Molinda, 2001). Case studies by G. Molinda confirm that a higher CMRR is related to lower number of roof falls. Even a difference of 10 points on the CMRR scale can affect roof stability significantly. One mine in West Virginia had a weak shale ($CMRR=40$) fall rate that was

3.4 times the strong shale (CMRR=50) fall rate (Molinda, 1998). In addition to the mine-wide geology, localized geologic anomalies are a major driver in roof stability and the support that may be required. The CMRR system is most applicable to gaining an understanding of the minimum support that will be needed in most parts of the mine, and additional support may be needed in problem areas such as faults and slip zones. Case studies have revealed that roof deflections at slip zones may be seven times greater than deflections measured in intact roof areas, indicating local movement along slip planes (Hanna, 1986).

2.6.4 Ground Reaction Curve Concepts

The goal of any support system is to achieve the equilibrium of the rock mass around the excavation in the most cost effective manner. A concept called the ground reaction curve has been used in the tunneling industry for many years (Brown et al., 1983) and can be utilized to estimate how much support is needed to achieve roof equilibrium. These curves plot the support pressure against the convergence, as shown in Figure 2.12.




Figure 2.12: Illustration of a ground response curve (Barczak, 2006)

Before excavation, the boundaries have stress equal to the in-situ field stress (Point A in Figure 2.12). Once the excavation is developed, the reactive/support stress that is required to prevent additional convergence reduces as the rock structure begins self-supporting (Point B). Once total rock failure occurs (Point C), and self-supporting capacity is lost, the rock deformation/deterioration accelerates and the required reactive load to create stability increases significantly. Equilibrium for the example shown is at Point B, when the support curve intersects the ground reaction curve. Using numerical modeling, these ground reaction curves and support interactions can be established to find the optimal method of support for a particular roof geology and location (Speers and Spearing, 1996 and Barczak, 2006).

2.6.5 Empirical Observations About Cutter Roof

The specific problem of cutter roof failure (or shear failure directly above pillars) has been investigated and studied intensively by researchers (Hill 1984, Anil Ray and Syd Peng 2009). Cutter roof failure is one of the most common ground control problems affecting the safety and economy of an underground coal mine operation (Ray, 2009). The massive roof falls that are typically associated with this type of failure have more potential for injury or loss of life than a small skin failure, due to the large area that they cover and the larger collapsed mass. The simple and traditional definition of a cutter refers to “fractures that occur at upper corners i.e. the intersection between the roofline and the pillar ribline.” (Peng, 2007.) Cutter failure initially begins as a fracture along one or both riblines, and continues vertically into the roof. When this fracture reaches a height above the anchor horizon or breaks along a weak bedding plane, a massive failure may occur (Hill, 1984). This mechanism can be seen in Figure 2.13 below.




Figure 2.13: Cutter roof failure diagram (modified from Hill, 1984).

Some of the common observations that Peng (2007) has found from the case studies of cutter roof failures are as follows:

- The cutters can form at all working places in entries and crosscuts.
- The duration for the cutter development may vary from 5 minutes to several hours. Thus it can form immediately after the continuous miner's cut or after several feet of face advance.
- The development stages of cutters can be different depending upon the site specific parameters.

- The immediate roof was typically highly laminated and it may be one of the important reasons for the immediate development of the cutter.
- The maximum horizontal stress orientation may influence the cutter formation.
- The cutters develop in sequences and progressively extend upward away from the roof and rib corner.
- The cutters are sometimes very irregularly distributed.

Past research on the topic of cutter roof failure has identified several factors that affect the location and severity of falls such as: magnitude and direction of in situ stresses, stress inducing activities (multiple seam extraction), mechanical properties of roof rocks and coal, geometry (entry width and pillar size, etc.), and geological disturbances (Ray, 2009). Research from the U.S. Bureau of Mines has shown that high horizontal stress fields, as well as the presence of clastic dykes (commonly called clay veins) can have an impact on where cutter failure will occur. Additional research using rock monitoring near clastic dykes has revealed that the roof strata were in fact behaving like a cantilever beam as shown in the previous figure. This beam would then initiate cutter roof failure, developing along an entry or crosscut often across several breaks (Hill 1984).

It is clear from the sources examined for this literature survey that shear (or cutter) failure of the roof above intersections is a serious problem, and a greater understanding of this failure and possible methods of controlling it will be beneficial to the safety and productivity of underground coal mining.

CHAPTER 3

RESEARCH OBJECTIVES AND PROCEDURES

3.1 Statement of the Objective

The objective of this thesis is to identify common characteristics of unplanned roof falls and support methods currently used, and to make recommendations to improve rock fall related safety.

3.2 Work Steps to Achieve the Objective

This study is to have 4 key work components. 1: Compiling a U.S. coal industry wide survey on roof support methods. 2: Analyzing the MSHA 7000 50a forms on roof falls. 3: 2D Finite Element Modeling of failure modes. 4: Statistical analyses of data compilations.

3.2.1 Survey of Roof Support Methods.

The end goal of the roof support survey was to obtain data from a majority of actively producing underground coal mines and examine the methods of roof support that are frequently being used in the industry. Other than sales data provided by roof bolt manufacturers which includes tunneling applications, the author is not aware of any such industry-wide surveys to the mines about their current methods of roof control. Mark Odum, the MSHA Ground Control Supervisor for District 8 maintains a good data set for his District, but it is limited to the Illinois Coal Basin. This survey database provides a current industry-wide snapshot of what mines are currently using.

This study, conducted during the summer of 2008, includes data that was gathered using a survey mailed to the mines that resulted in an 18% response rate. Following the mail survey, mines that did not respond were contacted by telephone for their

information; however some were unwilling to provide the details of their ground control. By law every mine needs to submit a Roof Control Plan to MSHA and this is public information, but the mines typically detail a bare minimum of support in their official plan and it may or may not be close to the actual support being used. This potential discrepancy in data is the reason the mines were surveyed directly about their ground control rather than using the publicly available plans. Information from a total of 70 underground mines was obtained that represents approximately 235 million tons of raw coal in 2007, or about 66% of the U.S. underground tonnage. Of these 70 mines, 28 used mainly longwall mining and 42 used the room and pillar method. Surveyed data included: mining method used, extraction height, average room width, maximum primary bolt length and diameter, bolt type (active/passive), and secondary support used. These mining and support conditions are what the mine reported as being used most frequently, and may not represent additional supplemental support deemed necessary by production personnel working in specific and unique strata conditions. Information collected from the surveys was standardized and inputted into Microsoft Excel for further analysis.

3.2.2 Compilation of MSHA 7000 50a Reports

The largest collection of U.S. data on unplanned roof falls is believed to be the MSHA 7000 50a forms. These forms are the most reliable data available on roof falls because they are the basis of any federally enforced fines or court investigations if necessary. Under the new MINER Act of 2006, coal mines are required to report unplanned roof falls to MSHA within 15 minutes of discovery. MSHA then has the option of sending inspectors to investigate the scene when a roof fall is reported. These 7000 50a forms are only written if an inspector chooses to investigate a particular event.

Nine of the 11 MSHA district offices were personally visited over a total of 12 days including travel to collect information from these reports and discuss the falls with MSHA personnel. District 1 (Wilkes-Barre, PA) was not visited because the anthracite mines had too few unplanned falls of ground in the database, and District 9 (Denver, CO) was not visited due to cost constraints. The data collected from 7000 50a reports represents over 600 falls of ground compiled over the summer of 2008. These reports include such details as: dimensions of the fall, primary support used, and the stand-up time before the fall. This aspect of the study is believed by the author and funding agency (NIOSH) to be unique in that no previous work has ever comprehensively examined a full inter-regional data set for roof fall patterns. More limited region specific examinations have been done, for example in the Illinois Basin (Gregory Molinda 2008; W.M. Kester and Y.P. Chugh 1980; W.C. Patrick and N.B. Aughenbaugh 1980). The national scope of work done here exceeds the geographical reach of these previous studies.

Although they are the most reliable fall data available, MSHA 7000 50a reports have potential biases and inconsistencies that could potentially affect results. Not every roof fall triggers a 7000 50a report so the data source begins with a bias as to what type of falls produce data. The law itself only requires operators to report roof falls that occur at or above the anchorage zone in active workings where roof bolts are in use; or, an unplanned roof or rib fall in active workings that impairs ventilation or impedes passage. There may be numerous spalling or crumbling incidents that fall short of the reporting requirement. On the other hand, since the motivation for this study is the large cost, productivity, and safety impacts that unplanned roof falls create, one would

probably only wish to focus on roof falls that rise to the level of creating significant impacts in those areas. The data set bias may thus be useful to the purpose of this work. There is another step of bias in that not every reported fall triggers a 7000 50a investigation. One would expect that only the larger falls would warrant this type of attention from MSHA inspectors.

Discussions with MSHA inspectors and individuals in the industry have suggested that a large number of unplanned falls tend to be massive and extend longer than the intersection width and higher than the bolt length. This suggests that increasing bolt length may not be the solution, because the bolts are creating a massive beam that eventually shears above the ribline and falls in a dead weight manner. The bolts create a solid beam and are usually effective at controlling tensile failure and skin failure, but the current support practices may be inadequate to stop a shearing/cantilever fall along the pillar edges. Again, a bias that focuses attention on roof falls large enough to impact productivity, cost and safety is not necessarily undesirable.

There are inconsistencies between districts on the recording of additional fall details such as water presence, cutter presence, and stand-up time before the falls. MSHA districts often function fairly independently of one another in implementing the Mine Health and Safety Act. While this provides for regional needs and flexibility, it can also generate inconsistencies in the way data is recorded that can impact many statistical analysis techniques, since many of them depend on putting data into standard categories. There are also measurements that are easier to write down on paper than to measure in a field setting. Inspectors must estimate fall dimensions without standing directly under the

unsupported roof, and they cannot safely detail the roof geology for example. The mine operators are typically present as well, so there is some validity to these estimates.

Data collected from the fall of ground study was organized using Microsoft Excel and plotted on graphs to view the averages and distributions of fall dimensions that were reported.

3.2.3 Finite Element Modeling of Failure Modes

To examine the common mode of failure that was observed in the study of unplanned roof falls, it was decided that computer modeling would be beneficial. The goal of this simulation was to create a model that would replicate a “cutter” type failure by breaking along the riblines to a weak roof layer and falling in a massive beam. Support modifications, such as installing longer bolts or angling bolts over pillars, could then be tested for their stability changes. Rocscience’s Phase² finite element analysis program was used for these simulations. This 2D program was chosen because it is commonly used by SIU students, NIOSH, and others to analyze simple underground excavation models. Using more complicated 3D software to simulate the type of failure observed is outside the scope of work here and could be considered a PhD dissertation topic itself.

A coal mine intersection profile was set up in Phase² 7.0, with bolt and rock characteristics that would be seen in a typical coal deposit at a depth of 500ft. At this depth, a vertical stress of 500 psi could be expected, assuming an overburden density of 144 lb/ft³. Similar to a study by C. Mark (2007), a horizontal stress of twice the amount of vertical stress could be expected, and this value was set at 1,000 psi. The intersection width was set at 20ft., and an extraction height of 6ft. Total model dimensions were

170ft. wide and 100ft. high to minimize any errors from stresses at the outside of the model influencing the center excavation. Boundary conditions were as follows, at the recommendation of Rocscience and G.S. Esterhuizen: sides of the model were restrained in the X direction, the top of the model was restrained in the Y direction, and the bottom edge was restrained in both X and Y directions. Figure 3.1 below shows the strata that were used in the model and the thicknesses of each layer.




Figure 3.1: Rock strata used in Phase²

Accurate input parameters such as tensile strength, Young's Modulus and Poisson's Ratio are crucial in obtaining accurate output in computer simulation, so this information was provided by Dr. Y.P. Chugh of Southern Illinois University, and NIOSH. Rock mass properties for each layer can be seen in Table 3.1.

Table 3.1: Input Rock Strata Values

Rock Type	Young's Modulus (psi)	Poisson's Ratio	Tensile Strength (psi)	Friction Angle	Cohesion (psi)
Limestone	750,000	0.2	700	25	2900
Poor Shale	100,000	0.3	150	25	290
Weak Limestone	400,000	0.2	700	25	1740
Grey Shale	350,000	0.25	200	30	653
Black Shale	200,000	0.25	200	30	479
Coal	150,000	0.28	100	26	87
Claystone	45,000	0.32	50	20	290
Shale	200,000	0.3	150	25	290
Sandstone	450,000	0.2	800	25	1740

After the model was created, it was run initially to verify that it was providing stresses and displacements that could be expected in an underground mine. Once it was confirmed the model was behaving realistically, simulations were run with ¾” diameter bolts. Both 4 ft. and 6 ft. lengths were used on 4 ft. spacing, as well as bolts angled over pillars to identify possible stability improvements of this method.

3.2.4 Statistical Analysis of Collected Data

The data from the 7000 50a reports that were collected was analyzed using SPSS 13.0 software from SPSS Inc. Statistical analysis of variance (ANOVA) tests were conducted on the fall of ground data to determine which independent variables affected fall length, width, height, and volume. The independent variables that were analyzed include MSHA District, bolt type (active/passive), bolt length, stand-up time before the fall, immediate roof thickness, and the presence of water or cutters near the fall. It is important to note that geology is regarded as one of the most important factors in roof fall occurrence and severity, and is specific to each site. Therefore, statistical analysis may or may not draw significant conclusions due to the wide variance between mines. Data recording inconsistencies by human beings can also raise the noise level and obscure

trends. Finding answers to the problem of mine roof falls can deal with needs for improved data as well as needs for improved practice.

The variables that resulted in the highest ANOVA confidence levels were analyzed further using regression analyses which was used to fit linear or curved models to the plots in an attempt to find more exactly how independent variables affected the dependent variables.

CHAPTER 4

STUDY RESULTS AND DISCUSSION

4.1 Intersection Support Survey

4.1.1 Summary of Results

Complete results of the intersection support survey by state are listed in the Appendices, and the results that follow are averages for all mines that were surveyed.

- The heights of the numerous different coal seams mined tend to vary from 3.5 to 8 ft. in the east, and 6 to 12 ft. in the west.
- Entry widths (rooms) are typically from 18 to 20 ft.
- Primary rock bolt support spacing (on cycle) is commonly 4 ft.
- Primary bolts vary in length from 3.5 to 8 ft.
- Cable bolts are commonly installed as secondary support in intersections, with lengths typically between 8 and 16 ft.
- Only two mines (both in Illinois) regularly installed bolts at a 45° angle over pillars. Neither mine had any 7000 50a forms on record at the time when the MSHA District 8 office was visited.
- The bolts closest to the rib are most commonly installed 3 to 4 ft. from the edge.

4.1.2 Complete Survey Results

The data collected from mines about their maximum reported room width did not include any rounding of pillars that may take place, or smaller rooms that were created locally due to adverse roof conditions. An analysis of the room widths given is in Figure 4.1 and it can be seen that a room width of 20 ft. is the most common, with 54% of the mines surveyed using 20ft. rooms.




Figure 4.1: Maximum reported room width

There was a wide distribution of mining heights that were reported, varying primarily according to the geographic location of the mine. For example, the western states of Utah, Colorado and New Mexico had higher average extraction heights than Midwestern or Eastern mines. From Figure 4.2, it is observed that the majority of mines have 5 to 7 ft. mining heights. A few mine locations had varying seam thicknesses, so the maximum value that was supplied is used in calculations and graphs.




Figure 4.2: Mining height distribution

When examining the roof bolt anchors that mines used, a few stated that they utilized both passive and active systems. The primary bolt type that was used is shown in Figure 4.3. It is important to note that none of the data in this study was normalized to each mine's production; it only reflects the total number of mines that reported using a

particular support method. Normalizing data to individual mines' production is a task beyond the scope of this study and would be difficult to accomplish accurately, as some mines used both systems. There were 47 mines that reported they primarily used passive bolt anchorage, and 23 reported active bolts. Of the 23 mines that reported active bolt systems as their main roof support, there were 16 (70%) using partially grouted bolts and the rest were mechanically anchored. There is an ongoing debate as to the preferred system and when they should be used, and it is the subject of a large NIOSH funded project led by Sam Spearing of SIU and Murali Gadde of Peabody Energy. The current consensus seems to be to use active support where the immediate roof is stack rock, although the overall popularity of passive bolt systems has been increasing during the last two decades (Dolinar, 2000). The term "stack rock" refers to thinly laminated rock layers that are usually weak.




Figure 4.3: Bolt types used

A significant portion of the mines reported that they used different diameter bolts for different applications, so Figure 4.4 was constructed using the largest reported bolt diameter that was regularly used at each mine. The most common bolts were .75" diameter (or #6 bar) with 41% of mines surveyed. This was followed by .625" diameter (#5 bar) bolts that accounted for 31%. As mentioned in the literature review in Chapter 2, Dolinar's research suggests that the optimal size bolt in a 1" hole is #6 bar.




Figure 4.4: Bolt diameter distribution

Bolt length data was also gathered during the surveys. Shown below in Figure 4.5 are the maximum bolt lengths that were reported, and the frequency of each. The most popular were 6 ft. bolts. A major factor in which bolt length is used is the coal seam height; there were only a handful of locations that reported using bolts longer than the mined height, possibly due to the added time and effort of bending bolts. There may also be a level of strength reduction caused by notching bolts to make them bendable. Data from Figures 4.4 and 4.5 were combined to form a chart showing how frequently each bolt length was used, separated by diameter. This is shown in Figure 4.6 and it displays that #6 bar 6 ft. long is by far the most popular bolt used in the mines that were surveyed.




Figure 4.5: Bolt length distribution




Figure 4.6: Bolt length distribution by diameter

Modern roof bolters are equipped with large mobile canopies to protect the operators, but many of these prevent the rock bolts from being installed closer than about 2 ft. from the pillars. Also, many bolter models cannot drill angled holes. Displayed in Figure 4.7 is the reported distance that primary rock bolts are installed from the pillars at the surveyed mines. It is interesting to note that at this time, Murali Gadde of Peabody Energy is having discussions with mines and manufacturers about solely using roof bolters that have the ability to install the first row of bolts closer to the pillars, and can angle bolts over pillars as well (Spearing, 2009). This may create a more stable environment at the roof-rib intersection where shear stresses are a maximum (also called the pillar knife edge).




Figure 4.7: Distance of nearest primary rock bolt to pillars

Figure 4.8 below shows the maximum length of cable bolts that the surveyed mines used. Approximately 70% of the mines used cable bolts as regular secondary support, and the rest either used them only in adverse conditions or did not use them at all.




Figure 4.8: Maximum cable bolt length distribution

About 90% of the mines surveyed used some type of supplemental free-standing support; however there did not seem to be a clear pattern relating to room size, bolt size, or other values that were surveyed. The supplemental support is typically installed according to geological conditions at a site which can vary widely at a single mine. Supports that were routinely used included: Timber props, posts, and cribs, pumped concrete posts, cans, and yielding and non-yielding steel props.

4.2 Unplanned Fall of Ground Study

An analysis of the unplanned falls of ground has revealed intriguing results. According to data collected, the average roof fall was 53 ft. long, 20 ft. wide and 8 ft. high. Figure 4.9 shows the distribution of intersection fall thicknesses that were found in the study. Most of the unplanned roof falls extended above the common primary bolt length of 6 ft. that was found in the intersection support survey. Falls reported to MSHA are not always at or above the anchorage height, as smaller falls can still be considered to be unplanned falls of ground if they impede passage or impair ventilation.




Figure 4.9: Unplanned fall of ground thickness

The relationship between fall thickness and bolt length installed was examined further, and these parameters are compared side by side in Table 4.1. This information was obtained for a total of 607 unplanned intersection falls of ground and confirms that most falls are at least as thick as the primary bolt length, and thus lengthening bolts may not be the solution. Longer bolts simply laminate a thicker beam which tends to fall when cutters reach the higher level. The presence of secondary or supplemental support was not frequently recorded in the MSHA 7000 50a reports and may not be totally accurate if such support was not visible under the falls. For the most part, where cables were

reported to be installed the falls were often above the cables. Unfortunately, the data available on presence of cutters in the roof at fall locations was reported too inconsistently to be of significance.

Table 4.1: Relationship of primary bolt length and fall height

Primary bolt length (ft)	Average fall height (ft)	No of data points
< 3	4.5	19
3.01 to 4.0	6.2	163
4.01 to 5.0	7.3	185
5.01 to 6.0	8.4	204
6.01 to 7.0	9.2	8
7.01 to 8.0	9.4	28

Figure 4.10 shows the length distribution of the unplanned intersection falls of ground. As shown in the chart below, a large percentage of unplanned roof falls extended beyond the average intersection width of 20 feet that was found in the mine surveys. Only about 12% of the roof falls were smaller than the intersection width. Informal comments by MSHA employees and mine personnel verified that most falls seem to be massive, extending to, or more frequently past the width of the intersection.




Figure 4.10: Unplanned fall of ground length

The results for fall length and fall thickness mirror a study conducted in 1980 by W.C. Patrick in which dimensions of roof falls were analyzed, mainly in the Illinois Basin. (Aughenbaugh, 2009).

Figure 4.11 below shows the fall length versus fall width, note the two falls that extended to almost 1,000 feet in length. Figure 4.12 shows the clustered results in more detail, and makes it easier to see the small number of falls that would be contained within a typical 20 x 20 ft. entry.




Figure 4.11: Fall length vs. fall width




Figure 4.12: Fall length vs. fall width (detail)

Figure 4.13 shows the relationship of stand-up time to the frequency of unplanned falls of ground. The individual graphs from each district are similar to this chart, and have the same bimodal distribution of stand-up times before roof falls.




Figure 4.13: Stand-up times for unplanned falls of ground

The amount of falls occurring much later than a month or two suggests that weathering of rock layers and possibly anchor deterioration, particularly by corrosion, may be issues. On the basis of this data, the Illinois Clean Coal Institute (ICCI) agreed to fund a bolt corrosion project led by Dr. A.J.S. (Sam) Spearing in collaboration with Dr. K. Mondal so more information can be gathered about this potential problem.

Discussions with MSHA inspectors while collecting roof fall data have suggested that a majority of unplanned falls tend to be massive and extend longer than the intersection width and higher than the bolt length. This suggests that increasing bolt length may not be the simple solution, because the bolts are creating a thicker massive beam that eventually seems to shear above the ribline and fall in a dead weight manner. The bolts create a solid beam and are usually effective at controlling tensile failure and skin failure, but the current support practices may be inadequate to stop a shearing/cantilever fall along the pillar edges.

4.3 Finite Element Modeling of Failure Modes

To test the validity of input data, the Phase² model described in Section 3.2.3 was run with a standard support system of 6 ft. bolts on 4 ft. spacing. The weak immediate roof showed deformation, and the floor was buckling upward slightly, which is a realistic response to the applied stresses. This roof and floor displacement is shown in Figure 4.14.




Figure 4.14: Roof and floor displacement

Although this model shows tensile failure in the center of the roof and does not display the massive failure mechanism that has been seen in real-world observations, it does compute the highest shear and normal stresses to be at the pillar edge where cutter failure begins. The actual cause of cutter failure along the pillar edge largely depends on geologic conditions and anomalies at a particular area, which are difficult to recreate in a computer model. The high principal stresses in all three dimensions that concentrate at

the pillar edge are displayed in Figure 4.15. As stress increases, the color spectrum on the figure changes from blue→green→yellow→red. Figure 4.16 shows the shear stress acting on the immediate roof, with much higher stress at the corners where massive failure typically occurs.




Figure 4.15: Normal intersection stress in three dimensions




Figure 4.16: Shear stress across intersection width

According to the 2D model, the amount of shear stress applied to the immediate roof above the pillars is a substantial amount, several times larger than the typical shear

strength of roof strata which is approximately 170 psi (Esterhuizen, 2009). Any geological discontinuities or cracks would be susceptible to becoming wider and deeper with the shear and normal stresses concentrated at the roof/pillar edge. Although the model did not show massive failure breaking to a greater depth than the roof bolts, trials were run to examine how support changes affected stability. Surprisingly, even adding two additional angled bolts a distance of 2 ft. from the pillars did not result in any reduction in stress or displacement from the standard 4 ft. bolting pattern. The axial load of each bolt was graphed and all bolts were loaded to some degree. A simulation was also run with no bolts, and this showed almost exactly the same stresses and displacements. To simulate the wide diagonal span across an intersection, a model was also run with a 28 ft. intersection and this yielded the same mode of failure and roof characteristics.

When the model was unsuccessful at demonstrating shear (cutter) failure above the pillars or improvements in stability as a result of support changes, numerous factors were adjusted in an attempt to “fix” the model and replicate the massive falls of ground that have been observed. Some of these factors were suggested by Rocscience and G.S. Esterhuizen of NIOSH, and include changing: cohesion, friction angle, strength of pillars and roof, and normal and shear stiffness of the roof joints. These manipulations proved to be unsuccessful and only resulted in minor stability changes according to the output; the failure was still in tension at the center of the roof in a dome fashion and did not represent the failure that is most commonly seen in coal mine intersections.

It is the author’s opinion that Phase² and 2-D modeling in general may not be powerful or comprehensive enough to capture the true shear behavior of the rock strata in the roof beam because it cannot model failure and dilation. The strength reduction that is

a result of combined buckling of layers and extension fracturing processes is beyond the capabilities of 2D elastic modeling software (Esterhuizen, 2008). From the comparisons between no support, 4 bolts, and 6 bolts, and the fact no stability changes occurred, it appears that Phase² also lacks the capability to compare support systems accurately. Additionally, the two-dimensional model represents a single continuous excavation and does not take into account the development of crosscuts and intersections, and the changes in stresses that occur over time. To demonstrate the massive shear failure that is observed in the mines, a more powerful program such as HcItasca's FLAC3D which can emulate progressive failure may prove to be more successful. Software with 3D capabilities can represent the intersections and crosscuts accurately, and how they affect roof stability.

4.4 Statistical Analysis of Collected Data

Statistical analysis of variance (ANOVA) tests using SPSS 13.0 were conducted on the fall of ground data to determine which independent variables affected fall length, height, and volume. The ANOVA analysis found a correlation between roof type and fall height, which is to be expected. To analyze this data, each roof type reported by the mines was assigned a number between 1 and 14. Dark shale and thinly laminated shale were the immediate roof types that resulted in more falls above 10ft than more competent roof strata such as limestone or sandstone. This ANOVA output table is represented in Table 4.2

Table 4.2: ANOVA test of roof type on fall height

Dependent Variable: Height

Source	Type III Sum of Squares	df	Mean Square	F	Sig.
Corrected Model	476.079 ^a	14	34.006	1.388	.154
Intercept	3020.586	1	3020.586	123.320	.000
RoofType	476.079	14	34.006	1.388	.154
Error	11732.534	479	24.494		
Total	46320.000	494			
Corrected Total	12208.613	493			

a. R Squared = .039 (Adjusted R Squared = .011)

The most important value considered on Table 4.2 is the p-value shown in the “Sig.” column, which indicates the percent chance for error. The p-value of .154 means there is a probability of 84.6% $[(1-.154)*100]$ that fall height is actually dependent on roof type. While statistical analyses typically require at least a 95% confidence level (thus a 5% chance of error), with the assumption of a wide variability in the geology and reporting of data there is a possibility these factors may be significant. Additionally, there was a correlation between fall length and District; this ANOVA table is displayed in Figure 4.3.

Table 4.3: ANOVA test of MSHA District on fall length

Dependent Variable: Length

Source	Type III Sum of Squares	df	Mean Square	F	Sig.
Corrected Model	142941.081 ^a	9	15882.342	3.280	.001
Intercept	1268219.760	1	1268219.760	261.940	.000
District	142941.081	9	15882.342	3.280	.001
Error	3471460.363	717	4841.646		
Total	5630973.000	727			
Corrected Total	3614401.444	726			

a. R Squared = .040 (Adjusted R Squared = .027)

It appears that due to the very low Sig. value shown in Table 4.3, there is a strong possibility that fall length varies according to MSHA District. The raw data was plotted, and in Figure 4.17 it can be seen that Districts 1, 4, and 10 experienced longer falls than the other Districts’ averages.




Figure 4.17: Fall length by MSHA district

Stand-up time and the effect on fall length was also found to be a significant relationship. From the ANOVA output in Table 4.4, the Sig. value for this test was .036.

Table 4.4: ANOVA test of stand up time on fall length

Dependent Variable: Length

Source	Type III Sum of Squares	df	Mean Square	F	Sig.
Corrected Model	180769.772 ^a	58	3116.720	1.497	.036
Intercept	264679.248	1	264679.248	127.126	.000
Standuptime	180769.772	58	3116.720	1.497	.036
Error	222775.987	107	2082.019		
Total	845572.000	166			
Corrected Total	403545.759	165			

a. R Squared = .448 (Adjusted R Squared = .149)

Regression analysis was used to fit linear or curved models to the plots in an attempt to find a correlation between variables. What appears to be a general downward trend in fall length with stand-up time is shown in Figure 4.18, although this may be due to the lack falls occurring after 300 months. If in fact a general reduction in fall length is occurring in these very late falls, a possible explanation may be during that extended timeframe, the areas exhibited cutters or other signs of weakness, and support was added which reduced the size of fall.




Figure 4.18: Stand-up time vs. fall length

Four-way ANOVA analysis showed that the combined factor of bolt length and water had an interaction effect on fall volume (with a p-value of .294) although it is unclear exactly how or if these two variables affected fall height together. The p-value for that test is very high by statistical standards and it is possible there is no interaction at all. This four-way ANOVA table is shown in Table 4.5.

Table 4.5: Four-way ANOVA test

Dependent Variable: Volume

Source	Type III Sum of Squares	df	Mean Square	F	Sig.
Corrected Model	1.594E+010 ^a	33	483080159.7	.709	.870
Intercept	1093326275	1	1093326275	1.606	.208
BoltType	37242837.7	1	37242837.722	.055	.816
BoltLength	1994016099	6	332336016.4	.488	.816
Water	162210987	1	162210987.3	.238	.626
RoofType	798634300	7	114090614.4	.168	.991
BoltType * BoltLength	125464611	2	62732305.725	.092	.912
BoltType * Water	37684509.1	1	37684509.091	.055	.814
BoltLength * Water	1687596168	2	843798083.8	1.239	.294
BoltType * BoltLength * Water	.000	0	.	.	.
BoltType * RoofType	.000	0	.	.	.
BoltLength * RoofType	571067462	3	190355820.5	.280	.840
BoltType * BoltLength * RoofType	.000	0	.	.	.
Water * RoofType	110906969	1	110906969.2	.163	.687
BoltType * Water * RoofType	.000	0	.	.	.
BoltLength * Water * RoofType	707469917	2	353734958.7	.520	.596
BoltType * BoltLength * Water * RoofType	.000	0	.	.	.
Error	7.354E+010	108	680883336.4		
Total	1.020E+011	142			
Corrected Total	8.918E+010	141			

The fact that there are very few (if any) statistical correlations between independent variables and fall dimensions suggests that: 1) Geological differences between sites and localized discontinuities are always a factor and will raise the probability for error in statistical analysis, or 2) Inconsistencies and errors in data reporting cause unreliable statistical results. The presence of cutters or water in the roof at a fall site was inconsistently reported across Districts, and the fact that fall dimensions are visually estimated introduces error as well. The reason for inconclusive statistical results is most likely a combination of widely varying geological conditions and reporting irregularities.

CHAPTER 5

CONCLUSIONS AND RECOMMENDATIONS

5.1 Conclusions

As mentioned in the previous chapter, this project has confirmed that simply increasing bolt lengths may not be the solution to massive shear failures, which seem to be caused primarily by local geologic conditions and shear stresses acting on the laminated strata beam. These massive failures have been shown to be very common, as only 12% of the falls studied were smaller than the average intersection width of 20 ft.

Figure 5.1 displays the rock bolt compression concept that was introduced in Chapter 2 and incorporates the bolt lengths and fall heights that were listed in Table 4.1. If the intersections are falling as a result of the cohesion/shear failure along the pillars, the height of the fall would then depend on that shear strength and would fail to a horizontal plane in the roof with limited or zero cohesion in a dead weight manner. The data to support this includes:

- The fact that the average fall height increased with increased bolt length.
- The informal observation from several MSHA inspectors that the falls in intersections tend to be massive in nature. These rock masses may be falling in one or several large blocks and breaking up due to impact with the floor.
- Comments from some inspectors indicated that the formation of cutters close to the pillars seemed frequently to be a pre-cursor to the falls.
- Over 75% of the unplanned falls extend to or beyond the total width of the intersection.
- Longer bolts seem not to be effective in resolving the fall problem.




Figure 5.1: Average results for primary bolt length and average fall of ground height (Spearing 2008)

4.2 Recommendations

If the mode of failure described is a correct hypothesis, then the solution would seem to be, in intersections where falls could be expected (based on prior knowledge/experience for example, or presence of rib rashing and cutters):

- Installing bolts closer to the pillars and also possibly angled over the pillars (to effectively increase the shear strength/cohesion against the roof and rib intersection). 3D modeling software that is able to exhibit the failure mechanism more accurately may be able to demonstrate the benefits in stability for this method. Installation of angled roof bolts near the rib has been suggested for mines as early as 1987, when W. H. Su recommended angle bolting at a mine experiencing frequent roof falls. He states, “Results of finite element analyses have shown that little improvement of roof conditions can be expected with the installation of angle bolts. Angle bolting, however, can delay or prevent roof falls at the rib-roof intersections” (Su, 1987). Additionally, the two Illinois mines that reported routinely angling roof bolts over pillars did not have any unplanned fall of ground reports at the District 8 office, although this does not necessarily mean falls did not occur; only that no falls were investigated.
- Designing the bolt length and spacing such that a more effective compression zone is created.
- Immediately installing supplemental support such as timbers or cribs at pillar edges if severe cutters occur.

A detailed study on the stability differences between bolts installed 2 ft. from the pillar edge and 4 ft. from the edge may yield useful data on possible advantages of

bolting closer to the rib. Simply comparing mines surveyed in this study may not be reliable due to the differences in geology, so a side-by-side comparison at the same mine and geology would make sense.

Weathering also seems to be a major factor as 60% of the unplanned falls occurred more than 3 months after they were developed, and almost 14% happened more than 5 years after the excavation was first developed. Weathering of the roof strata and/or anchor corrosion may be causing the system to fail in these late stages. Therefore, under roof conditions where weathering is considered possible, some form of effective sealing could be considered for critical long term intersections (such as main entries or belt entries). This sealing could be done using shotcrete or a thin support liner for example. Where cutters form close to the pillars (especially near intersections), the situation should be carefully monitored and free standing supports installed to support the dead weight if the cutters tend to grow. Photo 1 displays the onset of a cutter into the roof. Additionally, previous studies have noted that about 70% of roof falls occurred near areas of substantial rib rashing, indicating another warning sign that a fall may occur (Patrick, 1980).



Photo 1: The onset of a cutter into the roof against the pillar rib

There were wide variations in the reporting of unplanned falls of ground across different MSHA districts, with some districts consistently noting features such as bolt type, stand-up time, immediate roof geology, and if water or cutters were present. Other districts chose not to include this important information in their 7000 50a reports. In order to more effectively avoid a recurrence of a similar fall of ground mechanism, the actual mechanism causing the fall needs to be identified and understood. It would be therefore beneficial if the following was recorded routinely for all unplanned (and other) falls of ground:

- Details of the support associated with the actual fall. This is often difficult to identify but estimation would be useful, even if it is based on the installed support in the nearest stable intersection. A standard format across all districts would be easiest to follow.
- The support spacing and bolt installation angle are also important.
- The stand-up time.

- The presence and nature of any water present.
- The time after development when the primary and any secondary/supplemental support was installed.
- Dimensions of the fall.
- More specific details of the immediate roof strata and local geology in the area.

Additional parameters were suggested by W.C. Patrick in 1980 such as the location of the fall relative to crosscuts, the presence of rib rashing and floor heaving, and the apparent presence of extremely high or low stresses.

It would be helpful if the data gathered was standardized within the coal industry and easily available electronically. This fall data could then be analyzed more accurately using ANOVA and regression statistical analysis to identify and quantify factors that impact the dimensions and stand-up time of unplanned roof falls. More consistent reporting across districts may also show the importance of warning signs of falls such as water presence, rib rashing, and cutters. The main constraint to getting this data reliably is probably a shortage of manpower especially at MSHA, considering their more rigorous duties under the 2006 MINER Act.

REFERENCES

- Arch Coal, Inc. "Form 10-K Annual Report, 02/29/2008." EDGAR Online Pro. 28 June 2009 <http://google.brand.edgar-online.com/EFX_dll/EDGARpro.dll?FetchFilingHTML1?ID=5767597&SessionID=BrEtWv7XX3-zPm7>.
- Aughenbaugh, N.B. Personal Communications, September 2009.
- Barczak, T.M. "An Overview of Standing Roof Support Practices and Developments in the United States." Proceedings of the Third South African Rock Engineering Symposium (1995): 301-334.
- Barczak, T.M. "Mistakes, Misconceptions, and Key Points Regarding Secondary Roof Support Systems." Proceedings of the 20th International Conference on Ground Control in Mining (2001): 347-356.
- Barczak, Thomas M. "A Retrospective Assessment of Longwall Roof Support with a Focus on Challenging Accepted Roof Support Concepts and Design Premises." Proceedings: 25th International Conference on Ground Control in Mining (2006): 232-244.
- Bieniawski, Z. T. "Improved Design of Room-And-Pillar Coal Mines for U.S. Conditions." First International Conference on Stability in Underground Mining, Chapter 2 (1983): 19-51.
- Brady, B. Rock Mechanics For Underground Mining. New York: Springer (1985): 211.
- Brown, E., Bray, J., Ladanyi, B. and Hoek, E. "Ground Response Curves for Rock Tunnels." J. Geotech. Eng. 109 (1983): 15-39.

- Chugh, Y.P. and Missavage, R.A. "Effects of Moisture on Strata Control in Coal Mines." AIME Transactions, Volume 270 (1982): 1816-1820.
- Chugh, Y P. MNGE431 – Rock Mechanics: Principles and Design Course Notes (2007): 272-276.
- Chugh, Y. P. Personal Communications, May 2009.
- Dolinar, Dennis R., and Suresh K. Bhatt. "Trends in Roof Bolt Application." NIOSH: Proceedings: New Technology for Coal Mine Roof Support (2000): 43-51.
- Esterhuizen, G.S. Personal Communications, November 2008.
- Energy Information Administration. "Average Weekly Coal Commodity Spot Prices." Coal News and Markets (2009).
- Gadde, Murali, and Syd S. Peng. "Effect of in Situ Stresses on the Stability of Coal Mine Development Workings." Proceedings: 23rd International Conference on Ground Control in Mining (2004): 92-102.
- Gadde, Murali M., Rusnak, John. A., and Mark, Christopher. "An Integrated Approach to Support Design in Underground Coal Mines." Proceedings of the International Workshop on Rock Mass Classification in Underground Mining (2007) 49-56.
- Ganguli, Rajive. "MIN454: Underground Mining Methods, Handout 3." MIN454: Underground Mining Methods, Handout 3. University of Alaska Fairbanks. 28 June 2009 <http://www.faculty.uaf.edu/ffrg/min454/Handout3_UMM.pdf>.
- Hanna, K., Conover, D., Haramy, K. and Kneisley, R. "Structural Stability of Coal Mine Entry Intersections – Case Studies" 27th U.S. Symposium on Rock Mechanics, Chapter 74 (1986): 512-519.

- Hill, John L. "An Investigation of the Causes of Cutter Roof Failure in a Central Pennsylvania Coal Mine: A Case Study." 25th Symposium on Rock Mechanics, Chapter 62 (1984): 603-614.
- Hoek, E. "Model to Demonstrate How Rockbolts Work." Practical Rock Engineering (2007) <http://www.rocscience.com/hoek/PracticalRockEngineering.asp>
- JCMiras.net. "Estimated Capital Cost of Power Generating Plant Technologies." 26 June 2008. 16 June 2009.
- Jeremic, M. Strata Mechanics in Coal Mining. Dallas: Taylor & Francis (1985): 113-116.
- Mark, C, D R. Dolinar, and T M. Mucho. "Summary of Field Measurements of Roof Bolt Performance." NIOSH: Proceedings: New Technology for Coal Mine Roof Support (2000): 81-98.
- Mark, C, and A T. Iannacchione. "Ground Control Issues for Safety Professionals." Mine Health and Safety Management (2001): 347-367.
- Mark C., W. Gale, D. Oyler, J. Chen. "Case history of the Response of a Longwall Entry Subjected to Concentrated Horizontal Stress." Int J Rock Mech Min Sci (2007): 210-221.
- Mark, C, and M. Gadde. "Global Trends in Coal Mine Horizontal Stress Measurements." Proceedings of the 27th International Conference on Ground Control in Mining (2008): 319-331.
- Mine Safety and Health Administration. "Number and Distribution of Mining Fatalities by Work Location and Type of Incident, 2002-2006." Mining Fatalities (2006).

- Molinda, G M., C Mark, E R. Bauer, D R. Babich, and D M. Pappas. "Factors Influencing Intersection Stability in U.S. Coal Mines." Proceedings of the 17th International Conference on Ground Control in Mining (1998): 267-275.
- Molinda, Gregory M., Christopher Mark, and D Debasis. "Using the Coal Mine Roof Rating (CMRR) to Assess Roof Stability in U.S. Coal Mines." J Mines Met Fuels (India) (2001): 314-321.
- Molinda, G.M., C Mark, D.M. Pappas, and T.M. Klemetti. "Overview of Coal Mine Ground Control Issues in the Illinois Basin." Trans Soc Min Metal Explor 324 (2008): 41-48.
- Mucho, Thomas P. "Cable Bolts - a "New Support"" Holmes Safety Association: Bulletin (1998): 3-4.
- Patrick, W.C. and N.B. Aughenbaugh. "Classification of Roof Falls in Coal Mines." AIME Transactions Volume 266 (1980): 279-283.
- Peng, S.S. Ground Control Failures - A Pictorial View of Case Studies, S.S. Peng publisher (2007).
- Ray, Anil and Syd S. Peng. "Influence of Cutting Sequence on Development of Cutters and Roof Falls in Underground Coal Mine." Proceedings of the 28th International Conference on Ground Control in Mining (2009).
- Seegmiller, Ben L. "Specialty Truss Systems and Their Performance." Preceedings: 9th International Conference on Ground Control in Mining (1990): 30-34.
- Spearing, A, Mueller, A. "State of the Art Intersection Support in Coal Mines in the USA." Southern Hemisphere International Rock Mechanics Society Symposium Perth, Australia. Sept. 2008.

- Spearing, A. Personal Communications, March 2009.
- Speers, C. and Spearing, A. "A Methodology for the Design of Tunnel Support in Deep Hard Rock Mines Under Quasi-static Conditions." J. S. Afr.Inst. Min. Metall., Vol. 96, No. 2 (1996): 47–54.
- Su, W.H. and S.S. Peng. "Investigation of the Causes of Roof Falls in a Deep Underground Coal Mine." AIME Transactions Volume 280 (1986): 2019-2023.
- Tang, David H.Y. And Syd S. Peng "Methods of Designing Mechanical Roof Bolting in Horizontally Bedded Strata." 25th Symposium on Rock Mechanics, Chapter 63 (1984): 615-626.
- U.S. Bureau of Labor Statistics. "Fatal Workplace Injuries in 2005: A Collection of Data and Analysis." Publication. October 2007. Bulletin 2593 (2007).
- U.S. Energy Information Administration. "Coal Mining Productivity by State and Mine Type." Publication. September 2008. DOE/EIA-0584(2008).
- U.S. Energy Information Administration. "Annual Coal Report for 2007." Publication. February 2009. DOE/EIA-0584(2009).
- Zhang, Yunqing, and Syd S. Peng. "Intersection Stability and Tensioned Bolting." Proceedings: 22nd International Conference on Ground Control in Mining (2003): 208-217.
- Zhang, P., Mishra, M., and R. Lawrence. "Application of a Polymer-based Sealing Material to Prevent Roof From Weathering." Proceedings of the 28th International Conference on Ground Control in Mining (2009).

APPENDICES

APPENDIX A1: Current intersection support practices by state

Mine ID	Mine	Coal seam	Method	2007 production	Room width (ft)	Room height (ft)	Bolt type	Bolt length (ft)	Resin length (ft)	Bolt spacing (ft)	Active/Passive	Bolt angle
Alabama												
	Coke Mine #1 - Shelby Mining 201 Tucker Rd. Suite 101 Helena, AL 35080 Tel: 205-6644704 Greg Franklin - Safety Coordinator	Coke Seam	Room&Pillar	150,000	21	3.75	3/4" Fully Grouted	6	Full	4	Passive	Vert
	JWR No 4 Mine 14730 Lock 17 Rd Brookwood, AL 35444 Tel: 205-5546450 Bill Marston - MNGE	Blue Creek	Longwall	7,000,000	22	7	7/8" Fully Grouted	4	Full	5	Passive	Vert
	JWR No 7 Mine 18069 Hannah Creek Rd Brookwood, AL 35444 Tel: 205-5546750 Johnny Humphreys - MNGE	Blue Creek	Longwall	6,000,000	21	7	.804" Fully Grouted	6	Full	5	Passive	Vert
	North River #1 - Chevron Mining 12398 New Lexington Rd Barry, AL 35546 Tel: 205-3335041 Jeff Gregs - MNGE	Pratt	Longwall	5,000,000	18	6.67	.677" Combination	6	1.5	4.5	Active	Vert
	Oak Grove Mine 8800 Oak Grove Mine Road Adger, AL 35006 Tel: 205-497-3651 Tim Thompson - Manager of Safety	Blue Creek	Longwall	2,250,000	20	8	3/4" Fully Grouted	4-8ft	Full	4	Passive	Vert
	Shoal Creek Complex PO Box 1549 Jaspar, AL 35501 Tel: 205-4916200 Jay Vilsek - MNGE	May Lee Blue Creek	Longwall	4,000,000	20-22	7-11 ft	3/4" and 5/8" Combination	4 to 8	2	5	Active	Vert

Colorado

	Bowie Resources Ltd.	B Seam	Longwall	5,200,000	19	9.5
	PO Box 1488, Paonia, CO 81428 Tel: 970-5274135 Jim Abshire - MNGE					
O503505	Desarado Mine	?	Longwall	1,424,000	16 to 19	8 to 14
	3607 County Rd 65 Rangely, CO 81648 Tel: 970-6754345					
	King Coal	Menefee	Room&Pillar	550,000	17	6
	4424 CR 120 Espress, CO 81326 970-385-4528 ext. 15 Dan Meadors - Mine Manager					
503836	Twenty Mile Coal Co.	Wadge	Longwall	8,290,117	18-20	8.5-10
	29515 Routt County Rd 27 Oak Creek, CO 80467 Tel: 970-8793800/8702782 Bob Johnson - Tech Safety Coordinator					
O503672	West Elk Mine	B Seam	Longwall	6,500,000	18	10
	PO Box 591 Somerset, CO 81434 Tel: 970-9295015					
Illinois						
	Crown III Mine	#6 Herrin	Room&Pillar	1,511,109	18	7
	4440 Ash Grove, Suite A, Springfield, IL 62711 Tel: 217-6272161 Andy Ditch - MNGE					
1102752	Galatia Mine	#5 #6	Longwall	7,009,000	18 (#5) 20 (#6)	6
	PO Box 727 Harrisburg, IL 62946 Tel: 618-2686444					

3/4"	6 or 8	Full	4.5	Passive	Vert
Fully Grouted					
#7	7	5	4.5	Passive	Vertical Ribs 30-45 deg
#6	5 or 6	Full	5	Passive	Vert
Fully Grouted					
0.804	8	Full	5	Passive	Vert
Fully Grouted					
0.804"	6	Full	5.0	Passive	All vertical
1" Tension Rebar	6, 8	3	4	Active	Vert
#6 & #7	2.5 to 8ft (#6) 8ft (#5)	3	4.0	Active	All vertical

1120408	Gateway Mine 13101 Zeigler 11 Road Coulterville, IL 62237 Tel: 618-7582395	Herrin #6	Room & pillar	4,200,000	20	7	?	4	?	5.0	Active	All vertical
1103147	Prairie Eagle Underground Mine 7290 County Line Road Cutler, Illinois 62238 Tel: 618-4972768	Herrin #6	Room & pillar	597,000	19 to 20	6.5 to 7	#5 Gr75 #6 double lok	30, 36, 48, 60" 6 ft	N/A 2 ft	4.5 4.5	Active Active	All vertical All vertical
	Riola Mine - Vermillion Grove 4500 N 1500E Ridgeform, IL 61870 Tel: 217-2472145 Dick Reisinger - MNGE	Herrin	Room&Pillar	2,300,000	18-19 ft	6-7 ft	Combo or Fully Grouted	8' or 6'	Combo - ? Grouted - full	4.5	Active Passive	Vert
1103162	Royal Falcon Mine 2220 Royal Falcon drive Elkville, Illinois 62932 Tel: 618-9842483	Herrin #6	Room & pillar	0	18	8 to 10	#6	6 to 8	Full	4.0	Active	All vertical
	Viper Mine 8100 E. Main Williamsville, IL 62693 Tel: 217-5663000 Joe Olson - MNGE	Springfield #5	Room&Pillar	2,100,000	20	5.5	#5 Fully Grouted	4,6,8 ft	Full	4	Passive	Vert
1103058	White County Coal - Pattiki 1525 County Rd 1300E Carmi, IL 62821 Tel: 618-3824651	Herrin #6	Room & pillar	4,297,463	18 to 20	5 to 9	0.75" Gr75	3 to 10	2	4.5	Active	All vertical
1103156	Wildcat Hills 115 Grayson Lane El Dorado, IL 62930 Tel: 818-2738606	Herrin #6	Room & pillar	1,713,00	18 to 20	5 to 6.5	0.875" SRD	6	Full	4.5	Active	All vertical
1103054	Willow Lake Portal 420 Long Lane Road	Springfield #5	Room & pillar	6,469,000	18.5 to 20	5.25 to 6.25	#5 Gr60 #6 Gr40	4 to 6	Full	4.5	Passive	All vertical

Equality, Illinois 62934

Tel: 618-2731320

Indiana

Air Quality Mine

#7

Room&Pillar

5,000,000

19

6

PO Box 409

Monroe City,IN47557

Tel: 812-7439292

Steve Mesker - MNGE

Carlisle Mine

Indiana #5

Room&Pillar

1,000,000

18

4.5-8

6641 SR 46

Terre Haute, IN 47802

Tel: 812-3982200 ext 107

Sam Elder - MNGE

Gibson County Coal

Springfield #5

Room & pillar

4,900,000

18

4.5-9

PO Box 1269, 2579 West Gibson Rd

Princeton, IN 47670

Tel: 812-3851816

Chris Hoppie - Chief Engineer

Prosperity Mine (5 Star Mining Inc.)

Indiana #5

Room&Pillar

3,500,000

18

6

6594 W State Rd 56

Petersburg, IN 47567

Tel: 812-3546883

Triad Underground

#5

Room & pillar

1,068,000

18 to 20

4 to 6

14521 E State Road 58

Edwardsport, Indiana 47528

Tel: 812-3282491

Kentucky

Bledsoe Coal Corp.

Hammond #4

Room&Pillar

2,000,000

20

4.16-13 ft

Rt 2008 Box 3514

Big Laurel, KY 40808

Tel: 606-5385506

Adam Smith - MNGE

5/8"	4 ft	Full	4-5 ft	Passive	Vert
Fully Grouted					
5/8"	4.5-6	Full	4.5	Passive	Vert
Fully Grouted					
Resin, mech shell, 5/8-7/8	10	3	4	Passive	Vert
5/8"	5	Full	4	Passive	Vert
Fully Grouted					
#5	4 to 6	Full	4.5 to 5.0	Passive	All vertical
5/8"	4-5 ft	Full	4	Passive	Vert
Fully Grouted					

	C3 Mine - Rex Coal	Creek Seam	Room&Pillar	77,000	20	2.8	5/8" Fully Grouted	4	Full	4	Passive	Vert
	Box 269 Gray's Knob, KY 40829 Tel: 276-5237137 Mike Palmer - MNGE											
	Dodge Hill Mine #1	West Kentucky #6	Room & pillar	2,326,834	20	4.8	#6 Gr40	5 6	5 3	4 4	Passive Active	All vertical
	PO Box 165 Sturgis, KY 42459 Tel: 270-9526761											
1518826	Elk Creek Mine	KY #9	Room & pillar	3,770,000	18 to 20	4.5 to 5.3	#6	5 and 6	Full	4.0	Passive	All vertical
	35 Frank Cox Rd Madisonville, KY 42431 Tel: 270-3264007	KY #11			18 to 20	5 to 6	#6	6	Full	4.0	Passive	All vertical
	Flint Ridge Mine	#8 Haddix	Room&Pillar	800,000	20	6	5/8" Fully Grouted	4	Full	4	Passive	Vert
	Breathitt County, KY Tel: 606-6666802 Everett Kelly - Safety director											
1502709	Highland Mine	Kentucky #9	Room & pillar	6,572,000	20	5.5	#6	6	Full	4.0	Passive	All vertical
	530 French Road Waverly, Kentucky 42462 Tel:											
	Jones Fork Complex	Elk 1-3	Room&Pillar	1,422,398	20	4-6ft	#5 Fully Grouted	5	5	4	Passive	Vert
	550 184 Fourmile Branch Mousie, KY 41839 Tel: 606-9463100 John Hell - MNGE											
	Manalapan Mining Co. RB-P1 Mine	Path Fork	Room&Pillar	200,000	20	3.5	3/4" Fully Grouted	4	Full	4	Passive	Vert
	8174 E Highway 72 Pathfork, KY 40863 Tel: 606-5732020 ext 31 Dennis Wilson - Engr tech											
	Martin County Coal Corp	Coalburg	Room&Pillar	0	20	5.5-6	not sure Fully grouted	4-5 ft	Full	4	Passive	Vert
	PO Box 5002,											

Inez, KY 41224
 Tel: 606-3956881
 Philip Meade - MNGE

McCoy Elkhorn Complex Fireclay Room&Pillar 5,000,000 19-22 4.5
 1148 Long Fork Rd.,
 Kimper, KY 41539
 Tel: 616-835-2233 ext 21
 Robert Maynard - MNGE

Mine 77 Blue Diamond Elk Horn #3 Room&Pillar 600,000 19 5-6 ft
 P.O. Box 47
 Slemp, KY
 Tel: 606-6753311
 Craig Travis - MNGE

Pontiki/Excel Pond Creek Room & pillar 2,000,000 19 6
 HC 67, Box 615
 Pilgrim, KY 41250
 Tel: 606-395-5348
 David Arington - MNGE

Premier Elkhorn P-1 Elk Horn 3 Room&Pillar 240,000 20 4.3
 PO Box 130
 Myra, KY 41549
 Tel: 606-6399623
 Sid Stanley - Chief Engineer

Sidney Coal Co. Inc. - Freedom mine Pond Creek Room&Pillar 3,000,000 20 5-8 ft
 PO Box 299
 Sidney, KY 41564
 Tel: 606-3535509
 John Cline - Chief Engineer

1502132 **Webster County Coal - Dotiki** Kentucky #9 Room & pillar 6,400,000 20 5.17
 1586 Balls Hill Rd
 Nebo, KY 42441
 Tel: 270-249-2205
 Eric Blanford - Engr Manager

3/4" Fully Grouted	5	Full	4	Passive	Vert
3/4" Fully Grouted	6	Full	4	Passive	Vert
Mostly 3/4" Also use 5/8, 7/8	6	Full	4	Passive	All Vertical
Torque Tension	4	not sure	4	Active	Vert
5/8" Fully Grouted	5	Full	4	Passive	Vert
#6 Gr40	5	Full	5' width 4' advance	Passive	All vertical

New Mexico

San Juan Mine Fruitland #8 Longwall 7,000,000 18 9-9.5
 PO Box 561
 Waterflow, NM 87421
 Tel: 505-5982000
 Steve Jones - MNGE

Ohio

Powhatan #6 Pittsburgh #8 Longwall 5,000,000 18 6
 56864 Pleasant Ridge Road
 Alledonia, OH 43902
 Tel: 740-9261351
 Dick Homco - Safety Coordinator

Pennsylvania

Bailey Mine Pittsburgh #8 Longwall 9,827,946 15.5 7.75
 192 Crabapple Rd
 Wind Ridge, PA 15377
 Tel: 724-4281200
 Rob Robinson - MNGE

Clementine Mine Lower Kittanning Room & pillar 1,200,000 17 to 20 3.5 to 4.5
 151 Clinton Road
 Freeport, PA 16229
 Tel:

Enlow Fork Pittsburgh #8 Longwall 11,200,000 15.6 8
 Rte 231
 East Finley (Washington Co), PA
 Tel: 724-6633102
 Paul Kelly - MNGE

3600958 **Mine No. 84** Pittsburgh Longwall 3,606,000 16 6.5 to 8
 PO Box 284
 Eighty Four, PA 15330
 Tel: 724-2501500/1577

Utah

Bear Canyon #4 Tank Seam Longwall 2,000,000 18-19 ft 6-7 ft

1"	7	Full	4	Passive	Vert
Fully Grouted					
5/8"	8	2	4	Active	Vert
Combination					
Genmar	12	2	4	Active	Vert
"Install 2"					
Resin assist combo					
#6	3.5	Full	3.5	Passive	All vertical
Genmar	8	2	4	Active	Vert
Point Anchor					
#7 mech shell	8	2	3.0 to 4.0	Active	All vertical
3/4"	5-6 ft	Full	5	Passive	Vert

PO Box 300
 Huntington, UT 84528
 Tel: 435-6875777
 Miles Stevens - MNGE

Deer Creek Mine Hiawatha Longwall 3,500,000 20 8.5
 PO Box 310 Blind Canyon
 Huntington, UT 84528
 Tel: 435-6876626
 Larry Lafrent - MNGE

Dugout Canyon Gilson Longwall 3,800,000 20 8.5
 PO Box 1029
 Wellington, UT 84542
 Tel: 435-6376360
 David Spillman - Tech. Services Manager

Emery Mine I Seam Room&Pillar 1,200,000 20 7
 PO Box 527
 Emery, UT 84522
 Tel: 435-2862301
 Russel Hardy - MNGE

Skyline Complex Lower O'Connor A Longwall 2,560,000 20 9
 North Lease Mine
 PO Box 380
 Helper, UT 84526
 Tel: 435-6377925

Sufco Mine Hiawatha Longwall 7,000,000 18-20 9.5
 397 South 800 West
 Salina, UT 84654
 Tel: 435-2864880
 John Byers - MNGE

Westridge Mine Lower Sunny Side Longwall 2,500,000 18 7
 PO Box 910
 East Carbon, Utah 84520
 Tel: 435-8884000

Fully Grouted					
.914" gr 75	5	Full	5	Passive	Vert
Fully Grouted					
#7	6	Full	5	Passive	Vert
Fully Grouted					
5/8"	5	Full	5	Passive	Vert
Fully Grouted					
0.875" SRD	8	Full	5.0	Passive	All vertical
3/4"	5	Full	5	Passive	Vert
Fully Grouted					
3/4"	5	Full	5	Passive	45deg at rib
Fully Grouted					

Jay Marshall - MNGE

Virginia

Cumberland River F Seam, D Seam Room&Pillar 7,264,244 20 5-10 ft
 Pardee Complex Parson Seam
 PO Box 109
 Appalachia, VA 24216
 Tel: 606-6339474
 Willie Adams - MNGE

Knox Creek Coal Corp (Tiller 1) Tiller Room&Pillar 270,000 19.5 3.33
 PO Box 519
 Raven, VA 24639
 Tel: 276-9644333
 Eric - MNGE

Lone Mountain Processing Inc. Kellioka Room&Pillar 1,186,166 19 6
 Drawer C Darby
 St. Charles, VA 24282 Owl
 Tel: 606-8372299 ext 21
 James Sumner - MNGE

West Virginia

Bridger Coal Co. D-41 Longwall 2,700,000 17.5 10
 PO Box 68,
 Point of Rocks, WY 82942
 Tel: 307-3829741 (603)
 Tom Hurst - MNGE

Coal-Mac Inc, Mountaineer Mine Alma A Room & pillar 900,000 19.5 5.5
 Ragland Complex
 PO Box 1050
 Holden, WV 25625
 Tel: 304-6644000
 Brian Damron - MNGE

Independence (Justice Mine) Powellton Longwall 2,000,000 19 7
 PO Box 1800
 Madison, WV 25130

5/8"	4	Full	4	Passive	Vert
Fully Grouted					
3/4"	5	4	4	Active	Vert
Combination					
3/4"	8	not sure	4	Active	Vert
Combination bolt					
.972"	8, 12	3	5	Active	Vert
Combination					
Fully Grouted	4	Full	4	Passive	Vert
3/4"					
3/4"	4-6 ft	Full	4-5 ft	Passive	Vert
Fully grouted					
sometimes Torque Tension					

Tel: 304-3697103
 Andy Ashurst - MNGE

Kingston No 1 Glen Alum Room & pillar 2,700,000 19.5 4.5
 PO Box 76-C
 Scarbro, WV 25917
 Tel: ????????

Loveridge Mine Pittsburgh #8 Longwall 8,250,000 15.5 8
 County Road M, 2 miles N of Fairview
 Fairview, WV 26570
 Tel: 304-6621229
 Mark Cramer - MNGE

McElroy Mine Pittsburgh #8 Longwall 9,667,258 15.8 7.5
 Rd 1 (Marshall Co),
 Glen Easton, WV 26039
 Tel: 304-8433700
 Eric Shereda - MNGE

Miller Creek Complex Coalberg Room&Pillar 700,000 20 7
 1 Stella Deskins Drive
 Williamson, WV 25661
 Tel: 304-2351850 ext 11
 Duffy Farrell - MNGE

Mountaineer 2 Mine Thalma Longwall 4,100,000 19-19.5 ft 5-14 ft
 Box 100, State Route 17,
 Sharples, WV 25183
 Tel: 304-3697518
 Rob Brawner - MNGE

Performance (Upper Big Branch) Eagle Room&Pillar 650,000 19.9 5.5-10ft
 PO Box 457,
 Whitesville, WV 25209
 Tel: 304-8541761
 George Leao - MNGE

Pinnacle Mine Pocahontas #3 Longwall 2,000,000 20 6.5
 Pinnacle Creek Road
 PO Box 338

#5	3.5	Full	4.0	Passive	All vertical
Combination	8	1.5	5	Passive	Vert
Fully grouted Mech. Anchor	6	Full	4	Active	Vert
3/4" Fully Grouted	6	Full	4	Passive	Vert
5/8" Combination	5	Full	4	Active	Vert
5/8" Combination	6	not sure	5 ft	Active	Vert
3/4" Combination Genmar	5 or 6	not sure	4	Active	Vert

Pineville, WV 24874
 Tel:304-7325337
 David Trade - MNGE

Rockspring Mine	Winterford	Room&Pillar	7,000,000	20	8
PO Box 390					
East Lynn, WV 25512					
Tel: 304-720-2531					
George Smith - Senior Engineer					

Shoemaker Mine	Pittsburgh #8	Longwall	100,000	16	7.67
PO Box 62A (Ohio Co)					
Dallas, WV 26036					
Tel: 304-2381500					
Barry Miller - MNGE					

TOTAL PRODUCTION: **234,605,535**

Install 2					
3/4" Combination	6	2	4	Active	Vert
7/8" Fully Grouted	6	Full	4	Passive	Vert

APPENDIX A2: Current intersection support practices by state

Mine ID	Mine	Plate detail	Plate type	First bolt from rib	Wire Mesh	Channel Type	Size	Thickness	Cables Length (ft)	Diameter (in)	Resin lgth (ft)	Trusses L/Dia	Angle
Alabama													
	Coke Mine #1 - Shelby Mining 201 Tucker Rd. Suite 101 Helena, AL 35080 Tel: 205-6644704 Greg Franklin - Safety Coordinator	6x16"	Flat	3	Not used	Rarely Used	N/A	N/A	Nil			Nil	
	JWR No 4 Mine 14730 Lock 17 Rd Brookwood, AL 35444 Tel: 205-5546450 Bill Marston - MNGE	6x6"	Flat	4	If needed	Nil	N/A	N/A	8	1"	not sure	Nil	
	JWR No 7 Mine 18069 Hannah Creek Rd Brookwood, AL 35444 Tel: 205-5546750 Johnny Humphreys - MNGE	6x6"	Volcano	3-4 ft	no	Thin flat metal strips			8	0.6	6	Nil	
	North River #1 - Chevron Mining 12398 New Lexington Rd Barry, AL 35546 Tel: 205-3335041 Jeff Gregs - MNGE	8x8?	Flat	3	Not used	Nil	N/A	N/A	12	0.7	5	Nil	
	Oak Grove Mine 8800 Oak Grove Mine Road Adger, AL 35006 Tel: 205-497-3651 Tim Thompson - Manager of Safety	6x6"	Donut	<5 ft	Nil	Not used often			Used very rarely			Nil	
	Shoal Creek Complex PO Box 1549 Jaspar, AL 35501 Tel: 205-4916200 Jay Vilsek - MNGE	6x6"	Donut	5	Not used	Nil	N/A	N/A	Nil			Nil	

Colorado														
	Bowie Resources Ltd. PO Box 1488, Paonia, CO 81428 Tel: 970-5274135 Jim Abshire - MNGE	6x6"	Domed	2	4x4" Mesh	Monster Mat	not sure	not sure	8-12 ft	0.75	not sure	Nil		
O503505	Desarado Mine 3607 County Rd 65 Rangely, CO 81648 Tel: 970-6754345	6x6" Gr3	Domed	2 ft	Mesh/screen 14 gauge	Nil	N/A	N/A	10 12 per intersection	0.6	7.0	Nil		
	King Coal 4424 CR 120 Espress, CO 81326 970-385-4528 ext. 15 Dan Meadors - Mine Manager	6x6"	Flat	1.5	Used everywhere	Nil	N/A	N/A	Nil			Nil		
503836	Twenty Mile Coal Co. 29515 Routt County Rd 27 Oak Creek, CO 80467 Tel: 970-8793800/8702782 Bob Johnson - Tech Safety Coordinator	6x6" 3/8"	Volcano	2	Everywhere	Bacon strip	12x18"	not sure	8-12 ft	.6-.7	4 ft	Nil		
O503672	West Elk Mine PO Box 591 Somerset, CO 81434 Tel: 970-9295015	4x4"	Domed	2 ft	Mesh/screen 9 gauge	Nil	N/A	N/A	12		3.0	8ft #8 ?	45 deg	
	Illinois													
	Crown III Mine 4440 Ash Grove, Suite A, Springfield, IL 62711 Tel: 217-6272161 Andy Ditch - MNGE	6x16"	Dome	<4 ft	Not used	Nil	N/A	N/A	Nil			Nil		
1102752	Galatia Mine PO Box 727 Harrisburg, IL 62946 Tel: 618-2686444	8x8" Gr40	Flat	3 ft	Nil	Nil	N/A	N/A	12	0.6	3.0	8ft #7 0.6" cable	45 deg	

1120408	Gateway Mine 13101 Zeigler 11 Road Coulterville, IL 62237 Tel: 618-7582395	8x8" 6x16" 6x20"wood	Domed Flat Flat	2.5 ft	Nil	Nil	N/A	N/A	Nil	N/A	N/A	Nil		
1103147	Prairie Eagle Underground Mine 7290 County Line Road Cutler, Illinois 62238 Tel: 618-4972768	8x8" Gr2 8x8" Gr2	Dimple Flat	4 ft 4ft	Mesh/screen 8 gauge	Nil			Nil			Nil		Nil
	Riola Mine - Vermillion Grove 4500 N 1500E Ridgeform, IL 61870 Tel: 217-2472145 Dick Reisinger - MNGE	8x8"	Flat or Donut	<3.5	In about 25% Area	Metal	10"x16'		12-15 ft	Not sure	Not sure	Nil		
1103162	Royal Falcon Mine 2220 Royal Falcon drive Elkville, Illinois 62932 Tel: 618-9842483	8x8" Gr2	Dimple	3 ft	Nil	Roof matt		14 gauge	Nil				8ft #7	45 deg
	Viper Mine 8100 E. Main Williamsville, IL 62693 Tel: 217-5663000 Joe Olson - MNGE	6x6" 16ga	Flat	2	Mains, Beltway	Nil	N/A	N/A	12	0.6	12	Varied L .6"		45
1103058	White County Coal - Pattiki 1525 County Rd 1300E Carmi, IL 62821 Tel: 618-3824651	6x6" Gr 2&3	Domed	2 to 4 ft	2x6x12" boards	Nil	N/A	N/A	Nil	N/A	N/A	Nil		
1103156	Wildcat Hills 115 Grayson Lane El Dorado, IL 62930 Tel: 818-2738606	8x8" Gr2	Donut	2.5 ft	Mesh/screen 8 gauge	Nil	N/A	N/A	10	0.6	50"	Nil		
									4 per insecton					

1103054	Willow Lake Portal 420 Long Lane Road Equality, Illinois 62934 Tel: 618-2731320	8x8" Gr2	Domed	2 to 2.5 ft	Nil	Nil	N/A	N/A	12 & 16	0.6	4 ft	Nil
Indiana												
	Air Quality Mine PO Box 409 Monroe City, IN47557 Tel: 812-7439292 Steve Mesker - MNGE	6x16"	not sure	2.5 ft	In entries	Nil	N/A	N/A	Nil			Nil
	Carlisle Mine 6641 SR 46 Terre Haute, IN 47802 Tel: 812-3982200 ext 107 Sam Elder - MNGE	6x6"	not sure	4	in entries	Nil	N/A	N/A	Nil			Nil
	Gibson County Coal PO Box 1269, 2579 West Gibson Rd Princeton, IN 47670 Tel: 812-3851816 Chris Hopple - Chief Engineer	8x8"	Flat	<3ft	Welded wire in some areas	Nil	N/A	N/A	8	0.6	4	Nil
	Prosperity Mine (5 Star Mining Inc.) 6594 W State Rd 56 Petersburg, IN 47567 Tel: 812-3546883	6x16"	Donut	3.5 ft	No, pizza pan	Nil	N/A	N/A	12	0.8	not sure	Nil
	Triad Underground 14521 E State Road 58 Edwardsport, Indiana 47528 Tel: 812-3282491	6x6" Gr2	Donut	2 to 4ft	Nil	Nil			Nil			Nil
Kentucky												
	Bledsoe Coal Corp. Rt 2008 Box 3514 Big Laurel, KY 40808 Tel: 606-5385506 Adam Smith - MNGE	6x6"	Donut	4	Track, Belt line	Bacon strips			10 and 12	5/8" and 3/4"	4	Nil

	C3 Mine - Rex Coal Box 269 Gray's Knob, KY 40829 Tel: 276-5237137 Mike Palmer - MNGE	6x6"	Flat	4	Not used	Nil	N/A	N/A	Not used	Nil		
	Dodge Hill Mine #1 PO Box 165 Sturgis, KY 42459 Tel: 270-9526761	6x6" Gr2	Domed	2 ft	1x6x16" pinboards	Nil	N/A	N/A	10 8 per intersection	0.6	4.0	Nil
1518826	Elk Creek Mine 35 Frank Cox Rd Madisonville, KY 42431 Tel: 270-3264007	6x6" Gr2	Domed	3.0 to 3.5	Nil	Nil	N/A	N/A	8	0.6	6.0	Nil
		6x6 Gr2	Domed	3.0 to 3.5	Nil	Nil	N/A	N/A	8	0.6	6.0	Nil
									around slips			
	Flint Ridge Mine Breathitt County, KY Tel: 606-6666802 Everett Kelly - Safety director	6x6" or 6x16"	Flat	4	Not used	Used rarely			8 or 10 ft	5/8"	4 or 5 ft	Nil
1502709	Highland Mine 530 French Road Waverly, Kentucky 42462 Tel:	5x5" Gr?	Domed	2.5	Nil	Nil	N/A	N/A	10	0.6	3.0	Nil
	Jones Fork Complex 550 184 Fourmile Branch Mousie, KY 41839 Tel: 606-9463100 John Hell - MNGE	4x4"	Bearing Plate	4	In mains	Nil	N/A	N/A	10	not sure	not sure	Nil
	Manalapan Mining Co. RB-P1 Mine 8174 E Highway 72 Pathfork, KY 40863 Tel: 606-5732020 ext 31 Dennis Wilson - Engr tech	6x6"	Donut	3	Not used	Channel Straps		6"	Not used			Nil
	Martin County Coal Corp PO Box 5002,	6x6"	not sure	2 ft	Not used	Nil	N/A	N/A	Used very rarely as supplemental			Nil

Inez, KY 41224
 Tel: 606-3956881
 Philip Meade - MNGE

McCoy Elkhorn Complex
 1148 Long Fork Rd.,
 Kimper, KY 41539
 Tel: 616-835-2233 ext 21
 Robert Maynard - MNGE

Mine 77 Blue Diamond
 P.O. Box 47
 Slemp, KY
 Tel: 606-6753311
 Craig Travis - MNGE

Pontiki/Excel
 HC 67, Box 615
 Pilgrim, KY 41250
 Tel: 606-395-5348
 David Arington - MNGE

Premier Elkhorn P-1
 PO Box 130
 Myra, KY 41549
 Tel: 606-6399623
 Sid Stanley - Chief Engineer

Sidney Coal Co. Inc. - Freedom mine
 PO Box 299
 Sidney, KY 41564
 Tel: 606-3535509
 John Cline - Chief Engineer

1502132 **Webster County Coal - Dotiki**
 1586 Balls Hill Rd
 Nebo, KY 42441
 Tel: 270-249-2205
 Eric Blanford - Engr Manager

6x6" or 8x8"	Not sure	4	No	Nil	N/A	N/A	10	0.75	not sure	Nil
6x6"	Flat	4	Not used	Nil	N/A	N/A	10	3/4"	Not sure	Nil
8x8"	Donut	4 ft	Nil	Nil	N/A	N/A	10	0.75	N/A	Nil
8x8"	Flat	3	Not used	Nil	N/A	N/A	4	3/4"	not sure	Nil
8x8"	Donut	<2 ft	Not used	Bacon Strip	occasionally		6-10 ft	5/8"	not sure	Nil
8x8"	Donut	3-4 ft	Nil	Nil	N/A	N/A	10 & 12	0.6	5 ft	5-6' 1.5"

New Mexico													
	San Juan Mine PO Box 561 Waterflow, NM 87421 Tel: 505-5982000 Steve Jones - MNGE	8x8"	Flat	2	Everywhere	Nil	N/A	N/A	Nil				10ft 3/4"
Ohio													
	Powhatan #6 56864 Pleasant Ridge Road Alledonia, OH 43902 Tel: 740-9261351 Dick Homco - Safety Coordinator	6x6"	Flat	4	Occasional	Metal		14ga	12	not sure	not sure		Nil
Pennsylvania													
	Bailey Mine 192 Crabapple Rd Wind Ridge, PA 15377 Tel: 724-4281200 Rob Robinson - MNGE	6x6"	Waffle plate	<4 ft	Nil	T5	14'	T5	12-16ft	0.7	4		Nil
	Clementine Mine 151 Clinton Road Freeport, PA 16229 Tel:	6x6" Gr4	Donut	2.5 to 4.0	Nil	J Channel T-5 channel		0.25"	8 to 12	?	4.0		Nil
	Enlow Fork Rte 231 East Finley (Washington Co), PA Tel: 724-6633102 Paul Kelly - MNGE	5x7 3/8"	Channel	3.3 ft	Nil	Genmar T5	Not sure	T5	16	0.7	4.5		Nil
3600958	Mine No. 84 PO Box 284 Eighty Four, PA 15330 Tel: 724-2501500/1577	4x4" 6x6"	Embossed Flat	3.5 ft	Nil	T5 or T3	14ftx6"	?	8 to 20 8 per intersection	0.6 and 0.7	4.0		Nil
Utah													
	Bear Canyon #4	6x6"	Donut	3	on Gate roads	Nil	N/A	N/A	8	3/4"	2		Nil

PO Box 300
 Huntington, UT 84528
 Tel: 435-6875777
 Miles Stevens - MNGE

Deer Creek Mine
 PO Box 310
 Huntington, UT 84528
 Tel: 435-6876626
 Larry Lafrent - MNGE

Dugout Canyon
 PO Box 1029
 Wellington, UT 84542
 Tel: 435-6376360
 David Spillman - Tech. Services Manager

Emery Mine
 PO Box 527
 Emery, UT 84522
 Tel: 435-2862301
 Russel Hardy - MNGE

Skyline Complex
 North Lease Mine
 PO Box 380
 Helper, UT 84526
 Tel: 435-6377925

Sufco Mine
 397 South 800 West
 Salina, UT 84654
 Tel: 435-2864880
 John Byers - MNGE

Westridge Mine
 PO Box 910
 East Carbon, Utah 84520
 Tel: 435-8884000
 Jay Marshall - MNGE

6x6"	Flat gr4	<5 ft	Everywhere 6 ga 4x4"	Mats	10x16ft	14ga	7-16 ft	0.6	5' or 7'	Nil
6x6"	Not sure	<2.5 ft	Wire mesh in all development	Nil	N/A	N/A	10	no sure	6	Nil
6x6"	Domed	3	No	Nil	N/A	N/A	10	5/8"	not sure	Nil
6x6" Gr5/16	Domed	2.5 ft	Mesh/screen 10 gauge	W	16'x12"	3/16"	10	0.6	5.0	Nil
not sure	not sure	<1 ft	As needed	Nil	N/A	N/A	10-12ft	Varied	Not sure	Nil
6x6"	Flat	Angled in ribline	Rarely used	Nil	N/A	N/A	Nil			Nil

Virginia

Cumberland River

Pardee Complex
 PO Box 109
 Appalachia, VA 24216
 Tel: 606-6339474
 Willie Adams - MNGE

6x6" Flat 3.3 Not used

Nil N/A N/A

Nil

Nil

Knox Creek Coal Corp (Tiller 1)

PO Box 519
 Raven, VA 24639
 Tel: 276-9644333
 Eric - MNGE

3x3" and 4.5 x 4.5" Pizza Pans 3 Not used

Nil N/A N/A

6 3/4" 4

Nil

Lone Mountain Processing Inc.

Drawer C
 St. Charles, VA 24282
 Tel: 606-8372299 ext 21
 James Sumner - MNGE

6x6" Flat 3 ft Not often

Nil N/A N/A

8, 12 ft 0.75 not sure

Nil

West Virginia

Bridger Coal Co.

PO Box 68,
 Point of Rocks, WY 82942
 Tel: 307-3829741 (603)
 Tom Hurst - MNGE

6x6" Volcano 2.5 Everywhere

Pans

Nil

8' 45 deg

Coal-Mac Inc, Mountaineer Mine

Ragland Complex
 PO Box 1050
 Holden, WV 25625
 Tel: 304-6644000
 Brian Damron - MNGE

6x6" Flat 4 ft Nil

Used if in bad top
 no specifics available

Used where needed, not sure on dimensions

Independence (Justice Mine)

PO Box 1800
 Madison, WV 25130
 Tel: 304-3697103

8x8" Tension - flat 4 Very rarely
 Resin - Donut

Nil N/A N/A

8-12 ft .6 or .7 not sure

Nil

Andy Ashurst - MNGE

Kingston No 1

PO Box 76-C
 Scarbro, WV 25917
 Tel: ???????

6x6" Gr ? Donot 3.5 ft Nil Nil N/A N/A Nil N/A N/A Nil

Loveridge Mine

County Road M, 2 miles N of Fairview
 Fairview, WV 26570
 Tel: 304-6621229
 Mark Cramer - MNGE

6x6" Flat 3.5 Belt line and track not sure 12' not sure 12 not sure not sure Nil

McElroy Mine

Rd 1 (Marshall Co),
 Glen Easton, WV 26039
 Tel: 304-8433700
 Eric Shereda - MNGE

6x4" Channel 4 In mains T4 Not sure T4 12 0.7 4 Nil

Miller Creek Complex

1 Stella Deskins Drive
 Williamson, WV 25661
 Tel: 304-2351850 ext 11
 Duffy Farrell - MNGE

6x6" Flat <4 ft Not used Pizza Pans 10 3/4" not sure Nil

Mountaineer 2 Mine

Box 100, State Route 17,
 Sharples, WV 25183
 Tel: 304-3697518
 Rob Brawner - MNGE

6x6" not sure 4 Not used Thin Metal 8, 12 1" 4 Nil

Performance (Upper Big Branch)

PO Box 457,
 Whitesville, WV 25209
 Tel: 304-8541761
 George Leao - MNGE

8x8" Donut <4 ft No 8 ga 4' not sure 10-12ft 0.6 not sure Nil

Pinnacle Mine

Pinnacle Creek Road

6x6" Donut 3 Very rarely T5 16' T5 9 3/4" 3 Nil

PO Box 338
 Pineville, WV 24874
 Tel:304-7325337
 David Trade - MNGE

Rockspring Mine

PO Box 390
 East Lynn, WV 25512
 Tel: 304-720-2531
 George Smith - Senior Engineer

Shoemaker Mine

PO Box 62A (Ohio Co)
 Dallas, WV 26036
 Tel: 304-2381500

8x8"	Donut	3.5	Not used
6x6"	Not sure	3.5	Belt line entry

Nil N/A N/A
 Nil N/A N/A

12	.9"	not sure
12 and 16'	0.7	4

Nil
 Nil

APPENDIX A3: Current intersection support practices by state

Mine ID	Mine	Free standing support			Immediate roof geology			Typical time to install secondary
		Type	Spacing (ft)	Comments	From roof			
Alabama	Coke Mine #1 - Shelby Mining 201 Tucker Rd. Suite 101 Helena, AL 35080 Tel: 205-6644704 Greg Franklin - Safety Coordinator	Timbers, Cribs, Steel Jacks	5	As needed	4-8 ft Shale	Massive Sandstone		As needed
	JWR No 4 Mine 14730 Lock 17 Rd Brookwood, AL 35444 Tel: 205-5546450 Bill Marston - MNGE	Cribs, Timbers, Pumpable 6,8,10" Props	5		200 ft Massive sandstone			Soon after mining
	JWR No 7 Mine 18069 Hannah Creek Rd Brookwood, AL 35444 Tel: 205-5546750 Johnny Humphreys - MNGE	4, 9 point cribs Propsetters, 6x6 timbers	5' edge to edge	As needed	3-5 ft Sandy shale	1.5 ft Coal	Sandstone	As needed
	North River #1 - Chevron Mining 12398 New Lexington Rd Barry, AL 35546 Tel: 205-3335041 Jeff Gregs - MNGE	Heinzman Props	5		20 ft Shale	Sandstone		Varies
	Oak Grove Mine 8800 Oak Grove Mine Road Adger, AL 35006 Tel: 205-497-3651 Tim Thompson - Manager of Safety	8" Posts or 4' cribs	5	As needed	1 ft Shale	2-8 ft Sandy Shale	3-4 ft Coal	Varies
	Shoal Creek Complex PO Box 1549 Jaspar, AL 35501 Tel: 205-4916200	Pumpable Cribs	10-20 ft	Always in tailgate	10 ft Sandy Shale	20 ft Sandstone		Varies

Jay Vilsek - MNGE

Colorado

Bowie Resources Ltd.
 PO Box 1488,
 Paonia, CO 81428
 Tel: 970-5274135
 Jim Abshire - MNGE

Can crib 13' center Always installed

3-4 ft 1-6 ft
 Siltstone Sandstone

Soon after mining

O503505

Desarado Mine
 3607 County Rd 65
 Rangely, CO 81648
 Tel: 970-6754345

Nil

10ft
 mudstone/shale

?

King Coal
 4424 CR 120
 Espress, CO 81326
 970-385-4528 ext. 15
 Dan Meadors - Mine Manager

Timbers, Cribs, As needed As needed
 Heinzman Jacks

0-3 ft 20 ft
 Shale Sandstone

Varies

503836

Twenty Mile Coal Co.
 29515 Routt County Rd 27
 Oak Creek, CO 80467
 Tel: 970-8793800/8702782
 Bob Johnson - Tech Safety Coordinator

Timbers, Cribs Varies Always in some areas
 Propsetters, Cans also supplemental

3 ft 2-5 ft
 Laminated Shale Sandstone Shale

Soon after mining

O503672

West Elk Mine
 PO Box 591
 Somerset, CO 81434
 Tel: 970-9295015

Cans 7

1 to 3 ft 3 to 10 ft
 mudstone laminated sandstone

45 days

Illinois

Crown III Mine
 4440 Ash Grove, Suite A,
 Springfield, IL 62711
 Tel: 217-6272161
 Andy Ditch - MNGE

Props, Cribs As needed As needed

Varied Sandstone
 Shale

As needed

1102752

Galatia Mine

Cribs 6 FSS during longwall retreat

40 to 50 ft

?

	PO Box 727 Harrisburg, IL 62946 Tel: 618-2686444	Props Timbers	6 6		shale (#5) 0 to 4 ft shale (#6)	0 to 7 ft limestone	2 to 5 ft shale	30 to 40 ft sandstone	
1120408	Gateway Mine 13101 Zeigler 11 Road Coulterville, IL 62237 Tel: 618-7582395	8" Timber	5		1 to 2 ft shale	4 to 8 ft limestone	6 ft shale	12 ft shale	?
1103147	Prairie Eagle Underground Mine 7290 County Line Road Cutler, Illinois 62238 Tel: 618-4972768	Nil			2 to 4 ft black shale	5 to 9 ft brereton lime	> 50 ft shaley limestone		?
	Riola Mine - Vermillion Grove 4500 N 1500E Ridgeform, IL 61870 Tel: 217-2472145 Dick Reisinger - MNNGE	8x8" Timbers, Propesetters	4.5	As needed	Varied Shale	Varied Sandstone			As needed
1103162	Royal Falcon Mine 2220 Royal Falcon drive Elkville, Illinois 62932 Tel: 618-9842483	Nil			1 ft coal	4 to 6 ft gray black shale	>60 ft sandstone		0 to 5 days
	Viper Mine 8100 E. Main Williamsville, IL 62693 Tel: 217-5663000 Joe Olson - MNNGE	Wood props	5	As needed	0-5 ft Shale	2-4 ft Limestone			As needed
1103058	White County Coal - Pattiki 1525 County Rd 1300E Carmi, IL 62821 Tel: 618-3824651	Cribs	1 in each center	Cross cuts only	1 to 3 ft shale	2 to 5 ft limestone	10 to 60 ft sandstone		7 to 14 days
1103156	Wildcat Hills 115 Grayson Lane El Dorado, IL 62930	Cribs Timbers	6	As needed Where limestone absent in mains	2 to 10 ft shale	2 to 6 ft sandy shale	3 to 6 ft laminated shale	18 to 20 ft sandstone	In cycle

Tel: 818-2738606

1103054 **Willow Lake Portal**
 420 Long Lane Road
 Equality, Illinois 62934
 Tel: 618-2731320

Cribs/timbers/propsetters

4.5 ft

2 ft
 Dykersburg gray shale

3 to 6 ft
 Turner black shale

10 to 50 ft
 sandy shale

about 7 days

Indiana

Air Quality Mine
 PO Box 409
 Monroe City, IN47557
 Tel: 812-7439292
 Steve Mesker - MNGE

Cribs, Timbers

Varies, 5' max

As needed

0-15 ft
 Shale

Varied
 Sandstone

As needed

Carlisle Mine
 6641 SR 46
 Terre Haute, IN 47802
 Tel: 812-3982200 ext 107
 Sam Elder - MNGE

Timbers, cribs

As needed

As needed

2-3 ft
 Shale

1-3 ft
 Limestone

Shale

As needed

Gibson County Coal
 PO Box 1269, 2579 West Gibson Rd
 Princeton, IN 47670
 Tel: 812-3851816
 Chris Hopple - Chief Engineer

Propsetters, timbers
 strata props

As needed
 Usually 6-10

As needed

5-20 ft
 Shale

Sandstone

Varies, as needed

Prosperity Mine (5 Star Mining Inc.)
 6594 W State Rd 56
 Petersburg, IN 47567
 Tel: 812-3546883

Timbers, cribs, props

Varies
 usually 12' center

Always in main travelway
 as needed elsewhere

6-10 ft
 Shale

Sandstone or
 Limestone

1 month

Triad Underground
 14521 E State Road 58
 Edwardsport, Indiana 47528
 Tel: 812-3282491

Cribs
 Timbers

4
 4

12ft
 gray shale

3ft
 limestone

3 to 6 ft
 black shale

As needed

Kentucky

Bledsoe Coal Corp.
 Rt 2008 Box 3514

Timbers, Cribs

4

As needed

0-10 ft
 Sandy Shale

Sandstone

As needed

Big Laurel, KY 40808
 Tel: 606-5385506
 Adam Smith - MNGE

C3 Mine - Rex Coal

Box 269
 Gray's Knob, KY 40829
 Tel: 276-5237137
 Mike Palmer - MNGE

Dodge Hill Mine #1

PO Box 165
 Sturgis, KY 42459
 Tel: 270-9526761

1518826 **Elk Creek Mine**
 35 Frank Cox Rd
 Madisonville, KY 42431
 Tel: 270-3264007

Flint Ridge Mine

Breathitt County, KY
 Tel: 606-6666802
 Everett Kelly - Safety director

1502709 **Highland Mine**
 530 French Road
 Waverly, Kentucky 42462
 Tel:

Jones Fork Complex

550 184 Fourmile Branch
 Mousie, KY 41839
 Tel: 606-9463100
 John Hell - MNGE

Manalapan Mining Co. RB-P1 Mine

8174 E Highway 72
 Pathfork, KY 40863
 Tel: 606-5732020 ext 31
 Dennis Wilson - Engr tech

Timbers and Cribs	As needed	As needed	2 ft Shale	20-40 ft Sandstone		As needed
Nil			1.5 ft black shale slickensided on sandy shale	10 to 40ft sandy shale	50ft sandstone	About 7 days
Timbers Cribs as needed	5	Intakes and returns	2ft 0.5 to 2 ft gray shale	6 to 30 ft 0 to 8 ft limestone	5 to 30 ft 4 to 10 ft gray shale	Cables in cycle Timber 3-4 days
Cribs, Heinzman Jacks	As needed	As needed	0-15 ft Shale	Sandstone		As needed
Nil			2 ft Turner shale	>20 ft sandy shale		?
Timbers, Cribs	As needed	As needed	10-15 ft Shale	20 ft Sandstone		As needed
Cribs, Timbers, Heinzman Jacks	4 or 8	As needed	1 ft Shale	30 ft Sandstone		As needed

	<p>Martin County Coal Corp PO Box 5002, Inez, KY 41224 Tel: 606-3956881 Philip Meade - MNGE</p>	Cribs, timbers, blocks	As needed	As needed	6-20 ft Shale	Sandstone			As needed
	<p>McCoy Elkhorn Complex 1148 Long Fork Rd., Kimper, KY 41539 Tel: 616-835-2233 ext 21 Robert Maynard - MNGE</p>	Timbers, Cribs	4 in belt	As needed elsewhere	40-50 ft Sandstone	Shale			As needed
	<p>Mine 77 Blue Diamond P.O. Box 47 Slemp, KY Tel: 606-6753311 Craig Travis - MNGE</p>	Heinzman Jacks Cribs	As needed	As needed	1-10 ft Shale	5-20 ft Sandstone			Varies
	<p>Pontiki/Excel HC 67, Box 615 Pilgrim, KY 41250 Tel: 606-395-5348 David Arington - MNGE</p>	Timbers/Props	Varies	As Needed	Shale or Sandstone				Sooner if needed
	<p>Premier Elkhorn P-1 PO Box 130 Myra, KY 41549 Tel: 606-6399623 Sid Stanley - Chief Engineer</p>	Cribs, Timbers	As needed	As needed	2-3 ft Sandy Shale	20-30 ft Sandstone			7 days
	<p>Sidney Coal Co. Inc. - Freedom mine PO Box 299 Sidney, KY 41564 Tel: 606-3535509 John Cline - Chief Engineer</p>	Timbers, Cribs Heinzman Jacks	6 or 8'	As needed	5-80 ft Shale	Sandstone or coal			As needed
1502132	<p>Webster County Coal - Dotiki 1586 Balls Hill Rd Nebo, KY 42441 Tel: 270-249-2205</p>	Square Timbers	5 ft	Always on belt line also one intake, one return	1-2 ft Black Shale	10-30 ft Grey Shale	40 ft Sandstone	Limestone	3-7 days

Utah

Bear Canyon #4
 PO Box 300
 Huntington, UT 84528
 Tel: 435-6875777
 Miles Stevens - MNGE

Cans, Posts

10 ft

Always in tailgate

1 ft
 Shale

60-100 ft
 Sandstone

Varies

Deer Creek Mine
 PO Box 310
 Huntington, UT 84528
 Tel: 435-6876626
 Larry Lafrent - MNGE

3' Cans

8' Centers

Always installed

over 2000 feet
 Varied competent rock

Less than a week

Dugout Canyon
 PO Box 1029
 Wellington, UT 84542
 Tel: 435-6376360
 David Spillman - Tech. Services Manager

Rock props, ball busters
 timbers, cans

5

As needed

Varies
 Sandstone/Siltstone

3-7 days

Emery Mine
 PO Box 527
 Emery, UT 84522
 Tel: 435-2862301
 Russel Hardy - MNGE

Timbers in retreat
 Cribs rarely

4

0-12 ft
 Shale

60 ft
 Sandstone

Immediate

Skyline Complex
 North Lease Mine
 PO Box 380
 Helper, UT 84526
 Tel: 435-6377925

Cans
 24 & 30" diameter

5

skin to skin

Tailgates and bleeders

10 ft
 sandstone

12 ft
 siltstone

10 ft
 sandstone

?

Sufco Mine
 397 South 800 West
 Salina, UT 84654
 Tel: 435-2864880
 John Byers - MNGE

Cans (floor heave) timbers
 rock props

As needed

As needed

Varies
 Sandy Shale

Varies, as needed

Westridge Mine
 PO Box 910
 East Carbon, Utah 84520

Cans

Varies

Always in tailgate

10-15 ft
 Shale

Sandstone

Varies

Tel: 435-8884000
 Jay Marshall - MNGE

Virginia

Cumberland River
 Pardee Complex
 PO Box 109
 Appalachia, VA 24216
 Tel: 606-6339474
 Willie Adams - MNGE

Cribs, Timbers
 Heinzman Jacks

6 As needed

40-80 ft
 Sandstone

As needed

Knox Creek Coal Corp (Tiller 1)
 PO Box 519
 Raven, VA 24639
 Tel: 276-9644333
 Eric - MNGE

Cribs, Timbers

As needed As needed

5 ft Competent rock
 Sandstone

As needed

Lone Mountain Processing Inc.
 Drawer C
 St. Charles, VA 24282
 Tel: 606-8372299 ext 21
 James Sumner - MNGE

6x6 Timbers, cribs,
 heinzman jacks

As needed As needed

1-20 ft 1-20 ft
 Shale Sandstone

As needed

West Virginia

Bridger Coal Co.
 PO Box 68,
 Point of Rocks, WY 82942
 Tel: 307-3829741 (603)
 Tom Hurst - MNGE

Rock prop, timbers
 cribs

As needed As needed

1 ft 19 ft
 Claystone Siltstone

As needed

Coal-Mac Inc, Mountaineer Mine
 Ragland Complex
 PO Box 1050
 Holden, WV 25625
 Tel: 304-6644000
 Brian Damron - MNGE

Timbers, Cribs

As needed As needed

20-30 ft 10-20 ft
 Sandstone Shale

Varies, as needed

Independence (Justice Mine)

Propsetters or cribs

8 As needed

5-20 ft 20-30 ft

1-6 months

PO Box 1800
 Madison, WV 25130
 Tel: 304-3697103
 Andy Ashurst - MNGE

Kingston No 1

PO Box 76-C
 Scarbro, WV 25917
 Tel: ???????

Loveridge Mine

County Road M, 2 miles N of Fairview
 Fairview, WV 26570
 Tel: 304-6621229
 Mark Cramer - MNGE

McElroy Mine

Rd 1 (Marshall Co),
 Glen Easton, WV 26039
 Tel: 304-8433700
 Eric Shereda - MNGE

Miller Creek Complex

1 Stella Deskins Drive
 Williamson, WV 25661
 Tel: 304-2351850 ext 11
 Duffy Farrell - MNGE

Mountaineer 2 Mine

Box 100, State Route 17,
 Sharples, WV 25183
 Tel: 304-3697518
 Rob Brawner - MNGE

Performance (Upper Big Branch)

PO Box 457,
 Whitesville, WV 25209
 Tel: 304-8541761

				Shale	Sandstone	
	Nil			1 ft sandy shale	50 ft sandstone	
	Cribs, cans	5	Always installed on retreat	Shale	Sandrock	Limestone
						A few months
	24" Cans, cribs, Rock props	6' edge to edge	Always installed	10 Poorly laminated shale	Very thick Massive Limestone	
						1 mo - 1 yr
	Cribs, Timbers	As needed	As needed	Shale or Sandstone	10 ft Sandstone	
						As needed
	Cribs, Posts	6' edge to edge	Always installed	4-8 ft Shale	Sandstone	
						Varies
	Cribs	As needed	As needed	0-2 ft Shale	60 ft Sandstone	
						As needed

George Leao - MNGE

Pinnacle Mine

Pinnacle Creek Road

PO Box 338

Pineville, WV 24874

Tel:304-7325337

David Trade - MNGE

Rockspring Mine

PO Box 390

East Lynn, WV 25512

Tel: 304-720-2531

George Smith - Senior Engineer

Shoemaker Mine

PO Box 62A (Ohio Co)

Dallas, WV 26036

Tel: 304-2381500

Propsetter	4-5 ft or	As needed	2-3 ft	20-50 ft	As needed
4 Point Crib	as needed		Shale	Sandstone	
Cribs, Timbers	As needed	As needed	80 ft	Sandstone	As needed
			Shale		
Water Rock props	As needed	As needed	10-14 ft	20-30 ft	As needed
			Laminated Shale	Limestone	

APPENDIX B

THE UNPLANNED FALL RESULTS FROM MSHA

The results for each of the 11 MSHA Coal Districts are given, and it should be noted that all District Offices visited were very helpful.

The MSHA Districts are responsible for the following geographical areas:

- District 1 Anthracite coal mining regions in Pennsylvania
- District 2 Bituminous coal mining regions in Pennsylvania
- District 3 Maryland, Ohio, and Northern West Virginia
- District 4 Southern West Virginia
- District 5 Virginia
- District 6 Eastern Kentucky
- District 7 Central Kentucky, North Carolina, South Carolina, and Tennessee
- District 8 Illinois, Indiana, Iowa, Michigan, Minnesota, Northern Missouri, Wisconsin
- District 9 All States west of the Mississippi River, except for Minnesota, Iowa, and Northern Missouri
- District 10 Western Kentucky
- District 11 Alabama, Georgia, Florida, Mississippi, Puerto Rico, Virgin Islands



RESULTS FOR MSHA DISTRICT 1



The following are the underground mines in District 1. Of these, 3 are listed as currently “not active”.

The MSHA Data Retrieval System indicated that between 2005 and June 2008, there had been no unplanned rock falls reported.



*Mine ID	Operator Name	Mine Name
3601818	R S & W Coal Company Inc	R S & W Drift
3602022	S & M Coal Company	Buck Mountain Slope
3602203	Bear Gap Coal	N & L Slope
3606815	Tito Coal	Whites Vein Slope
3607741	B & B Coal Company	Rock Ridge No 1 Slope
3607838	Uae Coalcorp Associates	Harmony Mine
3608299	Little Buck Coal Company	No 2 Slope
3608341	R & K Coal Company Inc	Primrose Slope
3608346	Orchard Coal Company	Primrose Slope
3608637	F K Z Coal Inc	No 1 Slope
3608702	Joliett Coal Company	#3 Vein Slope
3608893	Alfred Brown Coal Company	7 Ft Slope
3609435	Kimmel's Mining, Inc	Williamstown Mine #1
3609475	Chestnut Coal Co	No 13 Slope
3609491	Little Buck Coal Company	Bottom Split Slope
3609493	Chestnut Coal Co	No 12 Slope



RESULTS FOR MSHA DISTRICT 2









RESULTS FOR MSHA DISTRICT 3









RESULTS FOR MSHA DISTRICT 4









RESULTS FOR MSHA DISTRICT 5









RESULTS FOR MSHA DISTRICT 6









RESULTS FOR MSHA DISTRICT 7








RESULTS FOR MSHA DISTRICT 8







RESULTS FOR MSHA DISTRICT 9









Note: There was no data available for stand-up times, as a visit was not personally made to District 9 in Denver, CO.



RESULTS FOR MSHA DISTRICT 10





RESULTS FOR MSHA DISTRICT 11





APPENDIX C – Detailed fall results by MSHA District

Contents:

- Unplanned intersection fall of ground data by mine in each MSHA District (note there were no falls reported in District 1 from 2005 to the present).
- Frequency distribution by District of the fall heights, lengths and stand-up time.

**MSHA DISTRICT 2 - UNPLANNED INTERSECTION FALLS OF
GROUND INVESTIGATIONS**

Mine	Owner	ID number	Date	Event #	Seam	Length	Fall size			Support	Supplemental	Water	Geology
							Width	Height	Height				
TJS #5	TJS Mining		3/16/2008	4020982	Upper Freeport	120ft	19ft	8ft	6ft tens	5X8ft cables	No	Brown gray sandstone & gray sandstone 40-60ft	
			5/31/2007	4051987	Upper Freeport	35ft	18ft	7ft	4ft tens	6ft tens	No	Gray sandys shale & gray sandstone	
			5/18/2007	4051986	Upper Freeport	45ft	20ft	12ft	5ft full	10ft cables		Gray sandys shale & gray sandstone	
Rossmoyne #1	TJS Mining Dana Mining		11/16/2007	4020969	Upper Freeport	40ft	17ft	7ft	4ft & 6ft full		No	9ft dark shale, 6ft gray sandy shale	
Titus Mine			6/13/2005	4025048	Sewickley	25ft	17ft	6.5ft	6ft full	9ft tens	No	5ft gray shale, 20ft sandstone	
West Mine	Dana Mining		9/8/2004	4025006	Sewickley	25ft	12ft	4ft	4ft full		No	15ft gray shale, 20ft sandstone	
			9/8/2004	4025008	Sewickley	30ft	16ft	5ft	4ft full		No	15ft gray shale, 20ft sandstone	
			6/14/2007	4025952	Sewickley	17ft	17ft	10ft	6ft full		No	5ft shale, 12ft sandstone	
			2/26/2007	4013111	Sewickley	30ft	20ft	12ft	5ft & 6ft full		No	5ft shale, 15ft sandstone/sandy siltstone	
			2/16/2007	4051269	Sewickley	17ft	10ft	10ft	6ft full	12ft cables	No	4.5ft shale, 12ft sandstone	
			1/27/2007	4013020	Sewickley	75ft	16ft	12ft	4ft full	12ft cables	No	Shale, Sandstone	
			10/10/2007	4011694	Sewickley	41ft	10ft	8ft	5ft full T-bar		No	5ft shale, 15ft sandstone/sandy siltstone	
Josephine #3	Rosebud Mining	36-08719	9/20/2006	4013105	Sewickley	32ft	18ft	13ft	6ft full T-bar		No	5ft shale, 15ft shale or sandstone	
			11/1/2004	4019197	Lower Kittanning	33ft	31ft	9ft	4ft full		No	5ft slickensided shale, 20ft sandstone & shale	
			9/13/2004	4050876	Lower Kittanning	30ft	20ft	9ft	4 & 6ft full		Yes	24ft gray shale, 28ft gray sandstone	
Tracy Lynne Deep	Rosebud Mining		4/8/2004	4050848	Lower Kittanning	40ft	18ft	12ft	4ft full		Yes	24ft gray shale, 28ft gray shale/sandstone	
			6/10/2005	4032379	Lower Kittanning	26ft	15ft	5ft	3ft full		No	20ft slickensided shale, 43 ft sandy shale	
Logansport	Rosebud Mining		6/10/2005	4032379	Lower Kittanning	26ft	15ft	5ft	3ft full & 6ft		No	20ft gray shale, 43ft sandy shale	
			12/16/2007	4051949	Lower Kittanning	60ft	19ft	4.5ft	3.5ft full	Spot cables & longer bolts	No	4ft dark laminated shale/ 16ft gray sandy shale	
			6/25/2007	4032420	Lower Kittanning	40ft	18ft	4ft	3.5ft full & posts		No	4ft laminated dark shale/ 16ft gray sandy shale	
Twin Rocks	Rosebud Mining	36-08836	12/12/2005	4032389	Lower Kittanning	25ft	16ft	4ft	3 & 3.5ft full		No	27ft dark shale, 16ft gray sandy shale	
			12/16/2007	4020973	Lower Freeport	30ft	19ft	6ft	3.5ft full		No	12ft gray shale, 10-32ft grayshale/sandy shale	
			4/22/2006	4051510	Lower Freeport	100ft	18ft	10ft	6ft supertwists 6ft full & 5ft tens T-bar	6X10ft cable	No	12ft gray shale, 10ft gray sandy shale	
			1/4/2006	4033505	Lower Freeport	19ft	6ft	8ft		8-12ft cables	No	12ft gray shale, 32ft gray & sandy shale	
			7/15/2005	4031280	Lower Freeport	200ft	20ft	8ft	3.5ft full		No	12ft gray shale with sandstone streaks, 15ft gray shale	
			4/5/2005	4050895	Lower Freeport	25ft	20ft	7ft	6ft full	spot 12ft cables	No	12ft gray shale, 20ft sandy shale	
Little Toby Mine	Rosebud Mining AMFIRE Mining		3/10/2004	4031205	Lower Freeport	900ft	20ft	14ft	4 & 6ft full	12 & 14ft cables	No	12ft gray shale, 20ft sandy shale	
			2/9/2004	4031202	Lower Freeport	120ft	20ft	10ft	4 & 6ft full		No	12ft gray shale, 20ft sandy shale	
			5/23/2007	4039672	Lower Kittanning	40ft	20ft	7ft	3.5ft & 6ft full		Yes	Dark gray shale, 10-40ft grayshale	
Dora 8	AMFIRE Mining	36-08704	7/27/2004	4050870	Lower Kittanning	25ft	20ft	6ft	4ft full	Yes	47ft hard shale, 25ft hardshale & sandstone		

Ondo Extension	AMFIRE Mining		2/13/2004	4050834	Lower Kittanning	25ft	15ft	6ft	3ft full	No	47ft hard shale, 250ft silty hard shale	
Ridge Deep Madison Mine	AMFIRE Mining	36-09127	8/7/2007	4039737	Lower Kittanning	25ft	18ft	15ft	6ft full	12ft cables	No	1.5ft shale, 15ft shale/sandstone
	AMFIRE Mining		3/3/2006	4020926	Pittsburgh	20ft	20ft	15ft	6ft tens		No	20ft dark shale/ 15ft sandstone
	AMFIRE Mining		8/14/2006	4051517	Upper Freeport	90ft	20ft	6ft	4ft full		No	2ft dark shale/ 10ft shale or sandstone
			10/18/2004	4031241	Upper Freeport	27ft	22ft	14ft	4ft & 5ft full	beams and props	No	4ft shale, 20ft mud shale
			10/11/2004	4031240	Upper Freeport	22ft	20ft	12ft	4ft full	beams and props	No	20ft shale, 20ft shale
Nolo Mine	AMFIRE Mining	36-08850	4/11/2007	4020959	Lower Kittanning	600ft	19ft	11ft	6.5ft combo T5 ch	10-12ft cables	No	19ft shale, 22ft sandy shale/sandstone
			2/8/2007	4020952	Lower Kittanning	65ft	30ft	11ft	6.5ft combo	10ft cables, 8ft spacing	No	19ft shale, 22ft sandy shale/sandstone
			3/18/2006	4020930	Lower Kittanning	60ft	18ft	7ft	7ft double tens T-bar	10ft cables, 8ft spacing	No	
			10/21/2005	4050579	Lower Kittanning	55ft	18ft	8ft	5ft point anchor		No	30ft dark shale, 22ft sandy shale & sandstone
			8/5/2005	4020545	Lower Kittanning	20ft	20ft	10ft	6ft full	5X12ft cables	No	30ft dark shale, 22ft sandy shale
			7/9/2005	4020544	Lower Kittanning	60ft	20ft	80ft	6ft point tens	12ft cables	No	30ft dark shale, 22ft sandy shale
			4/8/2005	4020540	Lower Kittanning	30ft	20ft	8ft	6ft tens		No	30ft dark shale, 22ft shale with sandstone
			4/8/2005	4020540	Lower Kittanning	40ft	20ft	8ft	6ft tens		No	30ft dark shale, 22ft shale with sandstone
			3/7/2005	4020388	Lower Kittanning	30ft	14ft	5ft	4ft tens		No	30ft dark shale, 22ft shale with sandstone
			6/25/2004	4050859	Lower Kittanning	40ft	20ft	8ft	4ft tens		Yes	19ft laminated shale, 22ft sandy shale
			6/28/2004	4050861	Lower Kittanning	35ft	20ft	7ft	5ft tens		No	19ft laminated shale, 22ft sandy shale
			2/20/2004	4050835	Lower Kittanning	140ft	18ft	14ft	4ft active		No	19ft laminated shale, 22ft sandy shale
			2/2/2004	4050832	Lower Kittanning	50ft	19ft	12ft	4 & 6ft active	12ft cables	No	30ft dark soft shale, 22ft shale with sandstone
Dooley Run Mine	Cobra Mining		1/26/2007	4013019	Sewickley	40ft	40ft	20ft	4ft full		No	Drawslate, shale/sandstone
Bailey Mine	CONSOL	36-07230	9/27/2007	4015817	Pittsburgh #8	53ft	16ft	13ft	8ft full & channels		No	6.5ft gray shale, 23ft sandy shale
			7/12/2005	4022594	Pittsburgh	40ft	16ft	12ft	8-12ft tens		No	8ft laminated shale, 22ft sandstone
			5/16/2005	4024570	Pittsburgh	30ft	16ft	7ft	8ft tens		No	6ft shale/coal, 22ft shale & limestone
			5/16/2005	4024570	Pittsburgh	30ft	16ft	7ft	8ft tens T5 ch		No	6.5ft shale/coal, 22ft shale & gray limestone
Cherry Tree Mine	Parkwood Resources		12/18/2006	4020947	Upper Freeport	30ft	19ft	10ft	6ft full	12ft cables	No	5ft sandy shale/ 15ft shale or sandy shale
Quecreek #1	Black Wolf Coal		10/9/2005	4031285	Upper Kittanning	400ft	20ft	15ft	4ft & 6ft full	10ft cables	No	10ft shale, 20ft sandstone
			8/7/2005	4031281	Upper Kittanning	240ft	20ft	15ft	4-6ft full	10ft cables	No	10ft shale, 20ft sandstone
Genesis #17		36-08980	9/27/2004	4031238	Upper Kittanning	40ft	20ft	7ft	5ft tens		No	5ft laminated shale, 15ft sandstone
Miller Mine	Rox Coal	36-08622	4/19/2004	4031209	Upper Freeport	30ft	30ft	10ft	4 & 5ft full	8ft cables	No	8ft shale, 10ft sandstone
			3/9/2004	4031203	Upper Freeport	47ft	20ft	6ft	4ft full		No	6ft shale and sandstone, 10ft sandstone

MSHA DISTRICT 3 - UNPLANNED INTERSECTION FALLS OF GROUND INVESTIGATIONS

Mine	Owner	ID number	Date	Event #	Seam	Fall size			Support	Supplemental	Water	Geology
						Length	Width	Height				
Whitetail	Alpha Natural Res.	46-08751	4/13/2008		Lower Kittanning	25ft	18ft	8ft	6ft full straps	Screen & trusses	No	10-15ft sandy shale to claystone then sandstone
			4/9/2008		Lower Kittanning	20ft	18ft	8ft	6ft full straps	Screen & 12ft cables	No	10-15ft sandy shale to claystone then sandstone
			4/8/2008		Lower Kittanning	20ft	17ft	7ft	6ft full straps	Screen & 12ft cables	No	10-15ft sandy shale to claystone then sandstone
			4/7/2008		Lower Kittanning	80ft	17ft	7ft	6ft full straps	Screen	No	10-15ft sandy shale to claystone then sandstone
			3/11/2008		Lower Kittanning	20ft	20ft	8ft	6ft full pans	12ft cables	No	10-15ft sandy shale to claystone then sandstone
			3/11/2008		Lower Kittanning	20ft	20ft	8ft	6ft full pans	12ft cables	No	10-15ft sandy shale to claystone then sandstone
			3/11/2008		Lower Kittanning	20ft	20ft	8ft	6ft full pans	12ft cables	No	10-15ft sandy shale to claystone then sandstone
			3/11/2008		Lower Kittanning	20ft	20ft	8ft	6ft full pans	12ft cables	No	10-15ft sandy shale to claystone then sandstone
			3/11/2008		Lower Kittanning	20ft	20ft	8ft	6ft full pans	12ft cables	No	10-15ft sandy shale to claystone then sandstone
			3/11/2008		Lower Kittanning	20ft	20ft	8ft	6ft full pans	12ft cables	No	10-15ft sandy shale to claystone then sandstone
			3/11/2008		Lower Kittanning	20ft	20ft	8ft	6ft full pans	12ft cables	No	10-15ft sandy shale to claystone then sandstone
			3/11/2008		Lower Kittanning	20ft	20ft	8ft	6ft full pans	12ft cables	No	10-15ft sandy shale to claystone then sandstone
			3/13/2008		Lower Kittanning	60ft	18ft	8ft	6ft full straps		No	10-15ft sandy shale to claystone then sandstone
			3/10/2008		Lower Kittanning	20ft	20ft	8ft	6ft full straps	12ft cables	No	10-15ft sandy shale to claystone then sandstone
			3/5/2008		Lower Kittanning	20ft	20ft	8ft	6ft full straps	12ft cables	No	10-15ft sandy shale to claystone then sandstone
			3/4/2008		Lower Kittanning	60ft	18ft	8ft	6ft full straps		No	10-15ft sandy shale to claystone then sandstone
			3/3/2008		Lower Kittanning	20ft	20ft	8ft	6ft full straps	12ft cables	No	10-15ft sandy shale to claystone then sandstone
			3/3/2008		Lower Kittanning	20ft	20ft	8ft	6ft full straps	12ft cables	No	10-15ft sandy shale to claystone then sandstone
			2/25/2008		Lower Kittanning	30ft	18ft	8ft	6ft full straps	12ft cables	No	10-15ft sandy shale to claystone then sandstone
			2/20/2008		Lower Kittanning	25ft	22ft	7ft	6ft full straps	12ft cables & trusses	No	10-15ft sandy shale to claystone then sandstone
			2/9/2008		Lower Kittanning	25ft	17ft	7ft	6ft full straps	12ft cables	No	10-15ft sandy shale to claystone then sandstone
			2/7/2008		Lower Kittanning	20ft	20ft	7ft	6ft full straps	Trusses	No	10-15ft sandy shale to claystone then sandstone
			2/5/2008		Lower Kittanning	20ft	17ft	8ft	6ft full straps	Trusses	No	10-15ft sandy shale to claystone then sandstone
			1/28/2008		Lower Kittanning	20ft	17ft	7ft	6ft full straps	Trusses	No	10-15ft sandy shale to claystone then sandstone
			1/27/2008		Lower Kittanning	10ft	8ft	4ft	6ft full straps	Trusses	No	10-15ft sandy shale to claystone then sandstone
			12/6/2007		Lower Kittanning	40ft	17ft	7ft	6ft full straps		No	10-15ft sandy shale to claystone then sandstone
			11/28/2007		Lower Kittanning	25ft	25ft	8ft	6ft full straps	12ft cables	No	10-15ft sandy shale to claystone then sandstone
			11/9/2007		Lower Kittanning	18ft	18ft	7ft	6ft full straps	12ft cables & cribs	No	10-15ft sandy shale to claystone then sandstone
			11/3/2007		Lower Kittanning	30ft	17ft	7ft	6ft full straps	12ft cables	No	10-15ft sandy shale to claystone then sandstone
			10/27/2007		Lower Kittanning	35ft	17ft	12ft	6ft full straps	12ft cables	No	10-15ft sandy shale to claystone then sandstone
10/22/2007		Lower Kittanning	50ft	17ft	8ft	6ft full straps	Trusses	No	10-15ft sandy shale to claystone then sandstone			

			10/11/2007	Lower Kittanning	10ft	8ft	8ft	6ft full straps	Cables & screens	No	10-15ft sandy shale to claystone then sandstone
			10/11/2007	Lower Kittanning	40ft	18ft	8ft	6ft full straps	Cables	No	10-15ft sandy shale to claystone then sandstone
			10/10/2007	Lower Kittanning	25ft	17ft	8ft	6ft full	Screens, 12ft cables & jacks	No	10-15ft sandy shale to claystone then sandstone
			9/29/2007	Lower Kittanning	30ft	17ft	7ft	6ft full straps	12ft cables	No	10-15ft sandy shale to claystone then sandstone
Tusky	Rosebud	33-04509	9/25/2007	Middle Kittanning	80ft	18ft	15ft	4ft full	Timber	No	15-20ft gray shale, 35-60ft gray sandstone
			8/12/2007	Middle Kittanning	20ft	20ft	6ft	4ft full	Cables	No	15-20ft gray shale, 35-60ft gray sandstone
			7/23/2007	Middle Kittanning	25ft	20ft	5ft			No	15-20ft gray shale, 35-60ft gray sandstone
			9/15/2007	Middle Kittanning	50ft	30ft	15ft			No	15-20ft gray shale, 35-60ft gray sandstone
			8/27/2007	Middle Kittanning	40ft	30ft	6ft	4ft full		No	15-20ft gray shale, 35-60ft gray sandstone
			7/16/2007	Middle Kittanning	70ft	18ft	4ft	4ft full	12ft cables	No	15-20ft gray shale, 35-60ft gray sandstone
			7/23/2007	Middle Kittanning	40ft	17ft	5ft	4ft full		No	15-20ft gray shale, 35-60ft gray sandstone
			5/22/2007	Middle Kittanning	30ft	17ft	4ft	5ft full	Cables	No	15-20ft gray shale, 35-60ft gray sandstone
Mountain View	Mettiki Coal	49-09028	11/3/2007	Upper Freeport	16ft	16ft	10ft	6ft tens	Roof mats	No	±10ft shale and siltstone then sandstone
			11/5/2007	Upper Freeport	25ft	20ft	9ft	6ft tens	Screen	No	±10ft shale and siltstone then sandstone
			10/18/2007	Upper Freeport	55ft	16ft	15ft	6ft tens	Screen	No	±10ft shale and siltstone then sandstone
			11/3/2007	Upper Freeport	16ft	16ft	10ft	6ft tens	Screen	No	±10ft shale and siltstone then sandstone
			1/18/2006	Upper Freeport	25ft	16ft	6ft	6ft tens	Screen	No	±10ft shale and siltstone then sandstone
			5/9/2007	Upper Freeport	25ft	20ft	9ft	6ft tens	12ft cables & trusses	No	±10ft shale and siltstone then sandstone
			8/25/2006	Upper Freeport	14ft	12ft	6ft	6ft tens	Screen	No	±10ft shale and siltstone then sandstone
			8/1/2006	Upper Freeport	20ft	16ft	6ft	6ft tens		No	±10ft shale and siltstone then sandstone
			2/14/2006	Upper Freeport	20ft	16ft	13ft	6ft tens	12ft spot bolts	No	±10ft shale and siltstone then sandstone
			2/1/2006	Upper Freeport	20ft	18ft	12ft	6ft tens T5 ch	12ft cables	No	±10ft shale and siltstone then sandstone
			8/25/2006	4358669 Upper Freeport	20ft	16ft	6ft	6ft tens T5 ch	Screen	No	±10ft shale and siltstone then sandstone
			1/18/2006	4077670 Upper Freeport	25ft	16ft	6ft	6ft tens T5 ch	Screen	No	±10ft shale and siltstone then sandstone
Imperial	Wolf Run	46-09115	1/19/2008	Middle Kittanning	17ft	15ft	6.5ft	6ft full		No	19ft shale, 20ft sandy shale
			4/28/2008	Middle Kittanning	110ft	18ft	8ft	6ft full		No	19ft shale, 20ft sandy shale
Blacksville No.2	Consol	46-01968	2/13/2008	Pittsburgh 8	40ft	16ft	8ft	8ft tens straps		No	8-20ft shale then 5-30ft redstone/limestone
			11/22/2007	Pittsburgh 8	12ft	10ft	8ft			No	8-20ft shale then 5-30ft redstone/limestone
			8/23/2007	4359483 Pittsburgh 8	30ft	12ft	10ft	8ft tens T3 ch	16ft cables	No	8-20ft shale then 5-30ft redstone/limestone
			2/13/2007	4358884 Pittsburgh 8	10ft	7ft	12ft	8ft tens T3 ch	12ft cables	No	8-20ft shale then 5-30ft redstone/limestone
			10/27/2005	4077664 Pittsburgh 8	20ft	16ft	9ft	8ft tens T3 ch		No	8-20ft shale then 5-30ft redstone/limestone
			12/11/2005	Pittsburgh 8	35ft	16ft	10ft	8ft tens T3 ch		No	8-20ft shale then 5-30ft redstone/limestone
			8/29/2007	Pittsburgh 8	14ft	10ft	8ft	8ft tens		No	8-20ft shale then 5-30ft redstone/limestone
			9/18/2007	Pittsburgh 8	25ft	16ft	8ft	8ft tens	12ft cables	No	8-20ft shale then 5-30ft redstone/limestone
			8/13/2007	Pittsburgh 8	16ft	9ft	8ft	8ft tens		No	8-20ft shale then 5-30ft redstone/limestone

8/4/2007

Pittsburgh 8

71ft

16ft

8ft

8ft tens

No

8-20ft shale then 5-30ft redstone/limestone

MSHA DISTRICT 4 - UNPLANNED INTERSECTION FALLS OF GROUND INVESTIGATIONS

Mine	Owner	ID number	Date	Event #	Seam	Fall size			Support	Supplemental	Water
						Length	Width	Height			
Round Bottom Powellton	Elk Run	46-09163	4/23/2008		Powellton	70	20	8ft			No
			4/13/2008			60	20	7ft			No
Justice #1	Independence Coal	46-07273	5/11/2008			45	20	10ft			No
Laurel Coalburg Tunnel Mine	Mammoth Coal Co.	46-09148	5/9/2008			20	20	6ft			No
No. 2 Gas	Mammoth Coal Co.	46-09108	5/10/2008			42	19	13ft			No
			5/5/2008			80	18	12ft			No
			4/23/2008			50	18	16ft			No
No. 130	Mammoth Coal Co.	46-06051	5/6/2008			60	18	12ft			No
Candice No. 2	Long Branch Energy	46-08429	5/2/2008			30	20	8ft			No
			4/8/2008			30	20	5ft			No
			4/8/2008			30	20	5ft			No
Laurel Creek 5	Laurel Creek Mining	46-09132	5/2/2008			20	19	5ft			No
Fork Creek Mine #1	Coal River Mining	46-08763	4/29/2008			20	20	6ft			No
Aracoma Alma	Aracoma Coal Co	46-08801	4/26/2008			300	20	12ft			No
Ruby Energy	Spartan Mining	46-08808	4/25/2008		#2 Gas	100	19	7ft			No
			3/20/2008			100	18	7ft			No
			1/14/2008			100	9	6ft			No
			1/28/2008			60	19	8ft			No
			1/14/2008			30	25	8ft	5ft full		No
Cedar Grove Mine	Marfork Coal Co.	46-09048	4/24/2008			70	20	6ft	4ft full		No
Mountaineer II	Mingo Logon	46-09029	4/7/2008		Alma & Cedar Grove	20	19	9ft			No
			3/4/2008			25	20	4.5ft	4ft full		No
			2/21/2008			60	20	6.5ft			No
			10/1/2007			30	18	4.5ft	4ft full		No
No. 23 Mine	Long Branch Energy	46-08637	4/18/2008			30	20	6ft			No
Lick Branch No. 2	Little Eagle Coal Co.	46-08676	4/15/2008			30	30	4ft			No
			9/25/2007			50	20	6ft	4ft full		No
Pocahontas Mine # 3	ICG	46-05252	4/14/2008			70	20	8ft			No
Midland Trail Mine #1	West Virginia Mine Power	46-08522	3/27/2008		Beckley	40	20	6ft			No
			1/17/2008			20	20	5ft	4ft full		No
			11/25/2007			20	12	6ft	6ft tens		No

			11/14/2007	Beckley	40	20	5ft	4ft full		No
			10/23/2007	Beckley	20	20	5ft	5ft full		No
			10/3/2007	Beckley	20	20	6ft	4-5ft tens		No
			9/11/2007	Beckley	18	16	7ft	6ft tens		No
			8/30/2007	Beckley	40	20	5ft	4-5ft tens		No
			8/30/2007	Beckley	70	20	5ft	4-5ft tens		No
			9/7/2007	Beckley	20	20	8ft	6ft tens		No
			8/30/2007	Beckley	40	20	5ft	4-5ft tens		No
Copperhead #1	Glow Worm Coal Co.	46-08897	4/2/2008		35	18	3.5ft			No
No. 1	Laurel Creek Co.	46-08019	3/17/2008	Coalburg	30	20	10ft	Bolts	Cribs	No
			3/25/2008	Coalburg	20	10	3ft	4ft full	Cribs	No
No. 5	Laurel Creek Co.	46-09132	3/19/2008		350	19	4ft	4ft full	Cribs	No
Camp Springs	Rocksprings Development	46-05121	3/23/2008	Winifred	60	20	6ft	5ft tens		No
Josephine # 2	Pocahontas Coal	46-07191	2/22/2008	Pocahontas 2	20	15	5ft	4ft full		No
			1/2/2008	Pocahontas 2	80	20	5ft			No
			10/16/2007	Pocahontas 2	110	20	5ft	4ft full		No
			10/16/2007	Pocahontas 2	200	20	5ft	4ft full		No
Poplar Ridge # 1	Brooks Run Mining Co.	46-08885	3/24/2008	Lower Kittanning	30	18	7ft	5ft tens		No
Pinnacle Mine		46-01816	3/21/2008	Pocahontas 3	30	18	12ft	5ft tens		No
			12/3/2007	Pocahontas 3	188	18	6ft	5ft full		No
Rivers Edge		46-08890	3/10/2008	Powellton	20	19	8ft	5ft full		No
			11/28/2007	Powellton	20	20	8ft	5ft full		No
Upper Big Branch	Performance Coal Co.	46-08436	3/12/2008	Eagle	20	20	5ft	4ft tens		No
			12/31/2007	Eagle	20	20	4.5ft	4ft tens		No
			12/31/2007	Eagle	20	20	4.5ft	4ft tens		No
			11/9/2007	Eagle	100	18	4ft	4ft full		No
			9/27/2007	Eagle	60	18	5ft	4ft full		No
			9/11/2007	Eagle	30	20	4.5ft	4ft tens		No
Rama 1A	Rama Development	46-09173	2/22/2008		50	20	6ft			No
Camp Creek	Rockspring Deer	46-05121	2/29/2008		240	?	8ft	5ft tens		No
			10/23/2007		100	20	7ft	5ft tens		No
Eagle # 1	Appalachian Fuels	46-09164	2/26/2008	Eagle	380	19	5ft	4ft full		No
Grassy Creek No. 1	White Buck Coal	46-08365	2/8/2008		25	20	6.5ft	4ft full		No
			1/4/2008		40	20	5ft	4ft full		No
			11/19/2007		20	20	7ft	6ft tens		No

		46-08345	9/24/2007		40	20	6.5ft	6ft tens		No
Mountaineer Pocahontas	West Virginia Mine Power	46-09154	1/29/2008		20	20	5ft	5ft tens		No
			1/14/2008		19	19	5ft	5ft full		No
Castle Logans Fork	Elk Run Coal	46-07009	1/5/2008	Peerless	50	20	5ft	4ft full		No
Tunnel Mine	Shelby Coal	46-09209	1/31/2008		76	18	7ft	5ft full straps		No
No. 65 Mine	Double Bonus Coal	46-09020	1/31/2008	Fire Creek	20	20	6ft			No
Tiny Creek # 2	Coal River Mining	46-08835	1/17/2008		30	20	10ft	6ft tens & 8ft points		No
Castle East Portal	Elk Run Coal	46-08923	1/2/2008		105	18	8ft	5ft full	Cables	No
			1/2/2008		105	18	8ft	5ft full	Cables	No
			11/7/2007		22	20	6ft	4ft full		No
		46-07009	11/1/2007		50	20	6ft	6ft full		No
			10/10/2007		70	20	5ft	4ft full		No
Allen Powellton	Marfolk Coal Co.	46-09092	1/8/2008	Powellton	20	20	15ft	4ft full & 6ft spot		No
			1/8/2008	Powellton	20	20	15ft	4ft full & 6ft spot		No
Poplar Ridge No. 1		46-08885	12/6/2007		60	18	6ft	5ft tens		No
White Buck Coal		46-07042	10/26/2007	Sewell	50	18	4ft	4ft full		No
Big Mountain # 16	Pine Ridge Coal	46-07908	11/26/2007	Coalburg	100	20	10ft	5ft full		No
			10/24/2007	Coalburg	100	20	7ft	5ft full		No
Rocklick Coalburg Deep Mine	Little Eagle Coal	46-09171	10/31/2007		30	20	4ft	4ft full		No
			10/2/2007		28	22	4.5ft	4ft full		No
			9/23/2007		35	19	5ft	4ft full		No
White Queen	Marfolk Coal Co.	46-08297	10/31/2007	Upper Powellton	70	20	6ft	4ft full		No
Pinnacle			11/5/2007		40	20	9ft	5ft full		No
			9/3/2007		30	20	8ft	5ft tens		No
War Branch # 1	Brooks Run Mining Co.	46-09055	11/6/2007	Douglas Red Ash	30	20	4ft	3.5ft full		No
Mountaineer # 2			10/23/2007	Alma	100	18	12ft	5ft point		No
Brody Mine # 1	Brody Mining	46-09086	10/15/2007		30	20	6ft	5ft tens		No
			9/11/2007		115	20	8ft	6ft tens		No
Aracoma Alma No. 1			10/19/2007	Alma	400	20	10ft	6ft tens	8ft cables	No
Horse Creek Eagle Mine	Marfolk Coal Co.		10/4/2007		100	18	6ft	4ft ?		No
			8/31/2007		60	20	6ft	4ft full	Cribs	No
Tiny Creek # 2	Coal Mining River	46-08835	10/1/2007		60	19	7ft	6ft tens		No
Slip Ridge Cedar Grove	Marfolk Coal Co.	46-09048	10/3/2007	Cedar Grove	10	10	8ft	4ft full		No
Mountaineer Pocahontas # 2			9/21/2007		20	20	10ft	4ft full		No
Rocklick # 3	Little Eagle Coal	46-09171	8/30/2007		38	18	4ft	4ft full		No

			8/28/2007			35	30	5ft	4ft full		No
Midland Trail # 2		46-08909	9/11/2007			40	18.5	7ft	6ft tens		No
Black King	Elk Run Coal	46-08553	9/18/2007			45	20	6ft	5ft tens		No
Beckley Crystal	Bryton Mining Inc.	46-08829	9/3/2007			20	20	8ft	6ft tens		No
Eagle Mine	Newtown Energy	46-08759	9/6/2007			35	19	5ft	4-6ft full		No
			9/6/2007			25	20	8ft	5-8ft tens		No
Mammoth #2	Mammoth Coal Co.	46-09108	9/3/2007			30	20	8ft	6ft tens T5 straps	8ft cables	No
Mine #1	Selah Corp	46-08999	9/7/2007			25	20	4ft	4ft full		No
Big Mine No. 16	Pine Ridge Coal	46-07908	1/22/2008	4118666		30	25	4ft	5ft full		No
Tiny Creek # 2	Coal River Mining	46-08835	1/29/2008	4120165		30	16	6ft			No
Mine No. 1A	Mare Development	46-09173	2/22/2008	4119879		50	20	7ft	5ft full		No
Diamond Energy	Spartan Mining	46-08738	2/27/2008	4190717	Williamson	24	20	10ft	5ft full		No
Jerry Fork Eagle	Alex Energy	46-08787	3/3/2008	4116826		100	20	6ft	4-6ft full		No
Beckley Pocahontas	ICG Beckley	46-05252	4/14/2008	4119552	Pocahontas No. 3	60	20	6ft	5ft tens		No
Ruby Energy	Spartan Mining	46-08808	4/20/2008	4120811	#2 Gas	50	20	8ft	6ft tens	12ft cables	No
Cucumber Mine	Brooks Run Mining Co.				Pocahontas No. 3						No
Grassy Creek No. 1	White Buck Coal	46-08365	3/7/2007	4112549	Sewell	52	20	5.5ft	4ft full		No
Brody Mine # 1	Brody Mining	46-09086	3/19/2007	4116438	Eagle	270	18	14ft	5ft full		No
Ruby Energy	Spartan Mining	46-08808	3/27/2007	4114280	#2 Gas	40	19	7ft	5ft full		No
Harris No. 1	Eastern Assoc. Coal	46-01271	4/21/2007	4113397	Eagle	30	20	6ft			No
8-C Mine	Hanover Resources	46-06500	6/15/2007	4115971	#2 Gas	80	18	8ft	4-6ft full		No
Camp Creek	Rockspring Deer	46-05121	7/13/2007	4116134	Coalburg	120	20	7ft			No
Rocklick Coalburg Deep Mine	Little Eagle Coal Co.	46-09171	7/17/2007	4117307	Coalburg	55	20	7ft	4ft full & 6ft tens		No
Dorothy No.3	Mountain Edge Mining	46-09150	7/18/2007	4118653	Dorothy	20	20	9ft			No
Big Mountain # 6	Pine Ridge Coal	46-07908	7/19/2007	4115840	Coalburg	60	20	6ft			No
Horse Creek Eagle Mine	Marfolk Coal Co.	46-09091	9/19/2007	4114687	Eagle	18	15	5ft			No
Deep Mine No.7	Argus Energy	46-08772	7/26/2007	4115976	Five Black	35	19	6ft	6ft full & 6ft tens		No
Mine No.7	Rock n' Roll Coal	46-09093	8/8/2007	4117859	Red Ash	45	20	6ft	2.5ft full		No
Justice #1	Independence Coal	46-07273	8/18/2007	4118366	Powellton	32	19	7ft			No
Mountaineer II	Mingo Logon	46-09029	8/19/2007	4117100	Alma	30	20	8ft			No
No. 6	Laurel Creek Co.	46-08224	9/4/2007	4112070	Cedar Grove	22	11	7ft			No
Harris No. 1	Eastern Assoc. Coal	46-01271	10/8/2007	4118382	Eagle	75	20	5ft			No

**MSHA DISTRICT 5 - UNPLANNED INTERSECTION
FALLS OF GROUND INVESTIGATIONS**

Mine	Owner	ID number	Date	Event #	Seam	Fall size				Supplemental	Water	Geology
						Length	Width	Height	Support			
Cherokee Mine	Dickenson Russell Coal	44-06864	3/20/2008	4402635	Splashdam	25	14	4	4' full			10' shale then 20' sandstone
Cherokee Mine			4/13/2007	4160316	Splashdam	52	40	3	4' full	Timber		5' laminated shale then 10' sandstone
Roaring Fork No 4	Dickenson Russell Coal	44-07146	11/18/2007	4156746	Lower Banner	20	20	8	5' full	8' cables		
Roaring Fork No 4			10/17/2007	4128985	Lower Banner	45	20	10	5' full	6 by 8' cables		10' gray shale then 20' sandstone
Roaring Fork No 4			8/16/2005	4128952	Lower Banner	30	16	6.5	6' tens			10' slickensided shale then 10' sandstone
Roaring Fork No 4			5/13/2005	4128936	Lower Banner	67	14	17	6' tens	8 & 12' cables		17' slickensided and laminated shale then sandy shale
Mine No 3	Guest Mountain	44-07069	1/17/2008	4127540	Upper Parson	80	20	25	5' full, 8' superbolts			10' shale then 10' sandstone
Mine No 4	Guest Mountain Bluff Spur Coal	44-05815	1/7/2008	4157529	Upper Parson	60	20	5	5' full, 8' superbolts			10' shale then 10' sandstone
Mine No 1		44-05559	12/17/2007	4127532	Mareker	20	18	5	5' pt anchor	10' cables		10' laminated shale then 10' shale
Mine No 1			9/11/2006	4141100	Taggart	120	50	15	4' full	8' cables		gray shale
Tiller No 1	Knox Creek Coal	44-06804	11/20/2007	4127521	Jawbone	25	16	6.5	5' tens			3.5' shale then 10' sandstone
Tiller No 1			9/20/2006	4153873	Tiller	30	18	8	6' tens	10' cables		3.5' shale then 10' sandstone
Tiller No 1			9/6/2005	4153403	Tiller	30	20	10	6' tens	10' cables		10' laminated shale then sandstone
Premium Mine	The Banner Co	44-07181	11/3/2007	4141170	Hagy	20	20	6	5' full			10' shale then 10' sandstone
Deep Mine No 26	Paramount Coal Co	44-06929	10/9/2007	4127515	Lower Banner	30	18	6	5' full	12' cables		shale
Deep Mine No 26			11/27/2006	4129279	Lower Banner	60	18	8	5' full	10' cables		shale
Deep Mine No 26			8/26/2006	4155491	Lower Banner	25	6	5	5' full	10' cables		shale
Deep Mine No 26			11/27/2006	4129279	Lower Banner	60	18	8	5' full	10' cables		shale
Deep Mine No 26			2/16/2005	4128001	Lower Banner	90	20	10	5' full	8' cables		10' laminated shale then 43' shale
No 2	Black Dog Coal	44-04946	9/14/2007	4127510	Jawbone	26	20	12	5' full	8' cables		10' shale then 10' sandstone
No 2			7/18/2006	4158440	Jawbone	20	20	18	5' full & 6' pt anchor	8' cables		10' slickensided shale then 20' sandstone
Dominion No 34	Dominion Coal Co	44-06839	8/28/2007	4402621	Kennedy	35	25	12	3.5 full			shale
Deep Mine No 35	Paramount Coal Co	44-07123	7/16/2007	4129245	Tiller	30	20	10	4' full	12' cables		6' laminated shale then 70' sandstone
No 5	Da Coal Mining	44-07154	5/8/2007	4128979	Hagy	27	5	5	4' full			shale
Mine No 4	Dorchester Enterprises	44-07052	6/29/2007	4129242	Imboden	22	22	8	6' pt anchor, 8' superbolts	12' cables		10' laminated shale then 10' sandstone
Mine No 4			8/9/2006	4129031	Dorchester	20	20	10	5' full	8' cables		10' laminated shale then 10' sandstone
Mine No 4			5/8/2005	4128935	Imboden	55	18	6	5' tens			10' shale then 10' sandstone
Miles Branch	Consolidation Coal	44-03932	4/19/2007	4402523	Pocahontas #5	60	20	8	4' full, 6' full	Timber		4' soft shale then 10' laminated sandstone
Miles Branch			8/18/2006		Pocahontas #5	22	20	8	4' & 6' full	Timber		?

Miles Branch			5/2/2006	4153709	Pocahontas #5	40	18	7	4', 5' & 6' full		10' laminated shale then 10' sandstone
Miles Branch			4/11/2006	4160285	Pocahontas #5	60	18	6	4' full		6' laminated shale then 10' sandstone
Miles Branch			2/7/2006	4153418	Pocahontas #5	40	14	4	4' full		10' laminated shale then 10' sandstone
Miles Branch			12/13/2005	4153412	Pocahontas #5	80	18	4	3.5' full		10' laminated shale then 10' sandstone
No 1 Mine	Keokee Mining L&J Equipment Co	44-06947	2/26/2007	4129213	Wilson	50	20	10	4' full		shale
No 4 Mine	JJJ Coal Corp	44-00280	10/9/2006	4129048	Lower Banner	14	10	5.5	5' full		8' slickensided shale then shale
Honey Branch		44-06599	10/2/2006	4158409	Jawbone	70	18	7	5' full		3' shale then 10' sandstone
Honey Branch			6/15/2005	4128748	Jawbone	20	18	7	4' full & 6' tens	Yes	3' sandy shale then 10' sandstone
Mine No 3	Cat Bird Mining	44-06812	6/27/2006	4129020	Splashdam	30	20	4	3' full		10' laminated shale then 15' sandstone
Mine No 1	SANW Inc	44-06836	4/17/2006	4153707	Jawbone	15	15	2	3' & 4' full	Cribs	10' laminated shale then 10' sandstone
Mine No 3	Paramount Coal Co	44-06853	8/11/2006	4157083	Jawbone	60	19	20	6' tens	10' cables	6' shale then 20' shale and sandstone
Mine No 1	Snapco Inc	44-06866	2/18/2006	4153419	Splashdam	140	20	8	4' full	8' cables	10' laminated shale then 10' sandy shale
Low Splint No 1	Meadow Branch Mining	44-06883	6/29/2006	4155484	Low Splint	40	20	8	4' full		10' sandy shale then 10' sandstone
Low Splint No 1			11/13/2005	4128113	Low Splint	30	20	10	4' full	8' cables	6' shale with coal streaks then 10' sandstone
Low Splint No 1			11/16/2005	4128954	Low Splint	54	36	7	4' full		6' shale with coal streaks then 10' sandstone
No 7 Mine	Sigmon Coal Co	44-06947	10/11/2006	4155500	Wilson	25	15	7	6' pt anchor	8' cables	shale
No 7 Mine			8/9/2006	4129029	Wilson Lower Banner	20	20	12	6' tens	8' cables	10' laminated shale then 10' shale
NME	Estep Coal Co	44-06979	3/21/2006	4153701	Lower Banner	20	20	6	4' & 6' full		10' sandy shale then 10' sandstone
Mine No 4	Hubble Mining Co	44-07048	9/8/2006	4129037	Low Splint	40	20	6.5	5' full	8' cables	10' laminated shale then 10' shale
Mine No 4			4/13/2005	4155856	Low Splint	20	20	10	5' full	10' cables	10' shale then sandstone
Deep Mine No 10	Paramount Coal Co	44-07055	5/29/2006	4125750	Jawbone	35	35	15	6' pt anchor	10' cables	15' shale then 15' sandstone/shale
Pardee/Wax	Powell Mountain Coal	44-07060	5/17/2006	4157014	Wax Lower Banner	60	18	10	4' full		10' shale then 10' sandstone
No 8	Bristol Coal Corp	44-07075	1/2/2006	4128778	Lower Banner	30	22	10	5' full	8' cables	10' laminated shale then 10' sandy shale
No 8			1/17/2006	4128780	Lower Banner	35	20	8	5' full	8' cables	10' laminated shale then 10' sandy shale
No 1 Mine	Exeter Coal Corp	44-07106	8/28/2006	4129035	Low Splint	20	20	5.5	5' full	8' cables	10' laminated shale then 10' sandy shale
Buchanon No 1	Consolidation Coal	44-04856	7/14/2005	4153398	Pocahontas #3	25	20	6	6' full		10' laminated and sandy shale then 10' sandstone
VP 8	Island Creek Coal	44-03795	6/10/2005	4153394	Pocahontas #11	100	20	9	6' full	Truss bolts	10' laminated and sandy shale then 10' sandstone
Mine No 1	Appalachia Coal Co	44-05815	7/28/2005	4128104	Parsons	30	20	8	? full	Cribs	6' soft shale then 10' shale
Laurel Mountain	Dickenson Russell Coal	44-06444	7/8/2005	4128943	Jawbone	80	20	10	6' tens	8' cables	12' sandy shale then 20' sandstone
Laurel Mountain			1/5/2005	4128091	Jawbone	50	20	10	5' full	8' cables	5' gray shale with slips then gray to black shale
Dominion No 22	Dominion Coal Co	44-06645	6/3/2005	4153391	Tiller	60	16	2	4' full		5' sandy shale then 10' sandstone
Dominion No 22			11/8/2005	6184249	Tiller	45	20	5	3' full	Cribs	5' sandy shale then 10' sandstone

Deep Mine No 3	Paramount Coal Co Tech	44-06853	4/20/2005	4128933	Jawbone	38	19	5.5	5' pt anchor		20' slickensided shale then 20' shale
Mine No 1	Leasing & Rebuild American Energy	44-06859	5/28/2005	4128693	Pocahontas #11	43	19.5	3.5	3.4' full		10' laminated shale then 10' sandstone
No 1 Mine Roaring Fork No 3	Dickenson Russell Coal CS&S Coal	44-06973	4/6/2005	4128929	Norton Lower Banner	20	20	10	4' full		10' stack rock then 10' shale
Mine No 9	Russell Coal CS&S Coal Corp Capital Coal	44-06975	10/24/2005	4128950	Lower Banner	25	22	10	6' tens	12' cables	shale
No 7 Mine Deep Mine No 10	Corp Capital Coal Corp Paramount Coal Co	44-07025	8/1/2005	4128947	Lower Banner	50	20	7	4' full		10' laminated sandy shale then 10' sandstone
Deep Mine No 10	Corp Paramount Coal Co	44-07049	6/27/2005	4128938	Imboden	80	19	8	4' full		14' shale then 14' sandstone
Mine No 3	Harvest Time Coal	44-07055	8/13/2005	4128951	Jawbone Widow	35	6	6	6' tens 4'		6' thinly laminated shale then 20' shale
		44-07104	10/27/2005	4128112	Kennedy	30	20	4.5	mechanicals		4.5' slickensided shale then 10' shale

**MSHA DISTRICT 6 - UNPLANNED INTERSECTION FALLS
OF GROUND INVESTIGATIONS**

Mine	Owner	ID number	Date	Event #	Seam	Fall size			Support	Supplemental	Water	Geology
						Length	Width	Height				
Meathouse Energy	Sidney Coal Co	15-17287	9/23/2007	4193650	Pond Creek	60	18	5	5' tens			10' shale then 50' sandstone and shale
Meathouse Energy			9/12/2007	4194510	Pond Creek	15	12	5	4' full			5' sandstone and shale then 200' mainly sandstone
Advantage No 1	Sapphire Coal Co	15-02057	7/20/2007	4193639	Elkhorn #2	40	30	10	5' full	2 by 8' cables	Yes	Shale
Advantage No 1			12/7/2007	4194463	Elkhorn #3	30	18	6	5' tens	8' cables		Shale
Advantage No 1			7/20/2007	4193639	Elkhorn #2	40	30	10	5' full	2 by 8' cables		Shale
Eagle	Jet Coal Co	15-19029	11/12/2007	4194648	Elkhorn #3	20	20	8	4' full			15' shale then 20' sandstone
Simpson Branch	Mitac Mining Co	15-18814	8/9/2007	4193640	Elkhorn #3	25	18	8	4' full	2 by 8' cables every 8'	Yes	Shale
Simpson Branch			3/20/2008	4191203	Elkhorn #3	100	20	6	6' full			Blue shale
Simpson Branch			1/13/2008	4190548	Elkhorn #3	40	20	6	6' full			Blue shale
Simpson Branch			3/14/2008	4190549	Elkhorn #3	18	18	4.5	4' full			Blue shale
Simpson Branch			8/9/2007	4193640	Elkhorn #3	25	18	8	4' full	2 by 8' cables every 8'		Shale
No 1	Midgard Mining	15-18827	11/7/2007	4194461	Lower Elkhorn	30	20	4	4' full			Sandstone
No 1	Freedom Energy Mining	15-07082	5/5/2008	4195179	Pond Creek	80	20	8	5' full			10' sandstone and shale then 60' sandstone
No 1			9/27/2007	4194451	Pond Creek	90	20	6	6' full	10' cables		10' sandstone and shale then 60' sandstone
No 1			12/23/2007	4194907	Pond Creek	20	20	10	6' full	10' cables		10' sandstone and shale then 60' sandstone
No 1			5/5/2008	4195179	Pond Creek	80	20	8	5' full			10' sandstone and shale then 60' sandstone
No 1			5/6/2008	4193545	Pond Creek	70	20	7	6' full			10' sandstone and shale then 60' sandstone
No 1			2/6/2008	4194524	Pond Creek	20	20	10	5' full			10' laminated sandstone then 50' sandstone
No 1			11/23/2007	4194907	Pond Creek	20	20	12	6' full	10' cables		10' laminated sandstone then 50' sandstone
No 1			10/27/2007	4194458	Pond Creek	40	20	8	6' full			10' sandstone and shale then 60' sandstone
No 1			10/15/2007	4194518	Pond Creek	22	20	7.5	6' tens	8' cables		8' sandstone and shale then 60' sandstone
No 1			9/27/2007	4194451	Pond Creek	90	20	6	6' tens	10' cables		10' sandstone and shale then 60' sandstone
Mine No 15	McCoy Elkhorn Coal	15-18775	6/22/2007	4193633	Glamorgan	20	10	8	5' full	10' cables		10' sandstone and shale then 60' sandstone
Mine No 15			5/7/2008	4173531	Miller	30	30	5	5' full	8' cables		16' sandstone and gray shale then 10' gray shale
Mine No 15			11/24/2007	4173488	?	70	20	12	5' full	6 by 10' cables		16' shale and sandstone then 10' shale
Mine No 15			6/22/2007	4193633	Glamorgan	20	10	8	5' full			10' laminated sandstone then 50' sandstone
Mine No 16	South Akers Mining	15-19127	12/31/2007	4194911	Elkhorn #3	20	19	8	4' full	8' cables		6' laminated shale then 20' sandstone
Mine No 16			11/17/2007	4190709	Elkhorn #3	60	20	8	4' full	8' cables		6' shale and coal rider then 20' sandstone
Mine No 16			12/31/2007	4194911	Elkhorn #3	20	19	8	4' full	8' cables		6' laminated shale then 20' sandstone
Love Branch Mine	Road Fork Development	15-09830	11/26/2007	4195151	Williamson	50	19	5	4' full			Shale

Love Branch Mine			11/12/2007	4173385	Williamson	40	19	7	2.5' & 4' full		Shale
Love Branch Mine			11/26/2007	4195151	Williamson	50	19	5	4' full		Shale
Love Branch Mine			11/20/2007	4173429	Williamson	25	25	8	4' full		Shale
Love Branch Mine			11/5/2007	4173427	Williamson	140	20	6	4' full		Shale
Love Branch Mine			6/13/2007	4194609	Williamson	70	4	4.5	4' full		Shale
Mine No 1	Clean Energy Mining	15-10753	5/12/2008	4173442	Pond Creek	70	20	7	5' tens		10' shale and sandstone then 5' sandstone
Mine No 1			2/27/2008	4173396	Pond Creek	25	19	8	5' full	8' cables	8' soapstone and shale then 10' sandstone
Mine No 1			3/13/2008	4173399	Pond Creek	20	20	9	5' tens		9' shale and sandstone then 10' sandstone
Mine No 1			12/4/2007	4195152	Pond Creek	20	20	7	5' tens		10' shale and sandstone then 60' sandstone
Mine No 1			10/28/2007	4173381	Pond Creek	30	19	8	5' full	4 by 10' cables	10' shale then 60' sandstone
Mine No 1			10/22/2007	4173380	Pond Creek	70	16	6	5' full		10' shale and sandstone then 60' sandstone
Mine No 1			12/21/2007	4173608	Pond Creek	40	19	7	5' tens		7' shale and chalkstone then 20' sandstone
Mine No 1			11/14/2007	4173387	Pond Creek	30	18	7	6' tens	4 by 10' cables	Shale
Mine No 1			9/6/2007	4173477	Pond Creek	40	20	8	5' full		10' shale and sandstone then 60' sandstone
Mine No 1			9/19/2007	4173478	Pond Creek	25	20	10	5' tens	4 by 8' cables	10' shale and sandstone then 60' sandstone
Mine No 1			9/3/2007	4173476	Pond Creek	50	20	9	5' tens	4 by 8' cables	10' shale and sandstone then 60' sandstone
Mine No 1			8/17/2007	4173475	Pond Creek	40	19	5	5' tens		10' shale and sandstone then 60' sandstone
Mine No 1			8/7/2007	4173504	Pond Creek	30	20	8	5' tens	4 by 8' cables	10' shale and sandstone then 60' sandstone
Mine No 1			5/1/2007	4193627	Pond Creek	30	20	8	5' full	4 by 10' cables	10' shale and sandstone then 60' sandstone
No 1	B&C Coal Sapphire Coal Co	15-19159	4/25/2008	4201748	Elkhorn #3	30	18	5	4' full		10' shale then 30' shale and sandstone
Sandlick II	TRC Mining Co	15-18782	4/21/2008	4182373	Elkhorn #3	20	20	4.5	5' full	8' cables	25' shale then 25' sandstone
No 2	North Star Mining	15-17720	4/16/2008	4182604	?	65	20	6.5	4' full		10' dark gray shale then 15' gray shale
No 12		15-18581	4/9/2008	4195176	Hazard #4	30	16	4	3.6' full		Sandstone
No 12			7/24/2007	4190282	Hazard #4	25	20	4.5	3.5' full		Laminated sandstone
No 12			10/2/2007	4190651	Elkhorn #3	20	19	4	3.5' full	Yes	10' sandstone and shale then sandstone
No 6	Murriel Don Coal Co	15-19129	2/12/2008	4190290	Elkhorn #3	26	20	8	4' full 4' full with straps		Shale
Clean Energy Mine	ICG Knott County Premier Elkhorn Coal	15-18393	2/1/2008	4182239	Hazard #4	40	27	5	4' full		20' shale then 20' sandstone
E3-5B		15-18370	1/10/2008	4182504	Elkhorn #3	20	15	5	4' full		22' shale then 6' sandstone
E3-5B			9/19/2007	4194512	Elkhorn #3	30	29	5	4' full		5' slate then 300' slate and shale
E3-5B			12/26/2007	4184166	Elkhorn ##	60	25	5.5	4' full		22' shale then 60' sandstone
Mine No 2	Excel Mining LLC	15-09571	4/7/2008	4195175	Pond Creek	40	18	6	5' full		10' shale then 30' shale and sandstone
No 10	Fools Gold Energy Corp	15-18927	2/11/2008	4190716	Fireclay	70	18	8	4' full 4' full with straps	Cribs	Sandstone
No 10			4/15/2007	4190430	Fireclay	40	19	7	4' full 4' full with straps		15' shale then sandstone

Mine No 25	McCoy Elkhorn Coal	15-15138	3/13/2008	4193726	Elkhorn #2	90	20	8	4' full		Shale
Mine No 25			5/21/2007	4193629	Elkhorn #2	30	19	8	4' full		Shale
Mine No 3	Excel Mining LLC	15-08079	3/12/2008	4193841	Hazard #4	50	20	10	6' full		10' laminated sandstone then 50' sandstone
Mine No 3			1/21/2008	4194126	Pond Creek	30	19	10	6' full	10' cables	10' weak shale then 10' firm shale and sandstone
Mine No 3			11/16/2007	4193715	Pond Creek Lower Elkhorn	20	15	4	3' chuck bolts		10' shale then 50' sandstone and shale
Mine No 3			7/12/2007	4194614		50	50	9	6' full		10' shale then 50' sandstone and shale
No 20	Eagle Coal Co	15-18929	1/17/2008	4190664	Coalburg	30	30	6	4' full		?
No 20			1/17/2008	4190664	Coalburg	90	20	6	4' full		?
No 20			7/16/2007	4194615	Coalburg	35	12	20	4' full		3' slate then 30' sandstone
Jones Fork	Consol Rockhouse Energy Mining	15-18589	1/6/2008	4438220	Elkhorn #3	130	20	12	4' full		6' laminated gray shale then 10' sandy shale
Mine No 1		15-17651	1/4/2008	4195053	Elkhorn #3	70	30	3.5	4' full		10' shale then 100' sandstone
Mine No 1			12/12/2007	4192899	Elkhorn #3	20	20	5	4' full		10' shale then 80' sandstone
Mine No 1			11/4/2007	4194460	Elkhorn #3	20	20	5	4' full		10' shale then 80' sandstone
Mine No 1			1/23/2007	4193028	Elkhorn #3	80	20	5	4' full		Slate
Mine No 16	McCoy Elkhorn Coal	15-18250	11/18/2007	4194650	Elkhorn #3	90	19	6.5	4' full		10' sandy shale then 50' shale and sandstone
Mine No 16			11/30/2007	4173518	Cedar Grove	40	20	5	4' full		7' shale then 50' shale and sandstone
Mine No 28	CAM Mining	15-18911	12/19/2007	4177614	Glamorgan	30	19	4.5	4' full		4.5' slate then 54' sandstone
Mine No 28			7/29/2007	4194616	Glamorgan	50	18	4.5	4' full		11' sandy shale then sandstone
Mine No 28			6/21/2007	4199853	Glamorgan	30	20	6.5	4' full	8' cables	11' shale then 54' sandstone
Mine No 1	Solid Energy Mining	15-07475	12/10/2007	4195201	Pond Creek	60	20	5	4' full		10' shale and sandstone then 60' sandstone
Mine No 8	Woodman Three Mine ICG Knott County	15-17979	10/26/2007	4177612	Clintwood	40	18	8	4' full		Shale
Raven Mine No 1		15-18949	10/26/2007	4201734	Elkhorn #2	20	20	6.5	6' full	10 by 14' cables	10' laminated shale then 10' sandstone
Raven Mine No 1		15-18949	8/30/2007	4194621	Elkhorn #2	40	19	6	5' tens		20' shale then 50' shale and sandstone
Van Lear Mine	Excel Mining LLC	15-18839	9/24/2007	4192893	Van Lear	25	24	13	6' full		10' sandy shale then 10' sandstone
?	Damco LLC	15-16855	8/29/2007	4178747	Elkhorn #3	140	20	4	3.5' full		8' sandstone and shale then 60' shale
No 7	Marshall Mining Inc	15-18709	6/13/2007	4190570	Elkhorn #1	200	18	15	5' tens		5' sandstone then 15' sandy shale
No 10	Ember Contracting	15-17894	12/20/2006	4177674	Elkhorn #3	60	18	10	4' full		Sandy shale

**MSHA DISTRICT 7 - UNPLANNED INTERSECTION FALLS
OF GROUND INVESTIGATIONS**

Mine	Owner	ID number	Date	Event #	Seam	Fall size			Support	Supplemental	Water	Geology
						Length	Width	Height				
Darby Fork No 1	Lone Mountain Processing	15-02263	8/25/2006		Darby	20	20	5	5' hy-tech (tens)			
Darby Fork No 1			9/20/2006		Darby	35	19	6	?			
Darby Fork No 1			11/20/2006		Darby	20	20	12	?			
Darby Fork No 1			12/14/2006		Darby	20	20	7	5' hy-tech (tens)			
Darby Fork No 1			8/9/2007		Darby	20	20	8	5' hy-tech (tens)			
No 77	Blue Diamond Coal	15-09636	2/15/2006		Alma	60	20	8	?			
No 4	Bledsoe Coal Corp	15-11065	1/22/2007		Hazard #4	20	20	6	?			
RB #4	Manalapan Mining Co	15-17077	8/1/2007		Hazard #4	40	12	4	?			
Huff Creek No 1	Lone Mountain Processing	15-17234	3/1/2006		Kelioka	20	20	6	5' hy-tech (tens)	8' super bolts		
Huff Creek No 1			4/11/2006		Kelioka	20	20	12	5' hy-tech (tens)	8' super bolts		
Huff Creek No 1			6/12/2006		Kelioka	20	18	8	5' hy-tech (tens)			
Huff Creek No 1			7/19/2006		Kelioka	50	20	8	5' hy-tech (tens)	8' super bolts		
Huff Creek No 1			7/30/2006		Kelioka	20	20	8	5' hy-tech (tens)			
No 75	Blue Diamond Coal	15-17478	3/20/2006		Hazard #4	30	25	10	?			
No 75			5/19/2006		Hazard #4	45	20	10	?			
No 74	Blue Diamond Coal	15-18022	2/17/2006		Hazard #4	100	20	10	?			
Clover Fork No 1	Lone Mountain Processing	15-18647	2/21/2007		Darby	40	18	6	5' hy-tech (tens)			
No 4	Century Operations	15-18422	2/17/2006		Hazard #8	30	20	3				
S&H No 10	S&H Mining	40-03143	11/2/2006	4219996	Walnut Mountain	160	20	6	4' & 6' full	Cribs		Sandstone
S&H No 10			1/2/2007	4242337	Walnut Mountain	70	20	6	4' full			Sandstone
Beech Fork No 30	Bledsoe Coal Corp	15-18939	8/2/2006	4239081	Hazard #4	50	20	7	5' full	10' cables		7.5' slate and sandstone then 7' sandstone
Moseley Spur	Bell County Coal	15-18939	10/27/2007	4443801	Poplarlick	20	20	14	5' full	10' cables		laminated
No 4	Bledsoe Coal Corp	15-11065	10/8/2007	4443411	Hazard #4	80	20	4	4' full			4' slate 20' sandstone
No 4			7/26/2007	?	Hazard #4	50	20	6	4' full			10' laminated sandstone
Beechfork	Bledsoe Coal Corp	15-18376	12/4/2007	4443027	Hazard #4	60	20	7	5' full			22' laminated shale then dark shale
Beechfork			11/30/2006	4239351	Hazard #4	80	80	5	5' full			5' shale then 50' shale & sandstone
Beechfork			2/27/2008	4443328	Hazard #4	40	20	7	5' full			20' grayshale
Beechfork			5/9/2008	4444213	Hazard #4	150	25	6	5' full			
Coal Creek	Bell County Coal	15-18058	11/26/2006	4239086	Buckeye Springs	60	18	5	4' full			5' shale then 10' sandy shale

Coal Creek			3/10/2008	?	Buckeye Springs	30	21	4.5	4' full			5' shale then 10' sandy shale
Coal Creek Huff Creek No 1	Lone Mountain Processing	15-17234	5/7/2007	4240307	Kelioka	35	20	6	5' hy-tech/tens	8' super bolts		5' shale then 10' sandy shale
No 1	Three Bells LLC Century Operations	15-17074	1/22/2007	4238891	Jellico	20	20	3	3' full			7' laminated shale then 10' sandstone
No 4		15-18422	2/16/2006	4239069	Hazard #8	35	20	3	2.5' full			2.5' shale then 10' sandstone
No 1	Altec Energy	15-09636	2/15/2006	4222540	Alma	45	20	10	5' full			?
No 1 Butcher Branch Butcher Branch	Century Operations	15-18924	3/16/1998	6130903	Alma	30	20	6	4' full plus straps			10' shale then 40' laminated shale
			5/12/2006	4238977	Hazard #4	40	20	5	4' full			10' gray shale then 10' sandstone
			1/22/2008	4443711	Hazard #4	40	20	4.5	?			Sandstone
F-M No 4 Straight Creek No 1	F-M Coal Corp	15-18466	8/19/2006	4239080	Blue Gem	28	22	5	2.5' full			?
	Left Fork Mining Bledsoe Coal Corp	15-12564	2/4/2008	4239399	Rim	10	7	4	5' full			Shale
Big Laurel		15-11065	3/28/2008	4443528	Hazard #4	65	20	8	5' full			4' slate then 50' sandstone
No 3	Arjay Mining	15-16695	1/3/1998	6076576	Poplarlick	200	20	20	4' full	Timbers		Gray shale with sandstone streaks
BRD #1	BRD Inc Straight Creek Mining	15-17907	1/12/1998	6093809	Hazard #8	80	18	5	5' full		Yes	Dark shale 18' shaley sandstone then 10' sandstone
No 1		40-02353	1/12/1998	6077229	Coal Creek	80	20	5	4' full			30' shale then 10' sandstone
No 1			3/23/1998	6078555	Mason	40	25	8	4' full plus straps			20' firm shale then 10' sandstone
No 37	Arch	15-04670	1/1/1998	6129481	Harlan	28	20	7	5' full			10' siltstone then 10' sandstone
No 2 Maces Creek Mine	T&T Mining	15-16576	1/6/1998	6129482	Kelioka	60	20	10	5' full			?
Maces Creek Mine	Leeco Inc	15-17911	2/2/1998	6082925	Hazard # 4	160	19	5	4' full			5' sandy shale then 30' sandstone
Maces Creek Mine			5/29/1998	6082963	Hazard # 4	18	15	4	5' full			4' sandy shale, coal and sandstone mix then shale
Maces Creek Mine			6/2/1998	6082401	Hazard # 4	480	20	12	5' full			4' sandy shale with coal then 15' sandy shale
Maces Creek Mine			6/17/1998	4213015	Hazard #4	100	20	10	5' full			5.5' ironstone then 7' sandy shale
Maces Creek Mine			6/21/1998	6082498	Hazard #4	30	18	5	4' full		Yes	5' laminated shale with coal then 15' gray shale
Mine No 1 Darby Fork No 1	Good Coal Co Lone Mountain Processing	15-15455	3/29/1998	6079228	Hazard # 4	20	20	4	3' full			Sandstone
Darby Fork No 1		15-02263	3/31/1998	5858980	Darby	22	22	12	5' full plus straps			10' shale then 10' sandstone
Mine No 6	US Coal Inc	40-03092	3/16/1998	6078581	Red Ash	20	20	5	4' full plus straps	5' full		5.5' sandstone and laminated shale then sandstone
Mine No 6			4/27/1998	4211201	Red Ash	40	20	7	3' full plus straps			16' gray shale then 36' sandstone & shale
Mine No 1	Blue Gate Energy	15-12482	3/28/1998	6129493	Kelioka	70	19	14	5' full			4' gray shale then 10' cross bedded shale
No 68	Leeco Inc Perry County Mining	15-17497	3/3/1998	4082993	Amburgy	55	20	6	3' & 4' full			4' laminated sandstone then 15' shale & sandstone
Eas No 1		15-02085	4/20/1998	6082979	Hazard No 4	40	20	8	4' full			8' shale with coal rider then 30' shale & sandstone
Eas No 1			5/27/1998	4213104	Hazard No 4	20	20	6	4' full			4' shale, coal and sandstone then shale and sandstone
Eas No 1 Stoney Fork No 2	G&P Contractors	15-17909	6/1/1998	4213105	Hazard No 4	80	20	18	8' full with straps		Yes	6' laminated shale, slate, coal and sandstone
			5/21/1998	4210001	Blue Gem	50	20	2.5	? Full with straps			20' laminated shale then 20' shale

Little Leaterwood Mine No 1	ANR Coal Co	15-17870	5/8/1998	6082976	Hazard #4	20	20	7	4' full		2' sandy shale then gray shale & sandstone
Little Leaterwood Mine No 1			6/4/1998	6082964	Hazard #4	20	20	5	4' full		2.5' sandy shale with coal then 15' gray shale
No 5	Ember Contracting Group Harlan Cumberland Coal	15-16727	6/1/1998	4214506	#3 Elkhorn	20	20	3	3' full		10' laminated shale then 40' shale
C-2		15-07201	6/11/1998	5858984	Creech	60	40	8	4' full	7' combo	10' dark shale then 30' sandstone 10' slate and sandstone then 10' sandstone
No 74	Leeco Inc	15-18022	6/24/1998	6130924	Hazard #4	85	20	5	4' full		

**MSHA DISTRICT 8 - UNPLANNED INTERSECTION
FALLS OF GROUND INVESTIGATIONS**

Mine	Owner	ID number	Date	Event #	Seam	Fall size			Support	Supplemental	Water	Geology
						Length	Width	Height				
Gibson		12-02215	2/3/2008	4245639		70	20	30	6' pt anchor	10' cables	Yes	laminated shale and clay
			1/7/2008	4245635		25	17	20	6' pt anchor	10' cables		thinly laminated shale
			1/9/2008	4245636		30	18	15	6' double lok	4 cribs		thinly laminated shale
			12/7/2007	4245331		?	?		?			stack rock shale
			5/1/2006	4244903		18	18	12	6' pt anchor			shale and stack rock
			7/20/2006	4244802		24	24	15		10' cables		stack rock
			2/23/2006	4244009		?	?	10		10' double lok		gray shale
			3/3/2006	6139499		80	18	20	6' double lok			gray shale
			11/6/2006	4244630		20	18	15		10' cables		stack rock
				4244630		20	18	15		10' cables		stack rock
	10/27/2005	6049703		20	20	19		10' cables		unconsolidated shale		
Prosperity		12-02249	2/18/2008	4245458		18	18	12	5' full gr	10' cables		laminated sandy shale
			2/22/2008	4286589		20	20	12	6' full gr			slip, stack rock
			2/26/2008	4244861		20	25	10	5' full gr	10' cables	Yes	slickenside
			12/18/2007	4245246		8	10	3	5' full gr			stack rock
			2/27/2007	4244423		?	?		?			slip
			9/6/2006	4244228		20	20	12	5' full gr	10' cables		cutters
	8/8/2006	4244804		30	20	8	4' full gr			slickenside		
Mach #1		11-03141	2/3/2008	6156326				9	8' tens full gr	Yes	horizontal stress	
Pattiki		11-02662	12/5/2007	6156542		25	25	7	?		Yes	shale, limestone then sandstone
			8/27/2007	6155937		45	18	9	6' tens full gr		Yes	?
			11/15/2006	6155763		200	20	10	4' tens full gr			weak shale
			1/24/2006	6155710		40	18	9	7' tens full gr	4 cribs	Yes	?
Willow Lake		11-03054	10/5/2007	6155987		20	19	5	3.5' full gr		?	
Riola		11-02971	8/10/2007	4244848		30	15	8	8' full gr			slips, gray shale
			5/30/2007	4244837		20	20	10	6' full gr			cutter, laminated shale
			11/28/2006	6136694		40	20	15	8' pt anchor			cutter, laminated roof
Crown II		11-02236	2/2/2007	4256416		30	18	8	6/8' tens full		gray shale	
Viper		11-02664	2/7/2007	4256308		60	40	10	6/8' tens full		?	
Freelandville		12-02316	8/13/2006	4244619		25	20	8	4/6/8' full gr		laminated rock and limestone	

			4244619	80	20	12	4/6/8' full gr				laminated rock and limestone
Howesville	12-02354	1/29/2006	4244602	40	18	12	6' full gr		Yes		shale and limestone
		11/11/2005	6138044	18	18	8	5' full gr	12' cables	Yes		laminated slickenside
		11/21/2005	6139474	25	18	12	5' full gr	12' cables	Yes		laminated shale
Gateway	11-02408	1/5/2006	6157064	30	16	6	4/6/7' full gr				?
		9/6/2005	6156275	30	17	5	5' full gr				?
Air Quality	12-02010	9/13/2006	4244529	25	25	5	5' full gr				laminated shale
Liberty	11-02636	11/20/2005	6156017	49	43	7	4' double lk		Yes		slips and shale

MSHA DISTRICT 9 - UNPLANNED INTERSECTION FALLS OF GROUND INVESTIGATIONS

Mine	Owner	ID number	Date	Seam	Fall size			Support	Supplemental	Water	Geology
					Length	Width	Height				
Bowie #2	Bowie Resources	05-04591	4/22/2007	B Upper	100	20	7				
Bowie #2			2/12/2004		20	18	12				
Bridger	Pacific Minerals	48-01646	7/24/2007	D 41	20	16	7			Yes	
Bridger			2/17/2007		30	20	15				
Bridger			12/24/2006		20	16	7				
Bridger			10/24/2006		50	14	9				
Bridger			6/14/2006		55	18	10				
Bridger			5/14/2006		35	14	10				
Bridger			3/16/2006		22	19	9				
Deer Creek	Energy West	42-00121	1/6/2008	Blind Canyon	35	20	8				
Deer Creek			11/3/2007	Hiamwatha	75	20	5.5	6ft full			
Deer Creek			6/25/2007		25	20	8	6ft full			
Deer Creek			5/23/2007		20	20	4	7ft full	10ft cables		
Deer Creek			8/11/2006		75	20	4				Laminated mudstone and caprock
Deer Creek			1/11/2006		45	20	7			Yes	Laminated mudstone and caprock
Deer Creek			7/28/2004		20	20	6				Laminated mudstone and caprock
Deer Creek			6/29/2004		45	35	6			Yes	Laminated mudstone and caprock
Deserado	Blue Mountain Energy	05-03505	8/18/2007	B seam	50	20	9				
Deserado			11/11/2006		20	17	20				
Deserado			7/28/2006		20	17	8	7ft full			
Deserado			7/18/2006		16	14	8				
Deserado			10/12/2005		26	20	9	7ft full			
Deserado			7/21/2005		28	14	9				
Dugout Canyon	Canyon Fuel	42-01890	No unplanned falls recorded								
Elk Creek	Oxbow Mining	05-04674	5/30/2008	D2 seam	35	20	9				
Elk Creek			2/25/2007		40	18	7				
Elk Creek			1/9/2007		30	18	8				
Elk Creek			12/20/2006		45	16	8			Yes	
Elk Creek			12/14/2006		50	18	8				
Elk Creek			12/15/2005		40	18	7				
Elk Creek			8/13/2005		40	20	6.5				

Elk Creek			8/7/2005		60	20	12	
Elk Creek			6/23/2005		40	20	8	
Elk Creek			4/7/2005		25	25	6.5	
Elk Creek			11/4/2004		24	20	7	
Elk Creek			6/6/2004		25	14	12	
Elk Creek			4/21/2004		46	31	12	
San Juan	BHP	29-02170	1/23/2007	Fruitland #8	20	20	15	
San Juan			12/7/2005		20	20	10	
San Juan			5/8/2004		23	23	14	?
SUFCO	Arch Coal	42-00089	1/23/2008	Hiawatha	40	18	6	5ft full & mesh
SUFCO			1/15/2006		30	20	5	
West Elk	Arch Coal	05-03672	5/15/2008	B seam	25	22	6	
West Elk			5/7/2008	E seam	17	15	8	
West Elk			1/22/2008		40	30	7	
West Elk			11/29/2007		40	20	10	
West Elk			5/24/2007		19	15	8	
West Elk			3/26/2007		30	25	10	
West Elk			3/14/2007		16	8	5.5	
West Elk			1/24/2007		20	18	9	
West Elk			11/19/2006		60	20	6	
West Elk			10/19/2006		34	34	7	
West Elk			7/24/2006		16	15	6	
West Elk			4/18/2006		20	16	9	
West Elk			2/6/2006		30	20	12	
West Elk			1/1/2006		35	15	7	
West Elk			9/18/2005		18	18	9	
West Elk			8/17/2005		30	20	7	
West Elk			4/14/2005		18	18	8	
West Elk			4/13/2005		32	23	6	

**MSHA DISTRICT 10 - UNPLANNED INTERSECTION
FALLS OF GROUND INVESTIGATIONS**

Mine	Owner	ID number	Date	Event #	Fall size			Support	Supplemental	Water	Geology
					Length	Width	Height				
Elk Creek			4/28/2006	4286819	90	19	10	4ft full	Cribs		1ft gray shale, 3ft limestone
#9 seam			4/27/2007		100	18	10	4ft full	No		?
			4/26/2007		25	18	6	6ft full	No		?
			8/2/2007		70	19	6	5ft full	Cablebolts/Cribs	Yes	gray shale, dark gray shale
			6/6/2007		35	19	6	5ft full	Cribs/Propsetters	Yes	gray shale, dark gray shale
			6/26/2007		19	19	12	6ft full	ACS/Propsetters	Yes	gray shale, dark gray shale
			7/6/2007		20	20	10	6ft full	Props/Cribs	Yes	gray shale, dark gray shale
			7/6/2007		30	20	10	6ft full	Props/Cribs	Yes	gray shale, dark gray shale
			7/6/2007		50	18	10	6ft full	Props/Cribs	Yes	gray shale, dark gray shale
			7/6/2007		20	19	10	6ft full	Props/Cribs	Yes	gray shale, dark gray shale
			6/21/2007		20	18	6	6ft full	Cables/Propsetters	Yes	gray shale, dark gray shale
			5/24/2007		40	18	6	6ft full	Timber	Yes	gray shale, dark gray shale
			5/24/2007		75	18	6	6ft full	Timber/Propsetters	Yes	gray shale, dark gray shale
			5/24/2007		30	18	6	6ft full	Timber	Yes	gray shale, dark gray shale
			5/22/2007		18	18	12	6ft full	8ft Cables		gray shale, dark gray shale
			5/22/2007		20	18	7	6ft full	Timber		gray shale, dark gray shale
			5/21/2007		40	18	10	6ft full	Propsetter		gray shale, dark gray shale
			5/16/2007		40	20	6	6ft full	Timber/Cribs	Yes	gray shale, dark gray shale
			5/11/2007		70	18	8	6ft full	Cables	Yes	gray shale, dark gray shale
			5/10/2007		95	18	6	6ft full	Cables	Yes	gray shale, dark gray shale
			4/25/2007		30	18	8	6ft full	Timbers	Yes	gray shale, dark gray shale
			4/27/2007		20	19	8	6ft full	Cables/Cribs	Yes	gray shale, dark gray shale
			5/3/2007		18	18	12	6ft full	Nil		gray shale, dark gray shale
			5/2/2007		90	18	12	6ft full	Timbers		gray shale, dark gray shale
			5/2/2007		18	18	12	6ft full	Timbers		gray shale, dark shale
			4/18/2007		30	20	12	6ft full	Timbers		gray shale, dark shale
			4/19/2007		50	18	6	6ft full	Timbers		gray shale, dark shale
			4/11/2007		18	18	10	6ft full	Timbers		gray shale, dark shale
			3/29/2007		18	18	8	6ft full	Cables/Propsetters		gray shale, dark shale
			1/30/2007		20	18	7	5ft full	Cribs/Propsetters/Timber		gray shale, dark shale
			3/14/2007		30	18	8	6ft full	Timbers/Cribs		gray shale, dark shale
			3/7/2007		30	18	8	6ft full	Timbers/Cribs		gray shale, dark shale
			3/5/2007		22	18	10	6ft full	Timbers/Cribs		gray shale, dark shale

	2/22/2007	70	18	8 5ft full	Timbers/Cribs	gray shale, dark shale
	2/5/2007	30	18	8 5ft full	Propsetters	gray shale, dark shale
	2/2/2007	50	18	8 5ft full	Trusses/Cribs	gray shale, dark shale
Cardinal Mine	7/3/2006	40	18	12 6ft tens	7/8 Trusses/Beams	gray shale, gray sandstone
#9 seam	12/6/2003	20	20	8 6ft tens	Timbers	gray shale, black shale
	12/4/2003	45	15	6 6ft tens	No	gray shale, black shale
	4/28/2003	19	19	7 6ft tens	Timbers/Props/Trusses	gray shale, dark shale
	4/19/2003	18	18	8 6ft tens	Cribs	gray shale, dark shale
	2/23/2003	20	20	8 6ft tens	Timbers/Trusses	gray shale, dark shale
	12/6/2002	30	30	6 6ft tens	Timbers/Trusses	gray shale, dark shale
	11/18/2002	50	18	12 4ft full	Timbers	gray shale, dark shale
	8/2/2002	40	18	10 8ft tens	Trusses	gray shale, dark shale
	7/11/2002	20	20	6 6ft full	Timbers	gray shale, dark shale
#11 seam	10/15/2007	105	19	9 4ft full	Cribs/Timbers	limestone
	11/5/2007	80	18	6 4ft full	Timbers/Cribs	GOB(very weak shale/mud), limestone
	8/4/2007	18	18	6 6ft full	Timbers	GOB, limestone
	5/27/2007	100	20	10 4ft full	Timbers	GOB, limestone
	5/24/2007	20	19	8 6ft full	Timbers	GOB, limestone
	11/18/2006	80	19	10 3&6ft full	Cribs,Steel Sets	GOB, limestone
	10/31/2006	50	20	8 4ft full	Timbers/Cribs	GOB, limestone
	9/27/2005	45	20	5 4ft full	Timbers	GOB (15 in.), 8ft limestone
	12/22/2005	80	19	8 4ft full	Timbers	GOB (15 in.), limestone
	1/12/2006	30	20	7 6ft full	Timbers	GOB (15 in.), limestone
	6/15/2006	50	22	5 3ft full	Timbers	GOB (6 in.), limestone
	8/9/2006	100	19	4 4ft full	Timbers	GOB, limestone
	7/25/2006	20	20	6 5ft full	Timbers/Cribs	GOB, limestone
	6/18/2004	70	19	8 4ft full	Timbers	GOB, limestone
	7/9/2004	75	19	7 3ft full	Cribs	GOB (15 in.), limestone
	10/19/2003	25	18	3 3ft full	Timbers	GOB (3 in.), limestone
	7/2/2003	300	20	5 4ft full	Timbers	GOB, limestone
Dodge Hill	2/4/2008	110	18	6 5ft full	10 ft Cables/Cribs	2ft gray shale, 5-16ft sandy shale
#6 seam	12/27/2007	75	20	8 6ft tens	10 ft Cables	gray shale, sandy shale
	8/9/2007	30	20	8 6ft tens	Timber	gray shale, sandy shale
	3/30/2007	18	18	6 5ft tens	Nil	gray shale, sandy shale
	8/18/2006	210	20	10 6ft tens	10 ft Cables/Cribs/Timbers	gray shale, sandy shale
	8/20/2006	20	20	10 6ft tens	Cables/Cribs/Timbers	gray shale, sandy shale
	7/21/2004	40	20	20 6ft tens	12 ft Cables	gray shale, sandy shale

		8/12/2004	40	50	10 6ft tens	12 ft Cables	gray shale, sandy shale
		7/16/2004	28	20	9 5ft tens	10 ft Cables/Cribs/Timbers	gray shale, sandy shale
	3 way	12/15/2003	10	18	5 5ft tens	Timbers	gray shale, sandy shale
	3 way	12/4/2003	25	18	15 6ft tens	Timbers	gray shale, sandy shale
	3 way	11/30/2003	22	20	8 6ft tens	Cribs	gray shale, sandy shale
	3 way	10/22/2003	25	17	15 6ft tens	Cribs	gray shale, sandy shale
		11/1/2006	60	30	15 6ft tens	No	gray shale, sandy shale
Freedom Mine		2/16/2004	40	20	7 6ft tens	9 ft Mega Bolts	black shale, gray shale
		3/24/2004	80	19	5 3 1/2 ft full	Timbers	black shale, gray shale
		3/25/2004	110	19	4 3 1/2 ft full	Timbers/6ft Tens	gray shale, dark shale
		9/21/2004	70	19	5 1/2 5ft full	Timbers/Cribs	black shale, gray shale
		10/19/2004	35	19	5 1/2 5ft full	No	black shale, gray shale
		8/22/2005	40	19	12 5ft full	Timbers/12 ft Cables	black shale, gray shale
		11/1/2005	160	19	6 5ft full	Timbers	black shale, gray shale
		3/23/2006	120	19	6 6ft tens	No	black shale, gray shale
		12/19/2006	80	20	45 4ft full	Timbers/Cribs	black shale, gray shale
		12/20/2006	110	20	3 1/2 4ft full	Timbers/Cribs	black shale, gray shale
		2/13/2007	100	19	7 4ft full	Timbers/Cribs	18 in. black shale, gray shale
Paradise Mine		2/19/2008	80	18	6 5ft full	Timbers/9ft mega Bolts	2 ft black shale, gray shale
#9 seam		2/19/2008	90	18	6 5ft full	Timbers/9ft mega Bolts	2 ft black shale, gray shale
		2/15/2008	19	19	6 5ft full	Nil	2 ft black shale, gray shale
		1/29/2008	31	19	9 5ft full	9ft Mega Bolts	2 ft black shale, gray shale
		12/21/2007	60	18	10 5ft full	Nil	2 ft black shale, gray shale
		10/27/2007	50	19	7 5ft full	Cribs	2 ft black shale, gray shale
		12/3/2007	30	18	6 ?	Timbers	2 ft black shale, gray shale
		12/4/2007	20	18	6 5ft full	9ft Mega Bolts	2 ft black shale, gray shale
		10/28/2007	18	10	6 6ft tens	12ft Cables	2 ft black shale, gray shale
		10/23/2007	58	19	7 5ft full	Timbers/Cribs	2 ft black shale, gray shale
		10/22/2007	70	19	7 5ft full	?	2 ft black shale, gray shale
		9/26/2007	970	18	5 5ft full	9ft Mega Bolts	2 ft black shale, gray shale
		9/26/2007	365	18	5 5ft full	9ft Mega Bolts	?
#11 seam		12/10/2007	50	18	5 2 1/2ft full	Cribs	limestone
		10/18/2007	25	18	5 3 1/2ft full	Cribs	GOB, limestone
		11/1/2007	50	18	5 2 1/2ft full	NIL	6ft GOB, limestone
		9/25/2007	18	18	4 2 1/2ft full	Timbers/Cribs	limestone
Dotiki Mine		7/2/2007	60	20	5 5ft full	?	gray shale, black shale
#9 seam		6/5/2007	120	18	6 5ft full	12ft Cables	2 ft dark shale, laminated shale

4/7/2007	80	20	18 5ft full	Timbers/Cables	2 ft dark shale, laminated shale
4/2/2007	80	20	8 5ft full	10ft Cables	2 ft dark shale, laminated shale
3/8/2007	25	20	6 5ft full	12ft Cables	2 ft dark shale, laminated shale
2/2/2007	80	18	10 5ft full	10ft Cables/Trusses/Timb ers	dark shale, laminated shale
1/28/2007	60	19	10 5ft full	?	dark shale, laminated shale
8/8/2006	19	19	6 5ft full	Timber	2 ft dark shale, laminated shale
8/9/2006	105	19	12 5ft full	Timber	2 ft dark shale, laminated shale
1/22/2002	130	18	6 5ft full	Timbers/Cribs	2ft dark shale, sandy shale
12/11/2001	50	18	5 5ft full	12ft Cables/Timbbers/Cribs	2ft dark shale, sandy shale
12/8/2001	170	20	7 5ft full	12ft Cables/Timbbers/Cribs	2ft dark shale, sandy shale
11/13/2001	105	19	7 5ft full	Timbers/Cribs	2 ft dark shale, laminated shale
10/24/2001	110	19	10 5ft full	12ft Cables/Timbbers/Cribs	2 ft dark shale, laminated shale
1/25/2008	100	19	7 5ft full	Truss Bolts	2 ft dark shale, laminated shale
1/2/2008	50	19	10 5ft full	10ft Cables	2 ft dark shale, laminated shale
12/24/2007	65	19	15 5ft full	10ft Cables	2 ft dark shale, laminated shale
1/2/2008	23	19	10 5ft full	Cables/Trusses	2ft gray shale, dark shale
10/27/2007	75	20	5 5ft full	?	?
1/8/2008	18	15	4 1/2 3 1/2ft full	Trusses	2 ft dark shale, laminated shale
2/14/2008	30	19	7 5ft full	Truss Bolts/Props	dark shale, sandstone
10/26/2007	65	19	8 5ft full	Trusses/Timbbers	2 ft dark shale, laminated shale
11/4/2007	70	18	8 5ft full	Timbers/Cribs	gray shale, laminated shale
9/14/2007	70	19	13 5ft full	12ft Cables/Trusses	?
12/10/2007	60	20	6 5ft full	Timbers/Cribs	2ft gray shale, laminated shale
12/24/2007	65	19	15 5ft full	10ft Cables	2ft gray shale, laminated shale
12/17/2007	50	20	8 5ft full	Timbered	2 ft dark shale, laminated shale
12/17/2007	25	25	8 5ft full	?	2 ft dark shale, laminated shale

MSHA DISTRICT 11 - UNPLANNED INTERSECTION FALLS OF GROUND INVESTIGATIONS

Mine	Owner	ID number	Date	Event #	Seam	Fall size			Support	Supplemental	Water	Geology
						Length	Width	Height				
Oak Grove	Oak Grove Resources Warrior	01-00851	9/22/2007	4298385	Blue Creek	70	21	6	4' full			6' imbedded shale and coal then 100' sandstone/shale
Corinth Mine	Investment Shelby Mining Co	01-03002	4/4/2007	4297831	America	25	20	9	3' full			4' shale then 14' sandy shale
Coke Mine No1		01-03217	4/6/2007	4299127	?	50	20	6.6	6' full			Sandy shale
Coke Mine No1			7/25/2007	4299060	Coke	33	18	9	6' full		Yes	30' gray shale then 100' sandstone
Coke Mine No1			8/10/2007	4298961	Coke	250	22	9	6' full		Yes	30' gray shale then 100' sandstone 4' laminated sandstone then 7' sandstone
Coke Mine No1			9/1/2006	4291262	Coke	40	20	5	6' full ?			
Coke Mine No1			8/28/2006	?	Coke	88	25	7	4' full			20' gray shale then 100' sandstone
Shoal Creek Mine	Drummond Co	01-02901	7/23/2005	4297536	Blue Creek	35	11	4	6' full			Sandstone 20' laminated sandstone & shale then sandstone
Shoal Creek Mine			2/8/2005	4295491	Blue Creek	40	20	6	6' tens			14' sandstone & shale then 230' sandy shale
Shoal Creek Mine			6/27/2004	4294069	Blue Creek	20	20	10	4' & 8' pt anchor	Trusses		
North River No 1	Pittsburg & Midway Coal	01-00759	5/5/2005	4297411	Pratt	29	20	9	6' pt anchor			Laminated shale and sandstone
North River No 1			7/7/2004	4295450	Pratt	86	18	7	6' tens			Shale with laminated sandstone streaks
North River No 1			9/24/2004	4293984	Pratt	21	20	8	6' tens			Laminated shale and sandstone
North River No 1			9/5/2004	4293979	Pratt	20	20	8	6' tens			Laminated shale and sandstone
North River No 1			9/11/2004	4295465	Pratt	24	20	8	6' tens			Shale with laminated sandstone streaks
No 4 Mine	Jim Walter Resources	01-01247	11/15/2006									

Data averaged per District

Average fall height (ft) distribution by District

Height	Frequency												
	All	#1	#2	#3	#4	#5	#6	#7	#8	#9	#10	#11	
<4	14	0	0	0	0	2	4	1	4	1	0	2	0
4 to 6	255	0	13	12	70	20	38	33	3	12	50	4	
6 to 10	349	0	27	48	49	36	45	22	11	38	62	11	
10 to 15	85	0	18	7	8	5	5	6	12	8	16	0	
15 to 20	17	0	1	0	1	3	1	2	6	1	2	0	
20 to 25	3	0	0	0	0	1	0	0	2	0	0	0	
25 to 30	1	0	0	0	0	0	0	0	1	0	0	0	
>30	1	0	0	0	0	0	0	0	0	0	1	0	
TOTAL	725												

Average fall length (ft) distribution by District

Length	Frequency											
	All	#1	#2	#3	#4	#5	#6	#7	#8	#9	#10	#11
<10	6	0	0	3	1	0	0	1	1	0	0	0
10 to 20	166	0	5	32	27	14	19	18	3	18	28	2
20 to 30	177	0	22	16	29	20	24	10	14	14	24	4
30 to 40	108	0	13	7	16	9	15	12	6	14	12	4
40 to 50	65	0	5	2	12	6	6	6	6	7	14	1
50 to 60	50	0	3	3	13	11	5	6	0	3	6	0
60 to 80	69	0	2	3	11	6	11	8	1	2	24	1
80 to 100	37	0	2	0	10	2	6	3	2	1	9	2
>100	49	0	8	1	11	2	4	5	1	0	16	1

Average stand-up time distribution by District

Age	Totals	District									
		1	2	3	4	5	6	7	8	9	10
< 1 month	124	0	7	5	13	10	8	3	37		38
1-3 months	118	0	4	4	7	10	10	5	49		29
3-6 months	68	0	1	2	14	6	8	4	16		14
6-12 months	67	0	5	5	12	3	5	2	26		9
1-3 years	115	0	2	15	14	10	11	11	42		9
3-5 years	22	0	0	5	0	1	6	0	4		5
> 5 years	87	0	1	9	8	12	20	11	13		12

NO
DATA

Note: There is no data for District 9 as a visit was not made to the MSHA Office in Denver, CO to review the 7000 50a reports.

VITA

Graduate School

Southern Illinois University

Allen R. Mueller

Date of Birth: January 14, 1985

4022 N. Central Park, Apt. 3W, Chicago, Illinois 60618

407 Pine Ridge Drive, Washington, Illinois 61571

AllenRMueller@gmail.com

Southern Illinois University, Carbondale

Bachelor of Science, Mining Engineering, December 2008

Thesis Title:

An Analysis of Current Intersection Support and Falls in United States Coal
Mines and Recommendations to Improve Safety

Major Professor: Dr. A.J.S. (Sam) Spearing

Publications:

Spearing, A.J.S., and A. Mueller (2008), "State-of-the-Art Intersection Support in Coal
Mines in the USA", *SHIRMS Proceedings – Vol. 1*, pp. 641-652.

Spearing, A.J.S., and A. Mueller (2009), "A Review of Rock Support and Falls in
U.S. Coal Mine Intersections", *SME Annual Meeting*, Feb. 22-25, 2009